Your Inspection Report

22 Strickland Ave Toronto, ON





PREPARED FOR: WENDY HAMMOND

INSPECTION DATE: Tuesday, November 10, 2015

PREPARED BY: Adam Hannan



Carson, Dunlop & Associates 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2

416-964-9415

www.carsondunlop.com info@carsondunlop.com

Powered by Knowledge



November 10, 2015

Dear Wendy Hammond,

RE: Report No. 50998 22 Strickland Ave Toronto, ON

Thank you for choosing us to perform your home inspection. We hope the experience met your expectations.

There are a series of coloured tabs at the top of each page of the attached report that you can click for easy navigation. The report begins with an Overview and then has one section for every major home system (Roofing, Exterior, Structure, etc.). Blue, underlined text indicates a hyperlink. Click on the hyperlink for more information on that subject or condition. There is further reference material at the end.

Please feel free to contact us with questions about the report or the home itself any time, for as long as you own your home. Our telephone and e-mail consulting service is available at no cost to you. Please watch for your follow-up e-mail. We hope you will fill out and return our client questionnaire.

Thanks again for choosing Carson Dunlop.

Sincerely,

Adam Hannan on behalf of Carson, Dunlop & Associates

> Carson, Dunlop & Associates 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2 416-964-9415 www.carsondunlop.com info@carsondunlop.com



INVOICE

November 10, 2015

Client: Wendy Hammond

Report No. 50998 For inspection at: 22 Strickland Ave Toronto, ON

on: Tuesday, November 10, 2015

Sellers Home Inspection - Professional Inspector	\$453.90	
Coupon		(\$25.00)
	Subtotal HST #108348343	\$428.90 \$55.76
	RT0001 Total	\$484.66

PAID IN FULL - THANK YOU!

Carson, Dunlop & Associates 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2 416-964-9415 www.carsondunlop.com info@carsondunlop.com

OVER	OVERVIEW Report No. 50998								
22 Strickland Ave, Toronto, ON November 10, 2015 www.carsondunlop.com									
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

INTRODUCTION

This Overview lists some of the significant report items that may need attention in the short term. This must not be considered as the complete report. Please read the entire report and the appropriate text included in the hyperlinks. The goal of a home inspection is to identify significant issues that would affect the average person's decision to buy a home. While looking for big issues we typically identify some minor defects along the way. We include these in the report as a courtesy, but please understand a home inspection is not a Technical Audit and does not include a comprehensive list of minor issues. (That service is available at additional cost.)

FOR THE BUYER

This inspection report is very helpful, but it's not enough to make a decision about buying a home. A complete home inspection includes both an onsite review of the property with the home inspector and the inspection report. To book your Onsite Review, call us at 800-268-7070. The fee is \$260. Without an Onsite Review, our obligation and liability is limited to the seller.

When you move into the home you may find some issues not identified in the report. That is to be expected and we suggest you allow roughly 1% of the value of the home annually for this type of maintenance and repair.

ELECTRICAL

OUTLETS \ Observations

Condition: • Some ungrounded 3-prong outlets were noted. There is a slight risk of shock in using three-prong appliances with these outlets. While they are not as good as grounding, Ground Fault Interrupter (GFI) outlets protect people and are a good cost-effective improvement. The cost is typically roughly \$100 each. One GFI protects one entire circuit. **Location**: Various

HEATING

ADDITIONAL \ Comments

Condition: • Insulation on or above the ducts may contain asbestos. Health Canada recommends the insulation be left in place undisturbed unless there is a risk of asbestos fibers being released into the house air. If this is a concern, a specialist should be consulted. If the insulation is damaged or is to be disturbed, and if it contains asbestos (confirm with Laboratory test), precautions should be taken that asbestos fibers are not released into the house air.

INTERIOR

BASEMENT LEAKAGE \ Observations

Condition: • Dampness

We noted dampness along the left side basement wall. Stone foundations are porous and are typically more damp than other foundation materials. Basement dampness is common with homes of this age. Follow exterior recommendation in the report. Also, you may consider parging the interior basement with a breathable portland cement. Consult with a masonry specialist familiar with stone foundations.

Location: Left Side Basement

22 Strickland Ave, Toronto, ON November 10, 2015

22 Strickland Ave, Toronto, ON November 10, 2015 OVERVIEW HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL H

REFERENCE

Task: Monitor / Parge Time: Ongoing / if desired

INTERIOR

APPENDIX

Houses are designed to last a very long time, but many of the components are consumable. Roofs, heating systems, air conditioning systems and water heaters, for example, wear out and are replaced from time to time. A home with older systems does not mean a poor quality house.

Many elements like kitchens, bathrooms, flooring, siding and windows are most often changed for lifestyle and decorating reasons. These discretionary home improvements are typically planned projects.

Un-planned repairs or replacements are never welcome, but are part of the 'joy of home ownership'. We encourage you to set up maintenance programs to protect your investment, reduce costs, improve comfort and efficiency, and extend life expectancy.

A Word About Water

Uncontrolled water is the enemy of homes. It not only damages the replaceable components, it also attacks the permanent elements of a home including wood and steel structural members, siding, trim, windows, doors, walls, floors and ceilings. Water also promotes mold growth.

Water sources include rain, snow, surface water, ground water; leaks from plumbing and heating systems and condensation. Again, preventative maintenance is the key to protecting your investment and avoiding water damage. This includes keeping gutters and downspouts clear and leak free, and discharging water well away from the building. Lot grading should slope slightly down away from the home to direct surface water away from the home.

Annual maintenance programs on roofs, gutters, heating and cooling systems help minimize water damage.

END OF OVERVIEW

NOTE: BALLPARK COSTS AND TIME FRAMES

Any ballpark costs and time estimates provided are a courtesy and should not be relied on for budgeting or decision-making. Quotations from specialists should be obtained. The word 'Minor' describes any cost up to roughly \$500.

HEATING

Time: Discretionary / If necessary Cost: Depends on approach

www.carsondunlop.com 22 Strickland Ave, Toronto, ON November 10, 2015 HEATING ROOFING PLUMBING APPENDIX REFERENCE **Observations and Recommendations GAS FURNACE \ Ducts, registers and grilles** Condition: • No heat source No registers in third floor, therefore no heating and cooling for this level. Add auxiliary heat source if needed (baseboard or space heater) Implication(s): Reduced comfort Location: Third Floor Task: Improve / Add auxiliary source

Report No. 50998 ROOFING www.carsondunlop.com 22 Strickland Ave, Toronto, ON November 10, 2015 ROOFING COOLING INSULATION PLUMBING APPENDIX REFERENCE Descriptions General: • The roof covering is newer and in good condition. Note: Reported to be 3 years old Sloped roofing material: Asphalt shingles

Asphalt shingles

Flat roofing material: • Modified bitumen membrane

Approximate age: • The roof covering appears to be at the beginning of its normal life expectancy.

Chimneys: • Masonry

Observations and Recommendations

<u>General</u>

• Asphalt shingle roof coverings wear out and are replaced every 15 years or more, depending on a number of variables. An annual roof tune-up by a qualified roofer is strongly recommended.

• Flat roof coverings wear out and are replaced every 15 years or more, depending on a number of variables. An annual roof tune-up by a qualified roofer is strongly recommended.

FLASHINGS \ Roof / Ridge Vent

Condition: • <u>Nail Heads - exposed (risk of leak)</u> Location: Roof Task: Improve Time: Less than 1 year Cost: Minor

Report No. 50998 22 Strickland Ave, Toronto, ON November 10, 2015 overview HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR APPENDIX REFERENCE INSULATION PLUMBING






Nail Heads - exposed (risk of leak)

Nail Heads - exposed (risk of leak) CHIMNEY \ Observations Condition: • Mortar - deteriorated/missing Location: Exterior Roof Task: Repair Time: Less than 1 year Cost: Regular maintenance item



Mortar - deteriorated/missing

VULNERABLE AREAS \ Observations Condition: • Skylight(s) - vulnerable area for leaks Location: Roof Task: Monitor Time: Ongoing Cost: Regular maintenance item



Inspection Methods and Limitations

Roof inspection method:

Walking on the roof
 From rear flat roof

EXTERIOR

22 Strickland Ave. Toronto. ON November 10. 2015

Report No. 50998

www.carsondunlop.com

OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Descriptions

Gutter and Downspout Material(s): • <u>Aluminum</u>

Wall Surfaces:

Brick

Observations and Recommendations

GUTTERS \ Observations

Condition: • <u>Dirty</u> Location: Various Exterior Task: Clean Time: Regular maintenance

WALKS \ Observations

Condition: • <u>Gap at house</u> Location: Left Side Exterior Task: Improve Time: Regular maintenance Cost: Regular maintenance item



Example

Condition: • Grading directs water toward Foundation

By grading, we are referring to the ground from house wall to 4 feet away. The walkway in this area has settled and has a minor slope toward the home. Until this area is improved, ensure all gaps are sealed

Location: Left Side Exterior

Task: Correct

Time: As required / if desired.

Cost: Minor to seal / Consult with landscaper for walkway cost.

WINDOWS \ Exterior side

Condition: • Sill - damage

Report No. 50998

ERIOR

22 Strickla	and Ave, Tor	onto, ON N	lovember 10), 2015				www.carso	ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
	Left Side Ex								
	oair / Replace								
	s than 1 yea								
Cost: Reg	jular mainten	ance item							

Sill - damage

WALL SURFACES \ Observations

Condition: • Mortar deteriorated/missing

Tuck pointing needed at various areas of the exterior walls. Most homes of this age need regular maintenance of exterior brickwork. Overall, the brickwork appears in good condition for the age of the home. Repointing:

- Soft mortar \$3.00-\$6.00 per sq. ft.

(minimum \$500)

- Hard mortar \$5.00-\$10.00 per sq. ft.


(minimum \$500)

Location: Left Side and Rear Exterior Wall

Task: Improve

Time: Regular maintenance

Cost: Regular maintenance item




Mortar deteriorated/missing

EXTERIOR STRUCTURES \ Railings Condition: • Incomplete Location: Rear Third Floor Balcony Task: Correct Time: As soon as possible Cost: Minor

Example

EXTERIOR 22 Strickland Ave, Toronto, ON November 10, 2015 www.carsondunlop.com OVERVIEW HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR APPENDIX REFERENCE INSULATION PLUMBING Interior APPENDIX REFERENCE Interior Insulation PLUMBING Interior APPENDIX REFERENCE Interior Interior Insulation PLUMBING Interior APPENDIX REFERENCE Interior Interior Interior Interior Interior Interior APPENDIX REFERENCE Interior <t

Location: Front Exterior Stairs Task: Provide Handrail Time: Less than 1 year Cost: Minor



EXTER	EXTERIOR Report No. 50998									
22 Strickland Ave, Toronto, ON November 10, 2015								www.carso	ndunlop.com	
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	
INTERIOR	APPENDIX	REFERENCE								



Missing


Condition: • Not well secured

Secure corner connections and reinforce Guardrails by adding reinforcements to the backside of the railing. **Location**: Exterior Balcony

Task: Improve

Time: Less than 1 year

Cost: Consult with deck specialist



Not well secured



Not well secured

EXTERIOR

Report No. 50998 www.carsondunlop.com

November 10, 2015 22 Strickland Ave, Toronto, ON

ROOFING

INSULATION

APPENDIX REFERENCE

Inspection Methods and Limitations

Exterior inspection method: • The exterior was inspected from ground level.

EXTERIOR

Limitations: • Fences, outbuildings (other than garages) and landscape features are not included as part of a home inspection.

Report No. 50998

22 Strickla		www.carsonduniop.com							
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
Descriptions									
	ons: • <u>Stone</u> ition: • <u>Base</u>								

Floor Construction: • Joists - wood

Exterior Wall Construction: • Masonry

Roof and Ceiling Framing: • Not visible

Observations and Recommendations

CONCRETE FLOORS \Observations

Condition: • Concrete basement, crawlspace and garage floors are not typically part of the structure. Almost all basement, crawlspace and garage concrete floors have minor shrinkage and settlement cracks. Also, we noted hollow areas below areas of the concrete slab.

Location: Basement

Task: Monitor/Repair Time: As Needed



Example


FOUNDATIONS AND MASONRY WALLS \ Observations

Condition: • Most foundation walls and masonry walls have small cracks due to minor shrinkage, settlement or shifting. These will not be individually noted, unless leakage or building movement is noted.

STRU	STRUCTURE Report No. 50998									
22 Strickland Ave, Toronto, ON November 10, 2015							www.carso	ndunlop.com		
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	
INTERIOR	APPENDIX	REFERENCE								
Inspection Methods and Limitations										

Limitations: • Finishes, insulation, furnishings and storage conceal structural components, preventing/restricting inspection. • The footings supporting the house are typically not visible and cannot be inspected. Only a small part of the foundation can be seen and inspected from outside the home. Finished or concealed portions of the interior of the foundation cannot be inspected.

Report No. 50998



MAIN PANEL \ Breakers and Fuses

Condition: • Link - missing on multiwire circuit Location: Basement Panel Task: Correct Time: Immediate Cost: Minor

Report No. 50998 **ELECTRICAL** www.carsondunlop.com 22 Strickland Ave, Toronto, ON November 10, 2015 ROOFING ELECTRICAL PLUMBING APPENDIX REFERENCE Special circuit breakers for 240 volts distribution panel

Link - missing on multiwire circuit

HOUSE WIRING \ Knob-and-tube

Condition: • It is possible that there is knob-and-tube wiring in the home, based on the age of the property, although none was noted during the inspection. If knob-and-tube wiring is found, the following information may be helpful. Various outlets and light switches were spot checked and no knob and tube was found.

Task: Remove

Time: if found during renovations

ELECT	RICAL							Report	No. 50998
22 Strickla	nd Ave, Tor	onto, ON N	lovember 10	, 2015				www.carso	ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR		REFERENCE							

10/11/2015

ELECTRICAL

INTERIOR APPENDIX	REFERENCE	
HOUSE WIRING \ Inte	ior	
Condition: • Abandon	<u>d</u>	
Location: Left Side Ba	ement	
Task: Remove or provi	e junction box	
Time: Immediate		

Abandoned

LIGHTS \ Observations

Condition: • Exposed wiring Location: First Floor Task: Correct Time: Immediate Cost: Minor



Exposed wiring

Condition: • Loose Location: Front Exterior Wall

Powered by Knowledge

Report No. 50998 www.carsondunlop.com


ELECTRICAL

22 Strickland Ave, Toronto, ON November 10, 2015

OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Task: Correct

Time: Regular maintenance **Cost**: Regular maintenance item






OUTLETS \ Observations

Condition: • Some ungrounded 3-prong outlets were noted. There is a slight risk of shock in using three-prong appliances with these outlets. While they are not as good as grounding, Ground Fault Interrupter (GFI) outlets protect people and are a good cost-effective improvement. The cost is typically roughly \$100 each. One GFI protects one entire circuit. **Location**: Various

Condition: • <u>Reversed polarity (black / white wires reversed)</u> Location: Second Floor Bathroom (left side of sink) Task: Correct and upgrade to GFI outlet Time: Immediate Cost: Minor



GROUND FAULT CIRCUIT INTERRUPTERS \ Observations

Condition: • Adding Ground Fault Circuit Interrupters (GFCIs) is a cost-effective safety improvement to existing homes. At an installed cost of roughly \$100 each, they provide enhanced protection against electric shock and are particularly useful near wet areas like outdoors, garages, and bathrooms). GFCIs may be either special circuit breakers or special wall outlets (receptacles). Either one protects all downstream outlets on that circuit.

Location: Exterior and Kitchen near sink Task: Upgrade Time: Less than one year

Cost: Minor

JUNCTION BOXES \ Observations

Condition: • <u>Cover Plate(s) - missing</u> Location: Various Basement Task: Correct Time: Immediate Cost: Minor

ELECTRICAL 22 Strickland Ave, Toronto, ON November 10, 2015 OVERVIEW HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INS

Report No. 50998
www.carsondunlop.com

PLUMBING

INTERIOR	APPENDIX	REFERENCE





Cover Plate(s) - missing

Cover Plate(s) - missing COVER PLATES \ Observations Condition: • Missing Location: Various Basement Task: Provide Time: Immediate Cost: Minor



Example

ELECTRICAL Report No. 5099									
22 Strickland Ave, Toronto, ON November 10, 2015 www.carsondunlop.com									ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
Inspect	ion Meth	ods and I	imitation	S					

Limitations: • Main disconnect cover not removed - unsafe to do so. • Concealed electrical components are not inspected. • The continuity and quality of the system ground are not verified as part of a home inspection. • The following low voltage systems are not included in a home inspection: intercom, alarm/security, doorbells, low voltage light control, central vacuum, telephone, television, Internet, and Smart Home wiring systems. • A professional home inspection includes the inspection of a representative sample of wiring, lights, receptacles, etc.

HEATING

Report No. 50998

22 Strickland Ave, Toronto, ON November 10, 2015	www.carsondunlop.com						
OVERVIEW HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLIN	NG INSULATION PLUMBING						
INTERIOR APPENDIX REFERENCE							
Descriptions							
Main Heating System - Type: • Furnace							
Efficiency: • Mid-efficiency							
Main Heating System - Fuel/Energy Source: • Natural gas							
Approximate Input Capacity: • 80,000 BTU/hr							
Approximate Age: • <u>9 years</u>							
Typical Life Expectancy: • Furnace (conventional/mid-efficiency) - 18 to 25 years							
Main Fuel Shut-off Location: • Gas Meter							

Observations and Recommendations

ELECTRIC HEAT \ Observations

Location: Third Floor baseboard heater Task: Replace Time: Discretionary

ADDITIONAL \ Comments

Condition: • Insulation on or above the ducts may contain asbestos. Health Canada recommends the insulation be left in place undisturbed unless there is a risk of asbestos fibers being released into the house air. If this is a concern, a specialist should be consulted. If the insulation is damaged or is to be disturbed, and if it contains asbestos (confirm with Laboratory test), precautions should be taken that asbestos fibers are not released into the house air.



Example

HEATI	Report	No. 50998							
22 Strickland Ave, Toronto, ON November 10, 2015 www.carsondunlop.com									ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
Inspect	ion Meth	ods and L	imitation	S					

Limitations: • Heat loss calculations are not performed as part of a home inspection. • Safety devices are not tested as part of a home inspection. • The heat exchanger is substantially concealed and could not be inspected.

Environmental issues outside the scope of a home inspection: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

COOLING

Report No. 50998

22 Strickland Ave, Toronto, ON November 10, 2015

www.carsondunlop.com ROOFING COOLING INSULATION PLUMBING APPENDIX REFERENCE

Descriptions

Air Conditioning Type: • Central air conditioning - air cooled

Cooling Capacity (Outdoor Unit): • 24,000 BTU/hr

Approximate Age (Outdoor Unit / Compressor): • <u>5 years</u>

Typical Life Expectancy: • 10 to 15 years

Observations and Recommendations

General

• No Cooling recommendations are offered as a result of this inspection.

• Air conditioning systems are complex with life expectancies of 10 to 15 years, if well maintained and serviced regularly. An annual maintenance contract is strongly recommended.

Inspection Methods and Limitations

Limitations: • Heat gain and heat loss calculations are not performed as part of a home inspection. • Low outdoor temperatures prevented testing in the cooling mode.

INSULATION

22 Strickland Ave, Toronto, ON

REFERENCE

Report No. 50998 www.carsondunlop.com

November 10, 2015 ROOFING COOLING

INSULATION

PLUMBING

Descriptions

Reference information on insulation levels: • Adding insulation is an improvement rather than a repair.

Attic air/vapour barrier: • Not visible • No access

Cathedral/sloped roof insulation - value & material: • Amount not determined • Material not determined

Flat roof insulation - value & material: • Amount not determined • Material not determined

Roof ventilation: • Roof vents

APPENDIX

Basement wall insulation - value & material: • None

Basement wall air/vapour barrier: • None

Observations and Recommendations

General

• No Insulation recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

Insulation inspection method: • See STRUCTURE: Inspection Methods and Limitations

Limitations: • Concealed wall insulation is not inspected. • The continuity of air/vapour barriers and the performance of roof and attic ventilation are not verified as part of a home inspection.

Environmental issues outside the scope of a home inspection: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070. • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

Report No. 50998

PLUMBING

22 Strickla	nd Ave, Tor			www.carso	ndunlop.com				
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
Descrip	tions								
General:	The kitche	n and bathroo	oms have be	en updated.					
Water Pip	ing to the E	Building: • <u>C</u>	opper						
Supply Pi	ping in the	Building: • 🤇	Copper						
Main Shut	t-off Valve L	-ocation: • F	ront of base	ment					
Water Hea	ater Type ar	nd Energy So	ource: • <u>Co</u>	nventional					
Water Hea	ater Tank C	apacity: • <u>18</u>	9 liters/50 U	<u>S gallons</u>					
Water Hea	ater Approx	imate Age:	4 years						
Typical Li	fe Expectar	ncy: • 10 to 1	5 years						
Waste Pip	Waste Piping Material: • Cast iron • Plastic • Not visible in some areas								
Floor Drai	Floor Drain Location: • Laundry Area								

Observations and Recommendations

General

• Most plumbing fixtures may be expected to last 15 years or more, although faucets are often replaced every 10 years. Domestic water heaters typically last 8 to 15 years, depending on several variables including type, usage levels and water quality.

SUPPLY PIPING \ In house

Condition: • Support inadequate Location: Basement Laundry Area Task: Improve Time: Less than 1 year **Cost**: Regular maintenance item



Support inadequate

PLUMBING 22 Strickland Ave, Toronto, ON November 10, 2015 www.carsondunlop.com overview HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR APPENDIX REFERENCE Verview <t

WASTE PIPING \ Observations

Condition: • A video inspection of the waste plumbing is recommended to determine whether there are tree roots, other obstructions, or damaged pipe. This is common on older properties, especially when mature trees are nearby. This is a great precautionary measure and can help prevent a sewage backup, although many homeowners wait until there are problems with the drains. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

Condition: • The cast iron waste piping is near the end of its normal life expectancy and is prone to rusting through or splitting. Replacement may be required in the near future.

Location: Various Task: Remove Time: When necessary

FAUCET \ Outdoor

Condition: • <u>Handle - damage / missing</u> Location: Left Side Exterior Task: Replace Time: Regular maintenance Cost: Minor



Handle - damage / missing

BATHTUB \ Observations

Condition: • <u>Drain slow</u> Location: Basement Bathroom Task: Clean / Improve Time: Before using Cost: Regular maintenance item

TOILET \ Observations

Condition: • <u>Tank Lid - missing</u> Location: Basement Bathroom Task: Provide Time: Discretionary

PLUMBING

www.carsondunlop.com

22 Strickland Ave, Toronto, ON November 10, 2015

November	10, 2015	

OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Cost: Minor

Inspection Methods and Limitations

Limitations: • Concealed plumbing is not inspected. This includes supply and waste piping under floors and under the yard. • Isolating valves, relief valves and main shut-off valves are not tested as part of a home inspection. • Tub and basin overflows are not tested as part of a home inspection. Leakage at the overflows is a common problem.

Environmental issues outside the scope of a home inspection: • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

INTERIOR

Report No. 50998

22 Strickland Ave, Toronto, ON November 10, 2015									ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
Descrip	otions								
Windows	• <u>Fixed</u> • <u>S</u>	Single/Double	Hung						
Exterior D	Doors: • <u>Cor</u>	nventional - h	inged						
Party Wal	Party Walls: • Masonry								

Observations and Recommendations

<u>General</u>

• Typical minor flaws were noted on floors, walls and ceilings. These cosmetic issues reflect normal wear and tear.

STAIRS \ Observations

Condition: • Railing - missing Location: Basement Staircase Task: Provide Time: Less than 1 year Cost: Minor

Report No. 50998 INTERIOR www.carsondunlop.com 22 Strickland Ave, Toronto, ON November 10, 2015 PLUMBING ROOFING APPENDIX REFERENCE INTERIOR Handrails and guards 1-1/2" | 1-1/2 top of handrail should be easy to grip opening 4" to 6" (tube or oval) max. wall projection -maximum 3-1/2" to 4" guardrail -36" minimum

handrail height (H)

34" to 38"


32" to 36"

line – through nosing handrail required when stairs are more than 24" or 3 risers high (2 risers in some areas)

10/11/2015

stairs against walls 30" to 38"

open stairs



cross section through railing (against wall)

U.S.

Canada

Powered by Knowledge

INTERIOR

22 Strickland Ave, Toronto, ON November 10, 2015

Report No. 50998

www.carsondunlop.com ROOFING INSULATION PLUMBING APPENDIX REFERENCE INTERIOR

BASEMENT LEAKAGE \ Observations

Condition:

 Dampness Location: Basement Laundry Room Task: Monitor / Improve

Time: As required





Dampness

We noted dampness along the left side basement wall. Stone foundations are porous and are typically more damp than other foundation materials. Basement dampness is common with homes of this age. Follow exterior recommendation in the report. Also, you may consider parging the interior basement with a breathable portland cement. Consult with a masonry specialist familiar with stone foundations.

Location: Left Side Basement Task: Monitor / Parge Time: Ongoing / if desired

Condition: • Dampness



Dampness



Dampness

Powered by Knowledge

Report No. 50998 www.carsondunlop.com

INTERIOR

22 Strickland Ave, Toronto, ON November 10, 2015

				,					
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Condition: • Efflorescence

Location: Various Basement

Task: Read information in the link above

BASEMENT LEAKAGE \ Potential

Condition: • We cannot predict the frequency or severity of basement leakage.

WHAT TO DO IF YOUR BASEMENT OR CRAWLSPACE LEAKS \ Observations

Condition: • Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and downspouts, and ground sloping down toward the house often cause basement leakage problems. Please read Section 10.0 in the Interior section of the Home Reference Book before taking any action.

To summarize, wet basement issues can be addressed in 4 steps:

1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost)

2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.)

3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.)

4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

Inspection Methods and Limitations

Limitations: • Security systems, intercoms, central vacuum systems, chimney flues and elevators are not included as part of a home inspection. Smoke detectors and carbon monoxide detectors are not tested as part of a home inspection. • Limited access to cabinets and closets • Perimeter drainage tile around foundations is not visible and is not included as part of a home inspection. • Basement leakage frequency or severity cannot be predicted during a home inspection • No comment is made on cosmetic finishes during a home inspection.

Limitations: • Storage/furnishings in some areas limited inspection

% of interior foundation wall not visible: • 70

Environmental issues outside the scope of a home inspection: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070. • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070. • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

INTERIOR	Report No. 50998
22 Strickland Ave, Toronto, ON November 10, 2015	www.carsondunlop.com
OVERVIEW HEATING ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING	COOLING INSULATION PLUMBING
INTERIOR APPENDIX REFERENCE	
END OF REPORT	

APPE	NDIX								
22 Strickla	and Ave, Tor	onto, ON	November 10	, 2015	www.carsondunlop.com				
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE	1						

GOOD ADVICE FOR ALL HOMEOWNERS

The following items explain how to prevent and correct some common problems around the house.

Roof Leaks

DDENDIV

Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced.

Annual Roof Maintenance

We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of the roof.

Ice Dams on Roofs

Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms at the lower edge of the sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather. For information on prevention and cure, please see section 1.14.2 of the Roofing section of the Home Reference Book. This can be found under the Reference tab in this report.

Maintaining the Exterior of Your Home

Regular maintenance includes painting and caulking of all exterior wood. Caulking should also be well maintained at joints, intersections, wall penetrations and any other places water may get into the building.

Heating and Cooling System - Annual Maintenance

An annual maintenance agreement that covers parts and labour is recommended for all heating and cooling equipment. Humidifiers and electronic air cleaners should be included in the service agreement. The first service visit should be arranged as soon as possible, preferably before equipment is used.

Filters for furnaces and air conditioners should be checked monthly during the operating season and changed or cleaned as needed. Duct systems should be balanced during regular servicing for maximum comfort. Systems with heating and air conditioning are balanced differently for summer and winter.

For boiler/hot water systems, we recommend that any balancing or adjusting the radiator valves be performed by a specialist, due to the risk of leakage. Heating system valves are not operated during a home inspection.

Gas fireplaces and heaters should be included in annual service plans.

Fireplace and Wood Stove Maintenance

Wood-burning appliances and their chimneys should be inspected and cleaned **before you use them** the first time, and annually thereafter. We recommend specialists with WETT (Wood Energy Technology Transfer, Inc.) designations for this kind of work.

Electrical System - Label the Panel

The electrical panel should be labeled to indicate what is controlled by each fuse or breaker. Where the panel is already labeled, please verify the labeling is correct. Do not rely on the labeling being accurate.

Report No. 50998

Report No. 50998 www.carsondunlop.com

APPENDIX

22 Strickland Ave, Toronto, ON November 10, 2015

OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Water Heaters

Tankless water heaters should be flushed by a heating or plumbing contractor every year to avoid poor performance and shortened life expectancy.

Bathtub and Shower Maintenance

Caulking and grout in bathtubs and showers should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

Basement/Crawlspace Leakage

Almost every basement (and crawlspace) leaks under the right conditions. Click for more information. For information on prevention and cure, please see section 10 of the Interior section of the Home Reference Book. This can be found under the REFERENCE tab in this report.

Washing Machine Hoses

We suggest braided steel hoses rather than rubber hoses for connecting washing machines to supply piping in the home. A ruptured hose can result in serious water damage in a short time, especially if the laundry area is in or above a finished area of the home.

Clothes Dryer Vents

We recommend vents for clothes dryers discharge outside the home. The vent material should be smooth walled (not corrugated) metal, and the run should be as short and straight as practical. This reduces drying time, energy consumption and cost; and minimizes the risk of a lint fire inside the vent.

Smoke and Carbon Monoxide (CO) Detectors

Smoke and carbon monoxide detectors should be provided at every floor level of every home, including basements and crawl spaces. (Even if they are present during the inspection, we recommend replacing detectors.) Smoke detectors should be close to sleeping areas, and carbon monoxide detectors should be in any room with a wood-burning stove or fireplace. These devices are not tested as part of a home inspection. Once you take possession of the home, detectors should be tested regularly, and replaced every 10 years. If unsure of the age of a smoke detector, it should be replaced. Smoke detector batteries should be replaced annually.

Priority Maintenance and Home Set-Up

When moving into a resale home, there are some things that you will want to take care of. The Home Set-Up and Maintenance section in the Home Reference Book will provide you with information regarding both things that are done just once as well as regular maintenance activities. This can be found under the REFERENCE tab in this report.

APPENDIX		Report No. 50998
22 Strickland Ave, Toronto, ON	November 10, 2015	www.carsondunlop.com
OVERVIEW HEATING ROOFING	EXTERIOR STRUCTURE ELECTRICAL HEATING	COOLING INSULATION PLUMBING
INTERIOR APPENDIX REFERENCE		
	This is a copy of our home inspection contract and outlines	
	the terms, limitations and conditions of the home inspection	
		—
THIS CC	INTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION	COMPANY.
	PLEASE READ CAREFULLY BEFORE SIGNING.	
The inspection is performed in Inspectors.	accordance with the STANDARDS OF PRACTICE of the Ont	ario Association of Home
To review the STANDARDS OF	PRACTICE, visit <u>www.oahi.com/webdocs/StandardsofPrac</u>	tice-OAHI-Rev.pdf
The Home Inspector's report is readily accessible features of t	an opinion of the present condition of the property, base he building.	d on a visual examination of the
In addition to the limitations in set out in this Agreement.	the STANDARDS, the Inspection of this property is subjec	t to Limitations and Conditions
LIMITATIONS AND CONDITION	S OF THE HOME INSPECTION	
be needed. It is not intended t	ope of this Inspection. It provides a general overview of the obserview of the bean exhaustive list. The ultimate decision of what to re ertain conditions require repair or replacement, while and	epair or replace is yours. One
1) THE INSPECTION IS NOT TEC	HNICALLY EXHAUSTIVE.	
	you with a basic overview of the condition of the propert me to go through the property, the Inspection is not tech	
	s foundation cracks or other signs of settling in a house, m nat is beyond the scope of the Home Inspection.	nay either be cosmetic or may
information than a Home Insp	depth, technically-exhaustive inspection of the home whic ection. We have both services available. By signing this agr ection instead of a Technical Audit.	
-	y conditions noted in the Home Inspection Report, we stro r or Consulting Engineer. These professionals can provide a at an additional cost.	
2) THE INSPECTION IS AN OPIN	ION OF THE PRESENT CONDITION OF THE VISIBLE COMPO	NENTS.
The Home Inspector's Report i the readily accessible features	s an opinion of the present condition of the property. It is of the building.	based on a visual examination of

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Powered by Knowledge

APPEN 22 Strickla	NDIX Ind Ave, Tore	onto, ON N	November 10				•	No. 50998 ndunlop.com	
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage or furniture to look underneath or behind.

3) THIS IS NOT A CODE-COMPLIANCE INSPECTION

The Inspector does NOT try to determine whether or not any aspect of the property complies with any past, present or future codes (such as building codes, electrical codes, fuel codes, fire codes, etc.), regulations, laws, by-laws, ordinances or other regulatory requirements.

4) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and ureaformaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fire proofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

5) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

6) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property. If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

R	eport No.	50998
---	-----------	-------

22 Strickla	ind Ave, Toro	onto, ON	November 10	, 2015	www.carsondunlop.com				
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

7) TIME TO INVESTIGATE

The Home Inspector and the Home Inspection Company will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

8) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

9) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the fee will apply.

10) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection and report are not a guarantee, warranty or an insurance policy with regard to the fitness of the property. A home warranty is available. For more information, visit <u>www.carsondunlop.com/home-inspection/home-warranty-plan/</u>

11) LIMIT OF LIABILITY

THE LIABILITY OF THE HOME INSPECTOR AND THE HOME INSPECTION COMPANY ARISING OUT OF THIS INSPECTION AND REPORT, FOR ANY CAUSE OF ACTION WHATSOEVER, WHETHER IN CONTRACT OR IN NEGLIGENCE, IS LIMITED TO A REFUND OF THE FEES THAT YOU HAVE BEEN CHARGED FOR THIS INSPECTION, OR \$1,000, WHICHEVER IS GREATER.

APPE								Report	No. 50998
	and Ave, Tor	onto, ON N	lovember 10), 2015				www.carso	ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							
			C				1	^	



Canadian Association Of Home & Property Inspectors

2012 NATIONAL STANDARDS OF PRACTICE

The National Standards of Practice are a set of guidelines for home and property inspectors to follow in the performance of their inspections. They are the most widely accepted Canadian home inspection guidelines in use, and address all the home's major systems and components. The National Standards of Practice and Code of Ethics are recognized by many related professionals as the definitive Standards for professional performance in the industry.

These National Standards of Practice are being published to inform the public on the nature and scope of visual building inspections performed by home and property inspectors who are members of the Canadian Association of Home and Property Inspectors (CAHPI).

The purpose of the National Standards of Practice is to provide guidelines for home and property inspectors regarding both the inspection itself and the drafting of the inspection report, and to define certain terms relating to the performance of home inspections to ensure consistent interpretation.

To ensure better public protection, home and property inspectors who are members of CAHPI should strive to meet these Standards and abide by the appropriate provincial/regional CAHPI Code of Ethics.

These Standards take into account that a visual inspection of a building does not constitute an evaluation or a verification of compliance with building codes, Standards or regulations governing the construction industry or the health and safety industry, or Standards and regulations governing insurability.

Any terms not defined in these Standards shall have the meaning commonly assigned to it by the various trades and professions, according to context.

NATIONAL STANDARDS OF PRACTICE. © COPYRIGHT 2012 CANADIAN ASSOCIATION OF HOME & PROPERTY INSPECTORS. ALL RIGHTS RESERVED.

Powered by Knowledge

APPENDIX									
	nd Ave, Torc	onto, ON	November 10	, 2015				www.carso	ndunlop.com
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING

INTERIOR APPENDIX REFERENCE

INDEX

- 1. Introduction
- 2. Purpose and Scope
- 3. General Limitations and Exclusions
- 4. Structural Systems
- 5. Exterior Systems
- 6. Roof Systems
- 7. Plumbing Systems
- 8. Electrical Systems
- 9. Heating Systems
- 10. Fireplaces & Solid Fuel Burning Appliances
- 11. Air Conditioning Systems
- 12. Interior Systems
- 13. Insulation and Vapour Barriers
- 14. Mechanical and Natural Ventilation Systems

Glossary Note: Italicized words are defined in the Glossary.

1. INTRODUCTION

1.1 The Canadian Association of Home and Property Inspectors (CAHPI) is a not-for-profit association whose members include the following seven provincial/regional organizations: CAHPI-British Columbia., CAHPI-Alberta, CAHPI-Saskatchewan, CAHPI-Manitoba, OAHI (Ontario), AIBO (Ouebec), and CAHPI-Atlantic. CAHPI strives to promote excellence within the profession and continual improvement of inspection services to the public.

2. PURPOSE AND SCOPE

2.1 The purpose of these National Standards of Practice is to establish professional and uniform Standards for private, fee-paid home inspectors who are members of one of the provincial/regional organizations of CAHPI. Home Inspections performed to these National Standards of Practice are intended to provide information regarding the condition of the systems and components of the building as inspected at the time of the Home Inspections. This does NOT include building code inspections.

These National Standards of Practice enable the building being inspected to be compared with a building that was constructed in accordance with the generally accepted practices at the time of construction, and which has been adequately maintained such that there is no significant loss of *functionality*.

It follows that the building may not be in compliance with current building codes, standards and regulations that are applicable at the time of inspection. These National Standards of Practice apply to inspections of part or all of a building for the following building types:

- single-family dwelling, detached, semidetached or row house
- multi unit residential building
- residential building held in divided or undivided co ownership
- residential building occupied in part for a residential occupancy and in part for a commercial occupancy, as long as the latter use does not exceed 40% of the building's total area, excluding the basement.

2.2 THE INSPECTOR SHALL:

A. inspect:

1. *readily accessible*, visually observable *installed systems*, and *components* of buildings listed in these National Standards of Practice.

B. report:

- 1. on those systems and components installed on the building inspected which, in the professional opinion or judgement of the *inspector*, *have a significant deficiency* or are unsafe or are near the end of their *service lives*.
- 2. a reason why, if not self-evident, the system or component has a significant deficiency or is unsafe or is near the end of its service life.
- 3. the inspector's recommendations to correct or monitor the reported deficiency.
- 4. on any systems and components designated for inspection in these National Standards of Practice which were present at the time of the Home Inspection but were not inspected and a reason they were not inspected.
- **2.3** These National Standards of Practice are not intended to limit inspectors from:
 - **A.** including other inspection services in addition to those required by these National Standards of Practice provided the *inspector* is appropriately qualified and willing to do so.
 - **B.** excluding *systems* and *components* from the inspection if requested by the client or as dictated by circumstances at the time of the inspection.

3. GENERAL LIMITATIONS AND EXCLUSIONS

3.1 GENERAL LIMITATIONS:

- **A.** Inspections performed in accordance with these National Standards of Practice
- 1. are not technically exhaustive.
- $\ensuremath{\text{2.\,will}}$ not identify concealed conditions or latent defects.

Report No. 50998 APPENDIX www.carsondunlop.com 22 Strickland Ave, Toronto, ON November 10, 2015 ROOFING COOLING INSULATION PLUMBING

REFERENCE APPENDIX 3.2 GENERAL EXCLUSIONS: 2. confined spaces. 3. spaces which are not readily accessible. A. The *inspector* is not required to perform any **F.** *Inspectors* are NOT required to *inspect*: action or make any determination unless 1. underground items including, but not limited specifically stated in these National Standards of Practice, except as may be required by lawful to storage tanks or other indications of their presence, whether abandoned or active. authority. 2. systems or components which are not installed. **B.** *Inspectors* are NOT required to determine: 3. *decorative* items. 4. systems or components located in areas that are 1. condition of systems or components which are not readily accessible. not readily accessible in accordance with these 2. remaining life of any system or component. National Standards of Practice. 5. detached structures. 3. strength, adequacy, effectiveness, or efficiency of any system or component. 6. common elements or common areas in multiunit housing, such as condominium properties 4. causes of any condition or deficiency. or cooperative housing when inspecting an 5. methods, materials, or costs of corrections. individual unit(s), including the roof and 6. future conditions including, but not limited to, building envelope. failure of systems and components. 7. suitability of the property for any use. 7. test and/or operate any installed fire alarm system, burglar alarm system, automatic 8. compliance with regulatory requirements (codes, sprinkler system or other fire protection regulations, laws, ordinances, etc.). 9. market value of the property or its marketability. equipment, electronic or automated installations, 10.advisability of the purchase of the property. telephone, intercom, cable/internet systems and any lifting equipment, elevator, freight elevator, 11.presence of potentially hazardous plants,

- animals or insects including, but not limited to wood destroying organisms, diseases or organisms harmful to humans.
- 12.presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water, and air.
- 13.effectiveness of any system installed or methods utilized to control or remove suspected hazardous substances.
- 14.operating costs of systems or components.
- 15.acoustical properties of any system or component
- 16.design adequacy with regards to location of the home, or the elements to which it is exposed.
- C. Inspectors are NOT required to offer or perform:
- 1. any act or service contrary to law, statute or regulation.
- 2. engineering, architectural and technical services.
- 3. work in any trade or any professional service other than home inspection.
- 4. warranties or guarantees of any kind.
- **D.** Inspectors are NOT required to operate:
- 1. any system or component which is shut down or otherwise inoperable.
- 2. any system or component which does not respond to normal operating controls.
- 3. shut-off valves.

E. Inspectors are NOT required to enter:

1. any area which will, in the opinion of the inspector, likely be hazardous to the inspector or other persons or damage the property or its systems or components.

- wheelchair lift, climbing chair, escalator or others;
- pools, spas and their associated safety devices, 8. including fences.

G. *Inspectors* are NOT required to:

- 1. perform any procedure or operation which will, in the opinion of the inspector, likely be hazardous to the *inspector* or other persons or damage the property or it's systems or components.
- 2. move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice, or debris.
- 3. *dismantle* any *system* or *component*, except as explicitly required by these National Standards of Practice.

22 Strickland Ave, Toronto, ON November 10, 2015

				, 2010					
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

4. STRUCTURAL SYSTEMS

4.1 THE INSPECTOR SHALL:

A. inspect:

- 1. *structural components* including visible foundation and framing.
- 2. by *probing* a sample of structural components where deterioration is suspected or where clear indications of possible deterioration exist. *Probing* is NOT required when *probing* would damage any finished surface or where no deterioration is visible.

B. describe:

- 1. foundation(s).
- 2. floor structure(s).
- 3. wall structure(s).
- 4. ceiling structure(s).
- 5. roof structure(s).

C. report:

- 1. on conditions limiting access to structural components.
- 2. methods used to *inspect* the *under-floor crawl space*
- 3. methods used to *inspect* the attic(s).

4.2 THE INSPECTOR IS NOT REQUIRED TO:

- **A.** provide any *engineering service* or *architectural service*.
- **B.** offer an opinion as to the adequacy of any *structural system* or *component*.

5. EXTERIOR SYSTEMS

5.1 THE INSPECTOR SHALL:

A. inspect:

- 1. exterior wall covering(s), flashing and trim.
- 2. all exterior doors.
- 3. attached or *adjacent* decks, balconies, steps, porches, and their associated railings.
- 4. eaves, soffits, and fascias where accessible from the ground level.
- 5. vegetation, grading, and surface drainage on the property when any of these are likely to adversely affect the building.
- 6. walkways, patios, and driveways leading to dwelling entrances.
- 7. landscaping structure attached or adjacent to the building when likely to adversely affect the building.
- 8. attached garage or carport.
- 9. garage doors and garage door operators for attached garages.

B. describe

- 1. exterior wall covering(s).
- C. report:
 - 1. the method(s) used to inspect the exterior wall elevations.

5.2 THE INSPECTOR IS NOT REQUIRED TO: A. inspect:

- 1. screening, shutters, awnings, and similar seasonal accessories.
- 2. fences.
- 3. geological, geotechnical or hydrological conditions.
- 4. recreational facilities.
- 5. detached garages and outbuildings.
- 6. seawalls, break-walls, dykes and docks.
- 7. erosion control and earth stabilization measures.

6. ROOF SYSTEMS

6.1 THE INSPECTOR SHALL:

A. inspect:

- 1. *readily accessible* roof coverings.
- 2. readily accessible roof drainage systems.
- 3. *readily accessible* flashings.
- readily accessible skylights, chimneys, and roof penetrations.

B. describe

- 1. roof coverings.
- C. report:
 - 1. method(s) used to inspect the roof(s).

6.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. antennae and satellite dishes.
- 2. interiors of flues or chimneys.
- 3. other *installed* items attached to but not related to the roof system(s).

7. PLUMBING SYSTEMS

7.1 THE INSPECTOR SHALL:

A. inspect:

- 1. interior water supply and distribution *systems* including all fixtures and faucets.
- 2. drain, waste and vent *systems* including all fixtures.
- 3. water heating equipment and associated venting systems.
- 4. water heating equipment fuel storage and fuel distribution systems.
- 5. fuel storage and fuel distribution systems.
- 6. drainage sumps, sump pumps, and related
- piping.

B. describe:

- 1. water supply, distribution, drain, waste, and vent piping materials.
- 2. water heating equipment including the energy source.
- 3. location of main water and main fuel shut-off valves.

NATIONAL STANDARDS OF PRACTICE. © COPYRIGHT 2012 CANADIAN ASSOCIATION OF HOME & PROPERTY INSPECTORS. ALL RIGHTS RESERVED.

Report No. 50998 www.carsondunlop.com

Report No. 50998

www.carsondunlop.com

22 Strickland Ave. Toronto, ON November 10, 2015

				, 2010						
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	
INTERIOR	APPENDIX	REFERENCE								
	7 2 THE INS	PECTOR IS NO		τo·	5 telecon	munication	minment			
	A inspect.		VI REGOIRED	10.	5. telecommunication equipment.					

A. inspect:

- 1. clothes washing machine connections.
- 2. wells, well pumps, or water storage related equipment.
- 3. water conditioning systems.
- 4. solar water heating systems.
- 5. fire and lawn sprinkler systems.
- 6. private waste disposal systems.

B. determine:

- 1. whether water supply and waste disposal systems are public or private.
- 2. the quantity or quality of the water supply.

C. operate:

1. safety valves or shut-off valves.

8. ELECTRICAL SYSTEMS

8.1 THE INSPECTOR SHALL:

A. inspect:

- 1. service drop.
- 2. service entrance conductors, cables, and raceways.
- 3. service equipment and main disconnects.
- 4. service grounding.
- 5. interior components of service panels and sub panels.
- 6. distribution conductors.
- 7. overcurrent protection devices.
- 8. a *representative number* of *installed* lighting fixtures, switches, and receptacles.
- 9. ground fault circuit interrupters (GFCI) (if appropriate).
- 10.arc fault circuit interrupters (AFCI) (if appropriate).

B. describe:

- 1. amperage and voltage rating of the service.
- 2. location of main disconnect(s) and subpanel(s). 3. wiring methods.
- C. report:
 - 1. presence of solid conductor aluminum branch circuit wiring.
 - 2. absence of carbon monoxide detectors (if applicable).
 - 3. absence of smoke detectors.
 - 4. presence of ground fault circuit interrupters (GFCI)
 - 5. presence of arc fault circuit interrupters (AFCI).

8.2 THE INSPECTOR IS NOT REQUIRED TO: A. inspect:

- 1. remote control devices unless the device is the only control device.
- 2. alarm systems and components.
- 3. low voltage wiring, systems and components.
- 4. ancillary wiring, systems and components not a part of the primary electrical power distribution system.

B. measure:

1. amperage, voltage, or impedance.

9. HEATING SYSTEMS

9.1 THE INSPECTOR SHALL:

- A. inspect:
 - 1. readily accessible components of installed heating equipment.
 - 2. vent systems, flues, and chimneys.
 - 3. fuel storage and fuel distribution systems.

B. describe:

- 1. energy source(s).
- 2. heating method(s) by distinguishing characteristics.
- 3. chimney(s) and/or venting material(s).
- 4. combustion air sources.
- 5. exhaust venting methods (naturally aspiring, induced draft, direct vent, direct vent sealed combustion).

9.2 THE INSPECTOR IS NOT REQUIRED TO:

- A. inspect:
 - 1. interiors of flues or chimneys.
 - 2. heat exchangers.
 - 3. auxiliary equipment.
 - 4. electronic air filters.
 - 5. solar heating systems.

B. determine:

1. system adequacy or distribution balance.

10. FIREPLACES AND SOLID FUEL BURNING APPLIANCES

(Unless prohibited by the authority having jurisdiction)

10.1 THE INSPECTOR SHALL:

- A. inspect:
 - 1. system components
 - 2. vent systems and chimneys
- **B. describe:**
 - 1. fireplaces and solid fuel burning appliances 2. chimneys

10.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. interior of flues or chimneys
- 2. screens, doors and dampers
- 3. seals and gaskets
- 4. automatic fuel feed devices
- 5. heat distribution assists whether fan assisted or gravity
- B. ignite or extinguish fires
- C. determine draught characteristics
- D. move fireplace inserts, stoves, or firebox contents

22 Strickland Ave, Toronto, ON

Report No. 50998 www.carsondunlop.com November 10, 2015 ROOFING COOLING INSULATION PLUMBING REFERENCE APPENDIX

11. AIR CONDITIONING SYSTEMS

11.1 THE INSPECTOR SHALL:

- A. inspect
 - 1. permanently *installed* central air conditioning equipment.

B. describe:

- 1. energy source.
- 2. cooling method by its distinguishing characteristics.

11.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect

- 1. electronic air filters.
- 2. portable air conditioner(s).
- **B. determine:**
 - 1. system adequacy or distribution balance.

12. INTERIOR SYSTEMS

12.1 THE INSPECTOR SHALL:

A. inspect:

- 1. walls, ceilings, and floors.
- 2. steps, stairways, and railings.
- 3. a representative number of countertops and installed cabinets.
- 4. a representative number of doors and windows.
- 5. walls, doors and ceilings separating the
- habitable spaces and the garage.

B. describe:

- 1. materials used for walls, ceilings and floors.
- 2. doors.
- 3. windows.

C. report

1. absence or ineffectiveness of guards and handrails or other potential physical injury hazards.

12.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. *decorative* finishes.
- 2. window treatments.
- 3. central vacuum systems.
- 4. household appliances.
- 5. recreational facilities.

13. INSULATION AND VAPOUR BARRIERS

- **13.1** THE INSPECTOR SHALL:
- A. inspect:
 - 1. insulation and vapour barriers in unfinished spaces.
- **B. describe:**
 - 1. type of insulation material(s) and vapour barriers in unfinished spaces.
- C. report
 - 1. absence of insulation in unfinished spaces within the building envelope.
 - 2. presence of vermiculite insulation

13.2 THE INSPECTOR IS NOT REQUIRED TO:

A. disturb

- 1. insulation.
- 2. vapour barriers.
- B. obtain sample(s) for analysis 1. insulation material(s).
- 14. MECHANICAL AND NATURAL
 - VENTILATION SYSTEMS

14.1 THE INSPECTOR SHALL:

A. inspect:

- 1. ventilation of attics and foundation areas.
- 2. mechanical ventilation systems.
- 3. ventilation systems in areas where moisture is generated such as kitchen, bathrooms, laundry rooms.

B. describe:

- 1. ventilation of attics and foundation areas.
- 2. mechanical ventilation systems.
- 3. ventilation systems in areas where moisture is generated such as: kitchens, bathrooms and laundry rooms.

C. report:

1. absence of ventilation in areas where moisture is generated such as: kitchens, bathrooms and laundry rooms.

14.2 THE INSPECTOR IS NOT REQUIRED TO:

- 1. determine indoor air quality.
- 2. determine system adequacy or distribution balance.

APPENDIX Report No. 509											
22 Strickla	and Ave, Toro	onto, ON	lovember 10	, 2015				www.carso	ndunlop.com		
OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING		
INTERIOR	APPENDIX	REFERENCE									

GLOSSARY

Adjacent

Nearest in space or position; immediately adjoining without intervening space.

Alarm Systems

Warning devices, installed or free-standing, including but not limited to; carbon monoxide detectors, flue gas and other spillage detectors, security equipment, ejector pumps and smoke alarms.

Architectural Service

Any practice involving the art and science of building design for construction of any structure or grouping of structures and the use of space within and surrounding the structures or the design for construction, including but not specifically limited to, schematic design, design development, preparation of construction contract documents, and administration of the construction contract, adequacy of design for the location and exposure to the elements.

Automatic Safety Controls

Devices designed and installed to protect *systems* and *components* from unsafe conditions.

Component

A part of a system.

Confined Spaces

An enclosed or partially enclosed area that: 1. Is occupied by people only for the purpose of completing work.

2. Has restricted entry/exit points.

3. Could be hazardous to people entering due to:

a. its design, construction, location or atmosphere. b. the materials or substances in it, or

b. the materials of substances in it, of

c. any other conditions which prevent normal inspection procedure.

Decorative

Ornamental; not required for the operation of the essential *systems* and *components* of a building.

Describe

To *report* a *system* or *component* by its type or other observed, significant characteristics to distinguish it from other *systems* or *components*.

Determine

To find out, or come to a conclusion by investigation.

Dismantle

To take apart or remove any component, device, or piece of equipment that would not be taken apart or removed by a homeowner in the course of normal and routine home owner maintenance.

Engineering Service

Any professional service or creative work requiring engineering education, training, and experience and the application of special knowledge of the mathematical, physical and engineering sciences to such professional service or creative work as consultation, investigation, evaluation, planning, design and supervision of construction for the purpose of assuring compliance with the specifications and design, in conjunction with structures, buildings, machines, equipment, works or processes.

Functionality

The purpose that something is designed or expected to fulfill.

Further Evaluation

Examination and analysis by a qualified professional, tradesman or service technician beyond that provided by the *home inspection*.

Home Inspection

The process by which an *inspector* visually examines the *readily accessible systems* and *components* of a building and which *describes* those *systems* and *components* in accordance with these National Standards of Practice.

Household Appliances

Kitchen, laundry, and similar appliances, whether *installed* or freestanding.

Inspect

To examine *readily accessible systems* and *components* of a building in accordance with these National Standards of Practice, *where applicable* using *normal operating controls* and opening *readily openable access panels*.

Inspector

A person hired to examine any *system* or *component* of a building in accordance with these National Standards of Practice.

Installed

Set up or fixed in position for current use or service.

Monitor

Examine at regular intervals to detect evidence of change.

Normal Operating Controls

Devices such as thermostats, switches or valves intended to be operated by the homeowner.

Operate

To cause to function, turn on, to control the function of a machine, process, or system.

22 Strickland Ave, Toronto, ON November 10, 2015

OVERVIEW	HEATING	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING
INTERIOR	APPENDIX	REFERENCE							

Probing

Examine by touch.

Readily Accessible

Available for visual inspection without requiring moving of personal property, *dismantling*, destructive measures, or any action which will likely involve risk to persons or property.

Readily Openable Access Panel

A panel provided for homeowner inspection and maintenance that is within normal reach, can be removed by one person, and is not sealed in place.

Recreational Facilities

Spas, saunas, steam baths, swimming pools, exercise, entertainment, athletic, playground or other similar equipment and associated accessories.

Report

To communicate in writing.

Representative Number

One *component* per room for multiple similar interior *components* such as windows and electric outlets; one *component* on each side of the building for multiple similar exterior *components*.

Roof Drainage Systems

Components used to carry water off a roof and away from a building.

Sample

A representative portion selected for inspection.

Service Life/Lives

The period during which something continues to function fully as intended.

Significant Deficiency

A clearly definable hazard or a clearly definable potential for failure or is unsafe or not functioning.

Shut Down

A state in which a system or component cannot be operated by normal operating controls.

Solid Fuel Burning Appliances

A hearth and fire chamber or similar prepared place in which a fire may be built and which is built in conjunction with a chimney; or a listed assembly of a fire chamber, its chimney and related factory-made parts designed for unit assembly without requiring field construction.

Structural Component

A component that supports non-variable forces or weights (dead loads) and variable forces or weights (live loads).

Report No. 50998

www.carsondunlop.com

System

A combination of interacting or interdependent components, assembled to carry out one or more functions.

Technically Exhaustive

An inspection is technically exhaustive when it is done by a specialist who may make extensive use of measurements, instruments, testing, calculations, and other means to develop scientific or engineering findings, conclusions, and recommendations.

Under-floor Crawl Space

The area within the confines of the foundation and between the ground and the underside of the floor.

Unsafe

A condition in a *readily accessible, installed system* or *component* which is judged to be a significant risk of personal injury during normal, day-to-day use. The risk may be due to damage, deterioration, missing or improper installation or a change in accepted residential construction Standards.

Vapour Barrier

Material used in the building envelope to retard the passage of water vapour or moisture.

Visually Accessible

Able to be viewed by reaching or entering.

Wiring Methods

Identification of electrical conductors or wires by their general type, such as "non-metallic sheathed cable" ("Romex"), "armored cable" ("bx") or "knob and tube", etc.

Note - In these National Standards of Practice, redundancy in the description of the requirements, limitations and exclusions regarding the scope of the Home Inspection is provided for clarity not emphasis.

(CAHPI acknowledges The American Society of Home Inspectors®, Inc. (ASHI®) for the use of their Standards of Practice (version January 1, 2000)

(AUGUST 22/12 VER. F)

Report No. 50998 APPENDIX www.carsondunlop.com 22 Strickland Ave, Toronto, ON November 10, 2015 ROOFING COOLING PLUMBING INSULATION APPENDIX REFERENCE Your health and Health Santé Votré santé et votre Canada Canada safety... our priority. sécurité... notre priorité. Health Risks of Asbestos IT'S YOUR HEALTH

Updated

January 2008



Health Risks of Asbestos

The Issue

Asbestos was a popular material used widely in construction and many other industries. If asbestos fibres are enclosed or tightly bound in a product, for example in asbestos siding or asbestos floor tiles, there are no significant health risks. Asbestos poses health risks only when fibres are present in the air that people breathe.

Background

Asbestos is the generic name for a variety of fibrous minerals found naturally in rock formations around the world. Because asbestos fibres are strong, durable and noncombustible, they were widely used by industry, mainly in construction and friction materials. Commercial asbestos fibres belong in two broad mineralogical groups: serpentine (chrysotile) and amphibole (tremolite, actinolyte and others).

- Amphibole asbestos often contains more iron and resists acid and extremely high temperatures. Because of this, it has been heavily used in industrial furnaces and heating systems. However when inhaled, amphibole fibres stay much longer in the lungs than chrysotile fibres and they are more likely to inflict damage and cause disease, including cancer. Accordingly, amphibole asbestos has been drastically controlled and largely replaced.
- Chrysotile is the only serpentine asbestos that is found in almost all asbestos-based products available today and is the main

form of asbestos still mined. Chrysotile is different from the amphiboles both structurally and chemically. It is generally accepted that chrysotile asbestos is less potent and does less damage to the lungs than the amphiboles.

How much asbestos is in a product does not indicate its health risk. If the asbestos fibres are enclosed or tightly bound in a compound, there is no significant health risk. One of the main problems with asbestos came from sprayed or "friable" (easily broken up) amphibole asbestos used in buildings until the 1970s. People working in construction, maintenance or in the renovation of older buildings should be particularly careful when handling this ashestos

Sources of Asbestos

Occupational

The risks are greatest for workers in industries which produce and use asbestos, such as mining and milling. In the past, workers in these environments were exposed to 100 - 1,000 times more asbestos than today's workers. Today's strict standards limit workers' exposure and the ban of most uses of amphibole asbestos have reduced the risks.

During renovations and repairs to older buildings, construction workers, tradespeople and other building maintenance workers may be exposed to very high concentrations of asbestos



22 Strickland Ave, Toronto, ON November 10, 2015



fibres. The environment and work methods of these occupations are more difficult to control than fixed workplaces, but most tradespeople are trained in the proper handling of asbestos-containing materials.

Environmental

Negligible levels of asbestos fibres are found in the soil, water and air, both naturally and from man- made sources. Asbestos concentrations in the air in rural areas are about ten times lower than those in larger cities, which are about 1,000 times lower than levels accepted in today's asbestos-related jobs. With such low exposure, environmental risks are negligible.

Due to natural erosion, high concentrations of chrysotile asbestos fibres may be found in some raw water supplies. Conventional water treatment methods can substantially reduce asbestos levels and there is no evidence that swallowed chrysotile fibres are a health hazard.

Buildings and Homes

Because it is a valuable reinforcing, insulating and fire-proofing material, asbestos was used widely in construction materials such as insulation board, asbestos cement, and floor and ceiling tiles. These products are very dense and do not release significant amounts of fibres under normal use. However, fibres may be released if these products are cut or damaged.

Asbestos fibre concentrations in the air in buildings are usually about the same as in the air outside, and are not a significant risk. However, levels may be higher if friable asbestos materials are disturbed.

There is also concern about vermiculite insulation which may contain small amounts of amphibole asbestos, principally tremolite or actinolite. These amphibole fibres may cause health risks if disturbed. However, there is currently no evidence of risk to your health if the insulation is sealed behind wallboards and floorboards, isolated in an attic, or otherwise kept from exposure to the home or interior environment.

The Health Risks of Asbestos

Asbestos poses health risks only when fibres are present in the air that people breathe. How exposure to asbestos can affect you depends on:

- the concentration of asbestos fibres in the air
- how long the exposure lasted
- how often you were exposed
- the size of the asbestos fibres inhaled
- the amount of time since the initial exposure.

When inhaled in significant quantities, asbestos fibres can cause asbestosis (a scarring of the lungs which makes breathing difficult), mesothelioma (a rare cancer of the lining of the chest or abdominal cavity) and lung cancer. The link between exposure to asbestos and other types of cancers is less clear.

Smoking, combined with inhaled asbestos, greatly increases the risk of lung cancer.

Minimizing Your Risk

Construction and maintenance workers should avoid creating asbestos dust from scraping, brushing, rubbing or cutting damaged insulation. Insulation damage should be reported to the appropriate authority, such as the Occupational Health and Safety Manager. If you work in this area, determine whether asbestos is present before beginning work and take appropriate precautionary measures.

Public and commercial building owners should keep an inventory of asbestoscontaining materials to inform users, authorities and contractors.

Homeowners should receive expert advice before removing materials that may contain asbestos. If you think your home may contain asbestos, check regularly for signs of wear or damage. However, you can't always tell just by looking at a material. If in doubt, have it analyzed by a qualified professional, who can be found by looking up experts in "asbestos abatement /removal".

Report No. 50998

If you must handle small amounts of damaged asbestos-containing materials, follow these steps.

- Keep other people and pets away, and seal off the work area.
- Wet the material to reduce dust, making sure it is not in contact with electricity.
- If possible, do not cut or damage the materials further and do not break them up.
- Clean the work area afterwards using a damp cloth, not a vacuum cleaner, and seal the asbestos waste and cloth in a plastic bag. Check with your local municipality on how to dispose of asbestos-containing waste.
- Wear appropriate protective clothing, including a single-use respirator approved by the National Institute for Occupational Safety and Health (NIOSH).
- Wash or dispose of clothing and shower after finishing the job.

Government of Canada's Role

Health Canada has encouraged provincial occupational health authorities to adopt stringent workplace exposure limits for asbestos. The sale of pure asbestos and certain high risk consumer products that are composed of or contain asbestos fibres is strictly regulated under the Hazardous Products Act. In addition, the emissions of asbestos into the environment from mining and milling operations are subject to the Canadian Environmental Protection Act

Need More Info?

For more information on asbestos and vermiculite visit, the following Web sites:

It's Your Health article Vermiculite Insulation Containing Asbestos at: www.hc-sc.gc.ca/iyh-vsv/prod/ insulation-isolant_e.html

Report No. 50998



Powered by Knowledge

Page 49 of 50

REFERENCE LIBRARY

Report No. 50998

	FERENCE LIBRARY rickland Ave, Toronto, ON November 10, 2015	www.carsondunlop.com
OVERVI		SULATION PLUMBING
INTERIOR APPENDIX REFERENCE		
The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.		
Click on any link to read about that system.		
>>>	01. ROOFING, FLASHINGS AND CHIMNEYS	
>>	02. EXTERIOR	
>>>	03. STRUCTURE	
\otimes	04. ELECTRICAL	
\otimes	05. HEATING	
>>>	06. COOLING/HEAT PUMPS	
>>>	07. INSULATION	
\bigcirc	08. PLUMBING	
>>>	09. INTERIOR	
>>>	10. APPLIANCES	
>>	11. LIFE CYCLES AND COSTS	
>>	12. SUPPLEMENTARY	
	Asbestos	
	Radon	
	Urea Formaldehyde Foam Insulation (UFFI) Lead	
	Carbon Monoxide	
	Mold	
	Household Pests	
	Termites and Carpenter Ants	
\bigotimes	13. HOME SET-UP AND MAINTENANCE	
>>	14. MORE ABOUT HOME INSPECTIONS	
		Value of the local division of the local div

Powered by Knowledge