



# YOUR INSPECTION REPORT

*Inspections Delivering Peace Of Mind*

**PREPARED BY:**

Troy Rack



**FOR THE PROPERTY AT:**

123 Oak St  
My Village, ON M1E 4P3

**PREPARED FOR:**

JOHN SMITH

**INSPECTION DATE:**

Thursday, July 5, 2012



Rival Inspection Services Inc.  
32 Winterberry Dr.  
Whitby, ON L1R 1Z2

905 922 5437

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

[rival@rogers.com](mailto:rival@rogers.com)





February 27, 2014

Dear John Smith,

RE: Report No. 1404, v.6  
123 Oak St  
My Village, ON  
M1E 4P3

Thank you for choosing Rival Inspection Services to perform your Home Inspection. We trust the experience was both informative and enjoyable.

The primary purpose of this inspection has been to educate you about the general condition of this home and its major systems and components. The inspection itself and the attached report comply with the requirements of the Canadian National Association of Certified Home Inspectors Standards of Practice. This document, which is included at the end of the report for your perusal, defines the scope of a home inspection.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein. The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

The Appendix and Reference sections at the end of the report will also provide you with comprehensive user friendly information on your home maintenance, repair and cost effective home improvement advice. We hope that it will be a reliable source for future reference.

Finally, we will continue to be here for you as long as you own this home. Please do not hesitate to contact us with any questions you may have.

Sincerely,

Troy Rack  
on behalf of  
Rival Inspection Services Inc.

Rival Inspection Services Inc.  
32 Winterberry Dr.  
Whitby, ON L1R 1Z2  
905 922 5437  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)  
[rival@rogers.com](mailto:rival@rogers.com)



# INVOICE

February 27, 2014

Client: John Smith

Report No. 1404, v.6

For inspection at:

123 Oak St

My Village, ON

M1E 4P3

on: Thursday, July 5, 2012

Home inspection	\$0.00
Infrared - Basic	\$0.00
Indoor Air Sampling	\$0.00
Suite Package	\$0.00

---

PAID IN FULL - THANK YOU!

Rival Inspection Services Inc.  
32 Winterberry Dr.  
Whitby, ON L1R 1Z2  
905 922 5437  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)  
[rival@rogers.com](mailto:rival@rogers.com)

# SUMMARY

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

The Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

The deficiencies listed in the report and the components related to these should be further evaluated and repaired by a licensed contractor or professional. This will allow a specialist to fully evaluate the system and components, and identify issues beyond our scope of work.

There are some important things you should do when taking possession of a home. These are detailed in the Priority Maintenance document, which you can access by clicking on the link below.

[Click this link for some important maintenance tips](#)

## Roofing

### **SLOPED ROOF FLASHINGS \ Chimney flashings**

**Condition:** • [Cricket missing, loose, damaged](#)

Cricket flashing at chimney is missing. Recommend a qualified roofer install to prevent water infiltration around chimney area.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

## Exterior

### **EXTERIOR GLASS \ General**

**Condition:** • [Lintel missing](#)

This should be assessed and rectified by a qualified contractor.

**Implication(s):** Weakened structure | Chance of structural movement

### **EXTERIOR GLASS \ Window wells**

**Condition:** • Missing window well cover: Open window wells should have either grates or, preferably, a weatherproof shield installed over them. This will keep debris, rain and snow from building up inside the well and possibly leaking into the home, as well as minimizing your liability from children falling inside them. If necessary, an egress ladder should also be installed within the well, especially at below-grade bedrooms. Recommend a qualified contractor to assess and install.

This should be considered a safety hazard.

**Location:** West

**Task:** Install

**Time:** Earliest opportunity

### **PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards**

**Condition:** • [Missing](#)

All exterior stairs with 3 or more steps require a handrail. Recommend a qualified carpenter install handrail for safety.

**Implication(s):** Fall hazard

**Task:** Install

**Time:** Earliest opportunity

# SUMMARY

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## LANDSCAPING \ Walkway

**Condition:** • [Uneven \(trip hazard\)](#)

Recommend a qualified contractor grind the uneven surface to prevent tripping.

**Implication(s):** Physical injury

## Electrical

### DISTRIBUTION SYSTEM \ Outlets (receptacles)

**Condition:** • [No GFI \(Ground Fault Interrupter\)](#)

This outdoor receptacle is not GFCI protected (cover is also broken).

**Implication(s):** Electric shock

### DISTRIBUTION SYSTEM \ Cover plates

**Condition:** • [Missing](#)

Various cover plates are missing through house.

**Implication(s):** Electric shock

## Heating

### GAS FURNACE \ Life expectancy

**Condition:** • [Near end of life expectancy](#)

**Implication(s):** Equipment failure | No heat for house

## Cooling & Heat Pump

### AIR CONDITIONING \ Life expectancy

**Condition:** • [Near end of life expectancy](#)

**Implication(s):** Equipment failure | Reduced comfort

THIS CONCLUDES THE SUMMARY SECTION.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a home inspection. These may have to be adjusted based on the findings of specialists.

The inspection is performed by a generalist, and in some cases, we will recommend specialists to further investigate conditions that we have identified. This is very similar to the doctor who is a general practitioner, identifying a physical condition and recommending further testing by a specialist.

Home inspectors have a limited amount of time on site. Market conditions and inspection fees dictate that inspections typically run about 2 - 3 hours. As a result, there will be things that are not picked up by inspectors. We ask that you understand and accept this. The inspection provides great value, and adds considerably to your understanding of the

# SUMMARY

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

home. But it is not an insurance policy with a one-time only premium, no exclusions, no deductible and no limits.

Please read the report carefully, and feel free to ask any questions that you may have of the inspector. Again, we will remind you that a home inspection addresses visually accessible components of the home, and does not include destructive testing. We will operate mechanical systems with normal homeowner controls. Where there are many systems of a similar type and a home, we inspect a representative sample. For example, we do not inspect every electrical outlet, every piece of siding or every brick or every window.

As you read the report, we encourage you to contact us with any questions about the report or the home.

The link below provides some typical costs for home repairs and improvements.

[Home Improvement - ballpark costs](#)

# ROOFING

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

**General:** • NOTE: Any amount of water infiltration may lead to mold growth, building material damage and/or structural integrity issues. If water infiltration exist, a qualified contractor should assess and rectify these conditions as soon as possible to avoid any further damage from occurring.

**General:** • Approximate age of roof covering:

Note: 10 - 12 years. As per owner

**General:** • Roofing material showing typical wear for age

**Sloped roofing material:** • [Asphalt shingles](#)

**Probability of leakage:** • Evidence of water infiltration: None found today

**Probability of leakage:** • Medium

## Limitations

**General:** • Roof access is at the sole discretion of the inspector. Work safety and potential material damage are the governing factors.

**General:** • This report is an opinion of the general quality and condition of the roofing. As such the inspector cannot and does not offer an opinion or warranty as to whether the roof has leaked in the past, leaks now or is subject to future leakage. An inspector cannot accurately predict roofing system failure.

**Inspection performed:** • By walking on roof • With binoculars from the ground • From roof edge

## Recommendations

### RECOMMENDATIONS \ Overview

**1. Condition:** • Recommend a roof tune-up every 5 years by a roofing professional to maintain the roofs life expectancy and reduce the chance of water infiltration.

**2. Condition:** • Moss/algae growth noted on roof surface. As a result, shingles can lift or be damaged. Leaks can result and/or the roof surface can fail prematurely. Recommend a qualified handyman to rectify to avoid any accelerated material damage.



1. Moss/algae growth noted on roof surface. As...

## **SLOPED ROOFING \ Asphalt shingles**


**3. Condition:** • [Cupping, curling, clawing](#)

**4. Condition:** • [Cracked](#)

Shingles on south side showing excessive wear.

**Task:** Monitor

**Time:** Ongoing



[Click on image to enlarge.](#)

## **SLOPED ROOF FLASHINGS \ Chimney flashings**

**5. Condition:** • [Cricket missing, loose, damaged](#)

Cricket flashing at chimney is missing. Recommend a qualified roofer install to prevent water infiltration around chimney area.


**Implication(s):** Chance of water damage to contents, finishes and/or structure

# ROOFING

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
www.rivalhomeinspections.ca

SUMMARY	<b>ROOFING</b>	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



[Click on image to enlarge.](#)

## SLOPED ROOF FLASHINGS \ Roof/sidewall flashings


### 6. Condition: • Siding not cut back

Wood siding is touching roof flashing. Water can wick up the wood siding causing rot.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Task:** Improve

**Time:** When remodelling



[Click on image to enlarge.](#)

# EXTERIOR

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
www.rivalhomeinspections.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

**Gutter & downspout discharge:** • [Above grade](#)

**Lot slope:** • [Away from building](#) • [Flat](#)

**Wall surfaces - wood:** • [Boards](#)

**Wall surfaces - masonry:** • [Brick](#) • [Stone](#)

**Soffit and fascia:** • [Metal](#)

**Driveway:** • Asphalt

**Walkway:** • Concrete • Interlocking brick

**Deck:** • Ground level • Pressure-treated wood

**Porch:** • Concrete

**Exterior steps:** • Concrete

**Patio:** • Interlocking brick

**Fence:** • Wood

## Limitations

**General:** • This report does not include geological or soil conditions. For this information a Geotechnical Engineer should be consulted.


**General:** • Gutters, downspouts and subsurface drains are not water tested for leakage or blockage. These components require regular maintenance to avoid water problems at roof and foundation.

**Inspection limited/prevented by:** • Grading not visible due to:

*Note:* Deck area

**Inspection limited/prevented by:**

• Car/storage in garage



2. Car/storage in garage

# EXTERIOR

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

**EXTERIOR**

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

- Poor access under steps, deck, porch
- Limited view under rear deck
- Vines/shrubs/trees against wall

## Recommendations

### **General**

7. • Grading and drainage are probably the most significant aspects of a property, simply because of the direct and indirect damage that moisture can have on structures. We suggest a positive grade away from the foundation walls around the entire house whenever possible to further channel water away from the foundation walls and reduce the potential for possible water infiltration into the home.
8. • Preventing Leakage - Ongoing maintenance is required for caulking on all doors, windows and wall penetrations such as furnace vents, hose bibs, air conditioning lines etc.
- It is recommended that the caulking is inspected annually for deterioration and replaced as required by a qualified contractor.
9. • Exterior caulking is the simplest energy-efficient measures to install. The purpose of exterior caulking is to minimize air flow and moisture through cracks, seams, and utility penetrations/openings. Controlling air infiltration is one of the most cost effective measures in modern construction practices. A home that is not sealed will be uncomfortable due to drafts and will use about 30% more heating and cooling energy than a relatively air-tight home. In addition, good caulking and sealing will reduce dust and dirt in the home and prevent damage to structural elements.
10. • Maintaining wood: All exterior wood needs regular maintenance to prolong the life expectancy. Recommend annual inspections and provide paint and caulking when necessary. The wood should be checked for any rot when preparing to paint and the wood should be repaired or replaced if necessary. Recommend a qualified contractor to inspect annually and maintain as required.
11. • Wood to soil contact is conducive to rot, decay and wood destroying insect infestation. Recommend that a qualified contractor repair as necessary. All rotten wood should be replaced.

### **ROOF DRAINAGE \ Gutters**

12. **Condition:** • Maintenance - The guttering system needs to be maintained to allow proper drainage away from the home. Recommend a qualified handyman to clean regularly to prevent leaking and improve water flow. Monitor during a moderate to heavy rain and seal or repair as needed.
13. **Condition:** • [Clogged](#)
- Implication(s):** Chance of water damage to contents, finishes and/or structure

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								




3. Clogged

### ROOF DRAINAGE \ Downspouts

**14. Condition:** • [Downspouts end too close to building](#)

Recommend extensions (4 to 6 ft) are installed to direct water discharge away from building foundation to avoid water infiltration.

**Implication(s):** Chance of water damage to contents, finishes and/or structure



[Click on image to enlarge.](#)

SUMMARY	ROOFING	<b>EXTERIOR</b>	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								




4. Downspouts end too close to building

**15. Condition:** • [Downspouts discharging onto roofs](#)

Gutters from upper roofs should discharge directly in to the lower gutter system. Excessive wear on lower roof shingles may allow water infiltration in to roof area. Recommend a qualified handyman install downspout.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Time:** as soon as possible



[Click on image to enlarge.](#)

SUMMARY	ROOFING	<b>EXTERIOR</b>	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



[Click on image to enlarge.](#)

### WALLS \ Soffits and fascia

16. **Condition:** • No issues found at time of inspection.

### WALLS \ Trim

17. **Condition:** • [Caulking missing or deteriorated](#)

**Task:** Recommend a qualified handyman to assess and rectify to avoid further deterioration

**Time:** Earliest opportunity



5. *Caulking missing or deteriorated*


SUMMARY	ROOFING	<b>EXTERIOR</b>	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

**WALLS \ Wood siding**

**18. Condition:** • [Too close to grade](#)

Recommend a landscaper lower ground around areas where soil contact the wood siding. Ensure lot grading slopes away from house.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Material deterioration | Rot | Insect damage



Click on image to enlarge.



6. Siding too close to grade


SUMMARY	ROOFING	<b>EXTERIOR</b>	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

## EXTERIOR GLASS \ General


### 19. Condition: • [Lintel missing](#)

This should be assessed and rectified by a qualified contractor.

**Implication(s):** Weakened structure | Chance of structural movement



[Click on image to enlarge.](#)



[Click on image to enlarge.](#)

# EXTERIOR

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

**EXTERIOR**

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



7. Missing

## EXTERIOR GLASS \ Exterior trim

**20. Condition:** • [Missing or loose pieces](#)

**Implication(s):** Cosmetic defects | Chance of water damage to contents, finishes and/or structure



8. Missing

## EXTERIOR GLASS \ Window wells

**21. Condition:** • Missing window well cover: Open window wells should have either grates or, preferably, a weatherproof shield installed over them. This will keep debris, rain and snow from building up inside the well and possibly leaking into the home, as well as minimizing your liability from children falling inside them. If necessary, an egress ladder should also be installed within the well, especially at below-grade bedrooms. Recommend a qualified contractor to assess and install.


This should be considered a safety hazard.

**Location:** West

**Task:** Install

**Time:** Earliest opportunity

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



Click on image to enlarge.

**PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards**


**22. Condition:** • [Missing](#)

All exterior stairs with 3 or more steps require a handrail. Recommend a qualified carpenter install handrail for safety.

**Implication(s):** Fall hazard

**Task:** Install

**Time:** Earliest opportunity



Click on image to enlarge.

# EXTERIOR

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

**EXTERIOR**

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



9. Missing

## PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ General

**23. Condition:** • Maintenance - Whether treated or not, it is important to keep a wood deck surface free of all forms of fungal growth and debris that retains moisture and will cause the deck to eventually rot. Recommend cleaning and re-sealing the deck annually by a qualified contractor.



10. Maintenance - Whether treated or not, it is...

## LANDSCAPING \ Driveway

**24. Condition:** • Recommend sealing the driveway as part of routine maintenance to educe deterioration and prolong the functional life of the driveway.

**25. Condition:** • [Cracked or damaged surfaces](#)

Typical cracks in driveway

**Task:** Monitor

# EXTERIOR

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

**EXTERIOR**

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## LANDSCAPING \ Walkway

**26. Condition:** • [Cracked or damaged surfaces](#)

**Implication(s):** Trip or fall hazard



11. *Cracked or damaged surfaces*

**27. Condition:** • [Uneven \(trip hazard\)](#)

Recommend a qualified contractor grind the uneven surface to prevent tripping.

**Implication(s):** Physical injury



12. *Uneven (trip hazard)*

## LANDSCAPING \ General

**28. Condition:** • Vegetation too close to the home can contribute to damage through root damage to the foundation, branches abrading the roof and siding, and leaves providing a pathway for moisture and insects into the home.

Recommend a landscaper or arborist to prune, move or remove vegetation as necessary to avoid damage and encourage surface drying.

# EXTERIOR

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

**EXTERIOR**

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


APPENDIX

REFERENCE

## 29. Condition: • [Trees or shrubs too close to building](#)

Vegetation should be trimmed back from structure to prevent hidden damage and encourage surface drying.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Chance of pests entering house | Material deterioration



[Click on image to enlarge.](#)



13. *Trees or shrubs too close to building*

## **IRRIGATION / SPRINKLER SYSTEM \ Observations**

**30. Condition:** • Irrigation/sprinkler systems are beyond the scope of this inspection and were not inspected or operated. These systems require seasonal maintenance and settings. Recommend having system inspected and tested by an irrigation contractor. At this time have contractor explain system operation and maintenance.

## Description

**General:** • NOTE: Any amount of water infiltration may lead to mold growth, building material damage and/or structural integrity issues. If water infiltration exist, a qualified contractor should assess and rectify these conditions as soon as possible to avoid any further damage from occurring.

**Configuration:** • [Basement](#)

**Foundation material:** • [Poured concrete](#)

**Floor construction:** • [Joists](#) • Steel columns • Steel beams • Subfloor - plywood

**Exterior wall construction:** • [Wood frame](#) • [Masonry](#)

**Roof and ceiling framing:** • [Trusses](#) • [OSB \(Oriented Strand Board\) sheathing](#)

## Limitations

**General:** • Foundation Cracks and Structural Member Issues - These conditions, no matter how small, must be evaluated by a Licensed Contractor or Consulting Engineer. It is beyond the scope of our Standards of Practice and the Inspector's expertise to properly evaluate these conditions.

**General:** • Attic and/or crawl space access is at the sole discretion of the inspector. Work safety and potential material damage are the governing factors.

**Inspection limited/prevented by:** • Wall, floor and ceiling coverings • Carpet/furnishings • Storage • New finishes/paint • Insulation

**Attic/roof space:** • The attic was partially accessed and viewed from hatch area only. Entering attics that are insulated can cause damage to the insulation, attic framing and the ceiling directly below attic. In addition attics with deep insulation cannot be safely inspected due to the limited visibility of the framing members. Based on this our review of the attic space is limited to visually accessible areas as observed from the hatch only.

**Percent of foundation not visible:** • As seen from the outside of the building

**Percent of foundation not visible:**

• 95 %


As seen from the outside of the building

## Recommendations

### **FOUNDATIONS \ Foundation**

**31. Condition:** • Typical hairline foundation cracks were noted. All cracks are risks for water ingress or structural movement although it may be normal concrete curing cracks. Any cracks, gaps or openings should be sealed to prevent potential water infiltration. Recommend monitoring all cracks and seek advice from a qualified foundation contractor.

SUMMARY	ROOFING	EXTERIOR	<b>STRUCTURE</b>	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



[Click on image to enlarge.](#)

## ROOF FRAMING \ Rafter/trusses

### 32. Condition: • [Modified or spliced](#)

Recommend a qualified framer assess and repair framing members in attic

**Implication(s):** Weakened structure | Chance of structural movement

**Time:** Earliest opportunity



14. Missing webs

SUMMARY	ROOFING	EXTERIOR	<b>STRUCTURE</b>	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								


### **ROOF FRAMING \ Sheathing**

**33. Condition:** • Stains observed on wood in attic area indicate previous leakage. Stains observed were dry at the time of the inspection. Stains were checked with a moisture meter where accessible at the time of the inspection and levels were normal. Wood and insulation was dry in the surrounding area. The stains may be from prior to having the roof replaced or serviced. Determining the condition of staining whether it be active or previous is beyond the scope of the inspection. Conditions for determining if stains are active may not be present at, or in recent time of the time of the inspection. Leakage may occasionally occur during wind swept rains or inadequate drainage from snow or ice. Check with the seller regarding history of leaks. This area should be monitored in the future during heavy rain and repaired as needed.

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	<b>ELECTRICAL</b>	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

## Description

**General:** • It is recommended that GFCI (ground fault circuit interrupter) protection is installed for any electrical outlet located outside, in bathrooms or within 1.5m (5') of any sink, such as kitchens and laundry areas. These safety devices should be tested regularly in accordance with the manufacturer's specifications.



**General:** • Modern electrical codes require branch circuits at all bedrooms to be AFCI (arc fault circuit interrupter) protected. The electrical code at the time this house was built may not have required AFCI protection at these circuits. Nonetheless, we strongly recommend they be added to all bedroom circuits as an extra preventive fire safety measure.

**Service entrance cable and location:** • [Underground - not visible](#)

**Service size:** • [200 Amps \(240 Volts\)](#)

**Main disconnect/service box rating:** • [200 Amps](#)

**Main disconnect/service box type and location:** • [Breakers - basement](#)

**System grounding material and type:** • [Copper - water pipe](#)

**Distribution panel rating:** • [200 Amps](#)

**Distribution panel type and location:** • [Breakers - basement](#)

**Distribution wire material and type:** • [Copper - non-metallic sheathed](#)

**Type and number of outlets (receptacles):** • Split receptacle(s) were noted in the kitchen. Split receptacles are special outlets in which the upper and lower halves of a duplex receptacle are on separate current overload protection devices (i.e. fuses or breakers). This arrangement allows for a kettle to be plugged into the upper half of the outlet, for example, and a toaster to be plugged into the lower half without the danger of overheating of the associated electrical wires or blowing/tripping a fuse or breaker.

**Type and number of outlets (receptacles):** • [Grounded - typical](#)

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • No AFCI

**Smoke detectors:** • [Present](#)

**Carbon monoxide (CO) detectors:** • None noted

## Limitations

**General:** • Many of the components that make up an electrical system are concealed in wall cavities, conduits, chases, junction boxes etc. No commentary will be provided on concealed items.

**Inspection limited/prevented by:** • Storage • Insulation

**System ground:** • Continuity not verified • Quality of ground not determined

**Circuit labels:** • The accuracy of the circuit index (labels) was not verified.

## Recommendations

### General

**34.** • All electrical issues noted should be assessed and rectified by a Licensed Electrician to avoid possible electrical shock and/or fires.

All electrical recommendations should be considered high priority items, since all electrical issues are safety concerns.

**35.** • Ensure that you have working smoke alarms and CO detectors installed on every floor and near bedrooms. Battery powered smoke detectors should be installed in every bedroom for back-up.

Typically these devices have a lifespan of 5 - 10 years. Ten year old detectors are less than 50% effective. Test and replace them regularly according to manufacturer's specifications.

Since the age and maintenance of existing detectors can not be determined we recommend a licensed electrician install new smoke and CO detectors as soon as possible.

### SERVICE BOX, GROUNDING AND PANEL \ Distribution panel


**36. Condition:** • Labeling of circuits is incomplete and/or unclear.

### DISTRIBUTION SYSTEM \ Wiring - installation


**37. Condition:** • [Double taps](#)

**Implication(s):** Fire hazard

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	<b>ELECTRICAL</b>	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



[Click on image to enlarge.](#)



15. Double taps

## DISTRIBUTION SYSTEM \ Lights

38. Condition: • [Missing](#)

Light fixture missing in upstairs hallway. Recommend a qualified contractor install asap for safety.

**Implication(s):** Inadequate lighting



16. Missing

### DISTRIBUTION SYSTEM \ Junction boxes

39. Condition: • [Missing, loose](#)

Implication(s): Electric shock | Fire hazard

Location: Attic

Task: Install

Time: Earliest opportunity

### DISTRIBUTION SYSTEM \ Outlets (receptacles)


40. Condition: • [Reversed polarity](#)

Some electric receptacles had reverse-polarity wiring, where the hot and neutral wires are reversed. This is a safety hazard due to the risk of shock. However reversed polarity, hot and neutral reversed and other terms used for electric receptacles are usually easily corrected by minor wiring adjustments at the specified item. When these conditions are noted in this report, a licensed electrician should be consulted for repairs/replacement as needed to ensure safety.

Implication(s): Electric shock

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	<b>ELECTRICAL</b>	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								


### Reversed polarity



when the polarity is reversed, the wide receptacle slot is (incorrectly) hot and the narrow slot is neutral - this is not uncommon when people forget that the black wire should be attached to the receptacle's brass screws

[Click on image to enlarge.](#)

### Importance of correct polarity with light fixtures



[Click on image to enlarge.](#)



17. Reversed polarity

**41. Condition:** • [No GFI \(Ground Fault Interrupter\)](#)

This outdoor receptacle is not GFCI protected (cover is also broken).

**Implication(s):** Electric shock



18. No GFI (Ground Fault Interrupter)

**DISTRIBUTION SYSTEM \ Cover plates**

**42. Condition:** • [Missing](#)

Various cover plates are missing through house.

**Implication(s):** Electric shock



19. Missing

## DISTRIBUTION SYSTEM \ Carbon monoxide (CO) detectors

43. Condition: • None

# HEATING

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6  
[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

**Fuel/energy source:** • [Gas](#)

**System type:** • [Furnace](#)

**Furnace manufacturer:**

• York



20. York

**Heat distribution:** • [Ducts and registers](#)

**Efficiency:** • [Mid-efficiency](#)

**Approximate age:** • [22 years](#) • Near end of life expectancy

**Typical life expectancy:** • Furnace (conventional or mid-efficiency) 18 to 25 years

**Main fuel shut off at:** • Meter

**Failure probability:** • [High](#)

**Exhaust pipe (vent connector):** • Type B

**Fireplace:** • [Wood-burning fireplace](#)

**Chimney/vent:** • [Masonry](#)

**Chimney liner:** • [Clay](#)

## Limitations

**General:** • Thermostats are not checked for calibration or timed functions

**Heat loss calculations:** • Not done as part of a building inspection


**Fireplace/wood stove:** • Quality of chimney draw cannot be determined

## Recommendations

### General

**44.** • Annual servicing and cleaning by a licensed technician is recommended for your furnace to achieve maximum efficiency and service life.

Also, having your ducts professionally cleaned will improve indoor air quality.



*21. Have the system cleaned by a qualified...*

**45.** • Recommend a qualified carpenter to undercut bedroom doors to allow more air movement which will increase air balancing allowing a more uniform air temperature.

### GAS FURNACE \ Life expectancy

**46. Condition:** • [Near end of life expectancy](#)

**Implication(s):** Equipment failure | No heat for house

### GAS FURNACE \ Thermostat

**47. Condition:** • Recommend the client have the homeowner provide the instructions for programming or show the client how to do so.

**48. Condition:** • Location:

**Location:** First Floor Dining Room

### GAS FURNACE \ Mechanical air filter

**49. Condition:** • Maintenance - The air filter(s) should be inspected at least monthly and cleaned or replaced as required. There are two types of filters commonly used: (1) Washable filters, (constructed of aluminum mesh, foam, or reinforced fibers) these may be cleaned by soaking in mild detergent and rinsing with water. Or (2) Fiberglass disposable filters that must be replaced before they become clogged. Remember that dirty filters are the most common cause of inadequate heating or cooling performance.

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	<b>HEATING</b>	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

**50. Condition:** • [Dirty](#)

**Implication(s):** Increased heating costs | Reduced comfort

**Task:** Replace

**Time:** Earliest opportunity

**FIREPLACE \ General**

**51. Condition:** • Wood burning fireplaces and stoves are beyond the scope of this inspection. Recommend W.E.T.T. (wood energy technology transfer) certification for safety and insurance purposes.

**CHIMNEY AND VENT \ Inspect/sweep chimney**

**52. Condition:** • [Inspect \(and/sweep if needed\) before using](#)


**Implication(s):** Fire hazard

**CHIMNEY AND VENT \ Masonry chimney**

**53. Condition:** • [Loose, missing or deteriorated masonry](#)

Recommend a qualified mason assess and repair chimney as needed

**Implication(s):** Material deterioration



[Click on image to enlarge.](#)



**22. Loose, missing or deteriorated masonry**

- SUMMARY
  - ROOFING
  - EXTERIOR
  - STRUCTURE
  - ELECTRICAL
  - HEATING**
  - COOLING
  - INSULATION
  - PLUMBING
  - INTERIOR
- APPENDIX REFERENCE

## CHIMNEY AND VENT \ Masonry chimney cap


**54. Condition:** • Recommend a metal liner to be installed by a qualified contractor to reduce chimney deterioration caused by gases.

**55. Condition:** • [Screen missing or damaged](#)

**Implication(s):** Chance of pests entering house | Fire hazard

**56. Condition:** • [Rain cap missing or damaged](#)

**Implication(s):** Chance of water entering house | Chance of pests entering house



[Click on image to enlarge.](#)

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

## Description

**Air conditioning type:** • [Air cooled](#)

**Manufacturer:** • York

**Compressor approximate age:** • 22 years • Near end of life expectancy

**Failure probability:** • [High](#)

## Limitations

**Not part of a home inspection:** • Automatic safety controls not tested • No pressure tests are performed on coolant systems, and no representation is made regarding coolant charge or line integrity.

## Recommendations

### AIR CONDITIONING \ Life expectancy

**57. Condition:** • [Near end of life expectancy](#)


**Implication(s):** Equipment failure | Reduced comfort

### AIR CONDITIONING \ Refrigerant lines

**58. Condition:** • [Missing insulation](#)

Have a qualified HVAC technician assess AC system

**Implication(s):** Reduced system life expectancy | Increased cooling costs | Reduced comfort



# COOLING & HEAT PUMP

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



**23.** *Missing insulation*

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

**INSULATION**

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

**General:** • Evidence of insects/rodents/pests found today

**Attic/roof insulation material:** • [Glass fiber](#)

**Attic/roof insulation amount/value:** • Approximate thickness:

*Note:* 18 inches

**Attic/roof ventilation:** • [Roof and soffit vents](#)

**Attic/roof air/vapor barrier:** • [Plastic](#)

**Wall insulation material:** • Not visible

**Wall insulation amount/value:** • Not determined

**Wall air/vapor barrier:** • Not determined

**Foundation wall insulation material:** • [Glass fiber](#)

**Foundation wall air/vapor barrier:** • Plastic

## Limitations

**General:** • Concealed insulation and vapour barriers not inspected.

**General:** • Air / Vapour barrier continuity not inspected

**Air/vapor barrier system:** • Continuity not verified

**Mechanical ventilation effectiveness:** • Not verified

## Recommendations

### General

**59.** • Evidence of insects/rodents/pests found today:

In attic area

**60.** • Evidence of mice or rodent droppings present in attic area. Inspector cannot determine if active infestation is present or if the droppings are from the past. Since mice and rodents can carry disease, they are considered a safety concern and should be treated accordingly by a qualified exterminator. Note: When rodent droppings are present, there is the potential for hidden mold and/or damage to electrical wiring below insulation, damage to heating/duct work, etc. It is beyond the scope of this inspection to remove insulation to determine if hidden damage may be present. Future investigative work is advised to make sure no hidden damage is present below insulation due to rodent activity.

# INSULATION AND VENTILATION

123 Oak St, My Village, ON July 5, 2012

Report No. 1404, v.6

[www.rivalhomeinspections.ca](http://www.rivalhomeinspections.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



24. Evidence of mice or rodent droppings presen...

## **RECOMMENDATIONS \ Overview**

**61. Condition:** • Recommend attic be "top-up" with insulation to lower energy costs and improve comfort. Consult a insulation contractor for advise.

## Description

**General:** • Water Leaks - Any amount of water may lead to mold growth, building material damage and/or structural integrity issues. A qualified contractor should assess and rectify these conditions as soon as possible to avoid further damage.

**Water supply source:** • Public

**Service piping into building:** • [Copper](#)

**Supply piping in building:** • [Copper](#)

**Main water shut off valve at the:** • South • Basement • Meter

**Water flow and pressure:** • [Typical for neighborhood](#)

**Water heater fuel/energy source:** • [Gas](#)

**Water heater manufacturer:** • Rheem

**Tank capacity:** • 50 gallons

**Water heater approximate age:**

• 6 years

As per serial number

**Typical life expectancy:** • Gas hot water heaters typically have a life expectancy of 7 - 10 years

**Water heater failure probability:** • [Medium](#)

**Waste piping in building:** • [ABS plastic](#)

**Floor drain location:** • Near water heater

**Gas piping:** • Steel

## Limitations

**General:** • Many of the components that make up a plumbing system are concealed in floor, wall, and ceiling chases. No commentary is offered on concealed components.

Evaluation of the plumbing system was limited to permanently connected fixtures and readily visible conditions. The function and effectiveness of laundry stand pipes, vent pipes, floor drains, fixture overflows, anti-siphon devices and similar items generally cannot be evaluated. Conditions are subject to unpredictable change, e.g; leaks may develop, water flow may drop, drains may become blocked, etc. The detection of sewer gases and the condition/function of sub-slab or in ground piping is excluded from a standard inspection.

## Recommendations

### General

**62.** • Preventing Leakage - Ongoing maintenance is required for grout and caulking in showers and bath tub areas. It is recommended that the grout and caulking is inspected annually for deterioration and repaired or replaced as required by a qualified contractor to avoid water infiltration.

### SUPPLY PLUMBING \ Supply piping in building

**63. Condition:** • Some minor corrosion was noted at some locations where pipe unions and valves were installed that should be monitored; corrosion can be the precursor for leaks. Some corrosion can typically occur as a result of residual flux material that can remain on the pipe/fitting from the original soldering process.

**Task:** Monitor

**Time:** Ongoing

### WATER HEATER \ Temperature/pressure relief valve

**64. Condition:** • The water heater's temperature-pressure relief valve drain line is routed upward. This valve is an emergency device, but periodically small amounts of water could be discharged. If the drain is routed up, water can collect near the valve and that can lead to corrosion and impair the operation of the valve during an emergency. Therefore, drain line must be routed either down or horizontally. Recommend having a qualified plumbing contractor repair. Suggest that plumber, while on site, evaluate system and make additional recommendations for improvements.




25. TPR valve facing up

**65. Condition:** • [Discharge tube missing](#)

**Implication(s):** Scalding

**Time:** Earliest opportunity

- SUMMARY
  - ROOFING
  - EXTERIOR
  - STRUCTURE
  - ELECTRICAL
  - HEATING
  - COOLING
  - INSULATION
  - PLUMBING**
  - INTERIOR
- APPENDIX REFERENCE



Click on image to enlarge.

## WASTE PLUMBING \ Traps - performance

66. Condition: • [Leak](#)

Implication(s): Sewage entering the house

Location: Bathroom Master Bathroom

Task: Repair

Time: Immediate



26. Leak

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	<b>PLUMBING</b>	INTERIOR
APPENDIX	REFERENCE								

## **FIXTURES AND FAUCETS \ Basin, sink and laundry tub**

**67. Condition:** • Recommend shutting off valves to washing machine when not in use to avoid bursting of rubber hoses and causing severe water damage.

Upgrading to braided stainless steel supply lines can increase reliability.

**68. Condition:** • Tip: Installing a water catch tray under the washing machine can prevent minor leaks from causing damage. Also, for washing machines with their water discharge in to the laundry tub we strongly suggest not to hang clothes along the edge of the tub. If they block the drain they may cause tub to overflow.

## **FIXTURES AND FAUCETS \ Shower stall**

**69. Condition:** • Grab bar and anti-slip flooring should be installed for safety.

## **FIXTURES AND FAUCETS \ Shower stall enclosure**

**70. Condition:** • [Caulking loose, missing or deteriorated](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure



**27.** *Caulking loose, missing or deteriorated*



**28.** *Caulking loose, missing or deteriorated*

## **FIXTURES AND FAUCETS \ Hose bibb**


**71. Condition:** • The hose bibs that were tested are functional but do not include anti-siphon valves. These valves are relatively inexpensive and are required by current standards. Recommend installation of check valve to prevent water backflow.

**72. Condition:** • Exterior faucets should be winterized prior to cold season to protect pipes from freezing. Ensure garden hose is disconnected for proper drainage to prevent ice damage to the valve.

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

## Description

- Major floor finishes:** • [Carpet](#) • [Hardwood](#) • [Ceramic](#)
- Major wall finishes:** • [Plaster/drywall](#)
- Major ceiling finishes:** • [Plaster/drywall](#) • [Stucco/texture/stipple](#)
- Windows:** • [Fixed](#) • [Sliders](#) • [Casement](#)
- Glazing:** • [Double](#)
- Exterior doors - type/material:** • Metal-clad • Garage door - metal
- Evidence of basement leakage:** • No evidence of water infiltration noted at time of inspection
- Kitchen ventilation :** • Exhaust fan
- Bathroom ventilation :**
  - None



Click on image to enlarge.

- Laundry room ventilation:** • Exhaust fan

## Limitations

**General:** • Water stains / damage may or may not indicate active leaks. Stains / damage remain after leaks have been repaired, making it almost impossible to determine whether or not a leak is active. Often leak activity will only be able to be determined by multiple inspections, over time, under varying atmospheric conditions (rain, snow, etc.) Monitoring conditions is recommended. Moisture meter use: Moisture meters can only detect active leaks. Indications of dry materials only indicates that the condition does not exist at the time of test.

**Inspection limited/prevented by:** • Carpet • Storage/furnishings • Storage in closets/cupboards

**Not included as part of a building inspection:** • Smoke and fire alarms, carbon monoxide detectors, intercom systems, central vacuum systems, security systems etc.

**Cosmetics:** • No comment offered on cosmetic finishes

**Basement leakage:** • Storage in basement limited inspection

**Garage door opener:** • This inspection does not certify the safe operation on any automatic garage door opener.

## Recommendations

### General

**73.** • Please note that any leak or moisture issue can result in mold growth, building material damage and/or structural integrity issues. Furthermore, mold can grow very quickly, and although it may not be present one day, if moisture levels increase, mold can grow and become visible overnight. If water infiltration exist, a qualified contractor should assess and rectify these conditions as soon as possible to avoid any further damage from occurring.

**74.** • Foundation Cracks and Structural Member Issues - These conditions, no matter how small, must be evaluated by a Licensed Contractor or Consulting Engineer. It is beyond the scope of our Standards of Practice and the Inspector's expertise to properly evaluate these conditions.

**75.** • Carbon Monoxide detectors are mandatory in houses and should be tested weekly by pushing the test / reset button which enables the unit to reset itself internally, an audible sound will be heard to indicate the unit is functioning properly. Each unit should be cleaned / vacuumed regularly to reduce internal dust accumulation which will prevent false alarms or improper readings. Always refer to the manufacturers instructions for additional information regarding proper installation, use and maintenance.

**76.** • Programmable systems such as alarm, thermostat, intercom, sprinklers, etc... Recommend the client have the homeowner provide the instructions for programming or show the client how to do so.

### CEILINGS \ General

**77. Condition:** • Stains

Moisture level not elevated at time of inspection.

**Implication(s):** Cosmetic defects

**Location:** Master Bedroom

**Task:** Monitor

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



29. Stains

**WINDOWS \ Glass (glazing)**

**78. Condition:** • [Lost seal on double or triple glazing](#)

Condensation was noted in one or more double pane window(s). This indicates a break or deterioration in the seal(s). Recommend evaluation by a qualified window contractor and replacing panes where necessary.

**Implication(s):** Cosmetic defects



30. Lost seal on double or triple glazing


**WINDOWS \ Means of egress/escape**

**79. Condition:** • [Too small](#)

For safety, a basement area should not be used as a living space if there are not at least 2 ways to egress in case of fire or other emergency. A fire at the top of the only stairs could block escape and also consume the oxygen from the basement air causing loss of life. This includes rooms in finished basements. The window/s as installed are not egress accessible. As a result of the lack of egress, the areas should not be considered as a sleeping area for safety reasons. If the basement is occupied on a regular basis, recommend a qualified contractor assess the possibility of increasing window/s size for emergency egress.

- SUMMARY
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- APPENDIX
- REFERENCE

**Implication(s):** Restricted emergency exits



[Click on image to enlarge.](#)

### **DOORS \ Hardware**

**80. Condition:** • It is recommended that exterior door locks be re-keyed by a locksmith when you take possession of your home, so there will not be keys outstanding that could gain access to your home. Double keyed dead bolts pose a safety hazard and should be changed to have a latch inside as a means of egress.

### **BASEMENT \ Wet basement - evidence**

**81. Condition:** • Although there are no signs of active water penetration today, we caution you to consider any basement as wet until experience proves it dry. Dampproofing materials could loose their integrity with time and allow water seepage through the foundation walls especially after prolonged periods of rain.

### **GARAGE \ Man-door between garage and living space**

**82. Condition:** • The door has a pet access installed. This can allow harmful gases to enter the dwelling which may potentially hazardous. Recommend a carpenter to either close the opening or replace the door for safety.



31. *pet access door*

### **GARAGE \ Vehicle doors**

**83. Condition:** • Regular lubrication of the tracks and rollers is recommended. The garage door is the largest moving object in the home and potentially very dangerous. Operation of the mechanisms should be verified monthly. Children should be warned of the potential risk of injury.


### **GARAGE \ Vehicle door operators**

**84. Condition:** • Safety sensors operated normally, reversing the door when tested. The automatic garage door opener(s) reversed direction when met with resistance.

### **EXHAUST FANS \ Exhaust fan**

**85. Condition:** • There is no exhaust fan in the bathroom/s, it was not required when the house was built. However, lack of bathroom exhausts can cause a buildup of moisture and eventually mold in the structure, especially where showers are in use. All house exhausts should be directed and the vented towards the exterior of the structure. A qualified contractor should be used to install venting.

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								



[Click on image to enlarge.](#)

## APPLIANCES \ Dryer

**86. Condition:** • Faulty and clogged dryer vents have been responsible for thousands of fires, hundreds of injuries, and even deaths. The best vents are a smooth-walled metal type that travels a short distance; all other types should be regarded as suspect, and should be inspected bi-annually to ensure that they do not contain trapped lint or moisture.

**END OF REPORT**



Troy Rack

905.922.5437

rival@rogers.com

rivalhomeinspections.ca

## CANADIAN NATIONAL ASSOCIATION OF CERTIFIED HOME INSPECTORS

The Standards of Practice are a set of guidelines for home inspectors to follow in the performance of their inspections. The Standards of Practice and Code of Ethics are recognized by many related professionals as the definitive standard for professional performance in the industry.

The Canadian Association of Certified Home Inspectors (CanNACHI) is a not-for-profit association. CanNACHI's objectives include promotion of excellence within the profession and continual improvement of inspection services to the public.



### PURPOSE AND SCOPE

1. The purpose of these Standards of Practice is to establish a standard for private, fee-paid home inspectors who are members of CanNACHI. Home Inspections performed to these Standards of Practice are intended to provide the client with information regarding the condition of the systems and components of the home as inspected at the time of the Home Inspection.
2. The Inspector shall inspect readily accessible and installed systems and components of homes listed in these Standards of Practice.
3. The Inspector shall report on those systems and components inspected which, in the professional opinion of the inspector, are significantly deficient, or are near the end of their service lives.
4. The Inspector shall report a reason why, if not self-evident, the system or component is significantly deficient or near the end of its service life.
5. The Inspector shall make recommendations (if he or she chooses) to correct or monitor the reported deficiency.
6. The Inspector shall report on any systems and components designated for inspection in these Standards of Practice which were present at the time of the Home Inspection but were not inspected and a reason they were not inspected.
7. These Standards of Practice are not intended to limit inspectors from:
  - Including other inspection services, systems or components in addition to those required by these Standards of Practice.
  - Specifying repairs, provided the inspector is appropriately qualified and willing to do so.
  - Excluding systems and components from the inspection if requested by the client.

*The CanNACHI Standards of Practice does not cover asbestos, radon gas, lead paint, urea formaldehyde, toxic or inflammable chemicals, etc. Where inspectors are qualified to carry out such inspections, they may do so after receiving approval from the client and for an additional fee.*

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
<b>APPENDIX</b>	REFERENCE								

*Canadian National Association of Certified Home Inspectors*

**STANDARDS OF PRACTICE**

BUILDING SYSTEM	<i>The Inspector <b>is</b> required to:</i>	<i>The Inspector <b>is not</b> required to:</i>
	<ul style="list-style-type: none"> <li>♦ <b>Observe and report on the systems and components herein.</b></li> <li>■ <b>Perform tasks as noted herein.</b></li> </ul>	<ul style="list-style-type: none"> <li>♦ <b>Observe and report on the systems and components herein.</b></li> <li>■ <b>Perform tasks as noted herein.</b></li> </ul>
<b>ROOFING</b>	<ul style="list-style-type: none"> <li>♦ Roof covering materials</li> <li>♦ Roof penetrations and flashings</li> <li>♦ Chimneys</li> <li>♦ Skylights</li> <li>♦ Roof drainage components including gutters and downspouts</li> <li>♦ Evidence of water penetration</li> <li>♦ General structure of the roof from the readily accessible panels, doors or stairs or hatch</li> </ul>	<ul style="list-style-type: none"> <li>♦ Accessories that do not make up part of the roofing such as lightning arrestor systems, antennae, solar heating systems, de-icing equipment</li> <li>♦ Predict the service life expectancy of the roof</li> <li>♦ Inspect underground downspout diverter drainage pipes</li> <li>■ Move or disturb insulation</li> <li>■ Perform a water test</li> <li>■ Warrant or certify or guarantee the roof</li> <li>■ Walk on roofing where in judgement of the inspector could be dangerous or cause damage</li> </ul>
<b>EXTERIOR</b>	<ul style="list-style-type: none"> <li>♦ Exterior wall covering/surfaces, eaves and trim</li> <li>♦ Doors, windows, and flashings</li> <li>♦ Garages and carports that are attached to the main building</li> <li>♦ All exterior doors, decks, stoops, steps, stairs, porches, railings, eaves, soffits and fascias</li> <li>■ Balconies including stairs, guards and railings</li> <li>♦ Observe and report lot grading and vegetation as it affects the building</li> <li>♦ Retaining walls when these are likely to adversely affect the structure</li> <li>♦ Walkways and driveways on the building</li> <li>■ Test the operation of power operated garage door openers, including the stop and automatic reverse functions</li> </ul>	<ul style="list-style-type: none"> <li>♦ Geological, hydrological and/or ground and soil conditions</li> <li>♦ Yard fencing</li> <li>♦ Seasonal accessories such as removable storm windows, storm doors, screens and shutters</li> <li>♦ Storage sheds and other structures not part of the building</li> <li>♦ Any items or facilities not directly related to the building structure, such as swimming pools, saunas, hot tubs, tennis courts, etc.</li> <li>♦ Seawalls, break-walls and docks</li> <li>♦ Playground equipment or recreation facilities</li> <li>♦ Erosion control and earth stabilization measures</li> <li>♦ Drain fields or dry-wells, septic systems or cesspools</li> <li>♦ Water wells or springs</li> <li>♦ Determine the integrity of the thermal window seals or damaged glass</li> <li>♦ Verify or certify safe operation of any auto reverse or related safety functions of garage doors</li> </ul>
<b>STRUCTURE</b>	<ul style="list-style-type: none"> <li>♦ Visible foundation wall</li> <li>♦ Floors, columns, walls, roofs, attic</li> <li>♦ Report any general indications of foundation movement observed by the inspector, such as but not limited to drywall cracks, brick cracks, out-of-square door frames or floor slopes and concrete wall crack</li> <li>♦ Report on any cutting, notching and boring of framing members which may present a structural or safety concern</li> <li>♦ Chimney</li> <li>♦ Wood in contact or near soil</li> <li>♦ Crawl spaces, basement</li> <li>♦ Observe and report any evidence of water penetration and condensation</li> <li>♦ Observe and report on any evidence of deterioration from insects, rot, or fire</li> </ul>	<ul style="list-style-type: none"> <li>♦ Inspect areas that are not reasonably accessible or visible</li> <li>♦ Enter any crawlspaces that are not readily accessible or where entry could cause damage or pose a hazard to the inspector</li> <li>♦ Move stored items or debris</li> <li>♦ Identify size, spacing, span, location or determine adequacy of foundation bolting, bracing, joists, joist spans or support systems</li> <li>♦ Report on the adequacy of any structural system or component</li> <li>♦ Provide any engineering or architectural service</li> </ul>
<b>INSULATION &amp; VENTILATION</b>	<ul style="list-style-type: none"> <li>♦ Insulation and vapour barriers in accessible attics, crawl spaces and unfinished basements</li> <li>♦ Ventilation of attics and unheated crawl spaces</li> <li>♦ Report on the general absence or lack of insulation in unfinished and reasonably accessible or visible areas</li> <li>■ Operate exhaust fan ventilation systems (i.e. kitchen and bathroom vents)</li> </ul>	<ul style="list-style-type: none"> <li>♦ Concealed insulation and vapour barrier systems</li> <li>♦ Inspect areas that are not reasonably accessible or visible</li> <li>■ Move, touch, or disturb insulation or vapour barriers</li> <li>♦ Identify the composition or exact R-value of insulation material</li> <li>♦ Determine the types of materials used in insulation or wrapping of pipes, ducts, jackets, boilers, and wiring</li> <li>♦ Determine the adequacy of ventilation</li> </ul>

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

Canadian National Association of Certified Home Inspectors

**STANDARDS OF PRACTICE**

BUILDING SYSTEM	<i>The Inspector <u>is</u> required to:</i>	<i>The Inspector <u>is not</u> required to:</i>
	<ul style="list-style-type: none"> <li>◆ <b>Observe and report on the systems and components herein.</b></li> <li>■ <b>Perform tasks as noted herein.</b></li> </ul>	<ul style="list-style-type: none"> <li>◆ <b>Observe and report on the systems and components herein.</b></li> <li>■ <b>Perform tasks as noted herein.</b></li> </ul>
<b>ELECTRICAL</b>	<ul style="list-style-type: none"> <li>◆ Service entrance cable and location and integrity of the insulation, drip loop, or separation of conductors at weatherheads and clearances from grade or rooftops</li> <li>◆ Main service panel, auxiliary panels and location</li> <li>■ Test all ground fault circuit interrupter (GFCI) receptacles and GFCI circuit breakers observed and deemed to be GFCI's during the inspection</li> <li>◆ Panel overcurrent protection and system grounding</li> <li>◆ Branch circuit wiring and related over current protection</li> <li>◆ Report on any unused circuit breaker panel openings that are not filled</li> <li>◆ Amperage ratings of the main service panel and accessible sub panels</li> <li>◆ A representative number of switches, receptacles, lighting fixtures, AFCI receptacles</li> <li>■ Outlets noted above are to be checked for polarity and grounding</li> <li>■ All exterior outlets and those within 1.5 meters of plumbing fixtures will be checked for polarity, grounding and ground fault circuit protection</li> <li>◆ Report the presence or absence of smoke detectors</li> <li>◆ Report the presence of solid conductor aluminum branch circuit wiring if readily visible</li> </ul>	<ul style="list-style-type: none"> <li>◆ Insert any tool, probe or device into the main panel board sub-panels, distribution panel boards, or electrical fixtures</li> <li>◆ Secondary wiring systems such as low voltage wiring, telephone wiring, cable television wiring, etc.</li> <li>◆ Any components not related to the primary electrical systems such as security systems, swimming pool wiring and time-control devices</li> <li>◆ Inspect private or emergency electrical supply sources, including but not limited to generators, windmills, solar panels, or battery or electrical storage facilities</li> <li>◆ Provide or remove power for equipment</li> <li>◆ Inspect or test de-icing equipment</li> <li>◆ Conduct voltage drop calculations</li> <li>◆ Determine the accuracy of circuit labeling</li> <li>◆ Verify or certify the service ground</li> <li>■ Test the operation of smoke detectors</li> <li>■ Dismantle, remove, adjust or perform any task on any electrical equipment that would require a qualified trades person to perform</li> <li>■ Insert or remove fuses, or operate circuit breakers</li> </ul>
<b>PERMANENTLY INSTALLED HEATING AND COOLING SYSTEMS</b>	<ul style="list-style-type: none"> <li>◆ The heating systems using normal operating controls and describe the energy source and heating method</li> <li>◆ Furnace and distribution system, including fans, ducts, dampers, supports, filters, insulation, and registers</li> <li>◆ Boilers and distribution system including pumps, piping, valves, supports, insulation, radiators and convectors</li> <li>◆ Flue piping, vents, and chimneys</li> <li>◆ Heat recovery ventilator</li> <li>◆ Interior fuel storage equipment supply piping, venting, supports, and evidence of leakage</li> <li>◆ Cooling equipment and distribution system including fans, ducts, dampers, supports, filters, insulation, registers and piping</li> <li>◆ The presence of a designated shut off switch and a fuel shut off valve</li> <li>◆ The presence of a heat source in each room</li> <li>■ Test system using the thermostat or other similar standard operating controls</li> <li>■ Readily accessible and removable panel covers designed for homeowner access may be removed for inspection purposes</li> </ul>	<ul style="list-style-type: none"> <li>◆ Inspect or evaluate interiors of flues or chimneys, fire chambers, heat exchangers, humidifiers, dehumidifiers, electronic air filters, solar heating systems or fuel tanks</li> <li>◆ Determine the uniformity, temperature, flow, balance, distribution, size, capacity, adequacy, BTU, or supply adequacy of the heating system</li> <li>◆ Any portable heating/cooling, humidifying, dehumidifying or air cleaning equipment</li> <li>■ Activate any HVAC systems when ambient temperatures or when other circumstances are not conducive to safe operation or may damage the equipment</li> <li>◆ Evaluate fuel quality</li> <li>◆ Verify thermostat calibration, heat anticipation or automatic setbacks, timers, programs or clock</li> <li>◆ Examine electrical current, coolant fluids or gases, or coolant leakage</li> <li>■ Dismantle, remove, adjust or perform any function on any heating or cooling equipment that would require a qualified tradesperson to perform</li> <li>■ Light or ignite pilot flames</li> <li>■ Change settings or conditions on equipment excluding thermostats</li> </ul>

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

Canadian National Association of Certified Home Inspectors

STANDARDS OF PRACTICE

BUILDING SYSTEM	<i>The Inspector <u>is</u> required to:</i>	<i>The Inspector <u>is not</u> required to:</i>
	<ul style="list-style-type: none"> <li>◆ <b>Observe and report on the systems and components herein.</b></li> <li>■ <b>Perform tasks as noted herein.</b></li> </ul>	<ul style="list-style-type: none"> <li>◆ <b>Observe and report on the systems and components herein.</b></li> <li>■ <b>Perform tasks as noted herein.</b></li> </ul>
PLUMBING	<ul style="list-style-type: none"> <li>◆ Verify the presence of and identify the location of the main water shutoff valve</li> <li>◆ Water supply piping into house and within house, pipe supports and insulation</li> <li>◆ Drain, waste, and vent piping, pipe supports and insulation</li> <li>◆ Inspect the water heating equipment, including combustion air, venting, connections, energy sources, seismic bracing, and verify the presence or absence of temperature-pressure relief valves and/or Watts 210 valves</li> <li>■ Inspect the drainage sumps and test pumps with accessible floats</li> <li>◆ Presence of cross-connections that could contaminate the potable water</li> <li>■ Water volume and pressure should be tested by opening the faucets to obtain a reasonable flow of one or more fixtures simultaneously, and at various locations in the house</li> <li>■ Water drainage should be tested by draining one or more fixtures simultaneously, and at various locations in the house</li> <li>■ Test the water supply by operating valves and faucets</li> <li>◆ Leaks in the piping systems</li> <li>◆ Determine if the water supply is public or private</li> <li>◆ Inspect and report on the general condition of toilets, proper mounting on the floor, leaks and general functionality</li> <li>◆ Determine the presence and location of accessible clean-outs for the drain/waste/vent piping</li> </ul>	<ul style="list-style-type: none"> <li>◆ Ignite or extinguish fires, pilot lights, change settings or conditions on equipment</li> <li>◆ Determine the exact flow rate, volume, pressure, temperature, or adequacy of the water supply</li> <li>◆ Inspect interiors of flues or chimneys, water softening or filtering systems, well pumps, tanks, safety or shut-off valves, floor drains, lawn sprinkler systems or fire sprinkler systems</li> <li>■ Operate any valves other than those used on a regular or daily basis</li> <li>◆ Determine the water quality or potability or the reliability of the water supply or source</li> <li>◆ Foundation drainage system and yard piping</li> <li>◆ Inspect clothes washing machines or their connections</li> <li>■ Test shower pans, tub and shower surrounds or enclosures for leakage</li> <li>◆ Evaluate the compliance with local conservation or energy standards, or the proper design or sizing of any water, waste or venting components, fixtures or piping.</li> <li>◆ Determine the effectiveness of anti-siphon, back-flow prevention or drain-stop devices</li> <li>◆ Determine whether there are sufficient clean-outs for effective cleaning of drains</li> <li>◆ Evaluate gas, liquid propane or oil storage tanks</li> <li>◆ Inspect any private sewage waste disposal or septic system or component thereof</li> <li>◆ Inspect water treatment systems or water filters</li> <li>◆ Inspect water storage tanks, pressure pumps or bladder tanks</li> <li>◆ Evaluate wait time to obtain hot water at fixtures, or perform testing of any kind to water heater elements</li> <li>■ Test, operate, open or close safety controls, manual stop valves and/or temperature or pressure relief valve</li> <li>◆ Determine the existence or condition of polybutylene plumbing</li> <li>■ Dismantle, remove, adjust or perform any function on any plumbing equipment that would require a qualified tradesperson to perform</li> </ul>
INTERIORS	<ul style="list-style-type: none"> <li>◆ Floors, walls, ceilings and trim</li> <li>◆ Fire separating walls and party walls</li> <li>◆ Stairs, guards and railings</li> <li>◆ Observe condition of permanently installed counters and cabinet</li> <li>◆ Evidence of water penetration and condensation</li> <li>◆ The presence or absence of smoke detectors</li> <li>■ Randomly select and operate, where reasonably accessible, a representative number of doors and window</li> </ul>	<ul style="list-style-type: none"> <li>◆ Treatments such as paint, wallpaper, carpeting, blinds, drapes, and other similar treatments</li> <li>◆ Kitchen, bathroom, and laundry appliances</li> <li>◆ Observe fireplace insert installation</li> <li>◆ Any items or facilities not directly related to the interior systems and components such as swimming pools, saunas, hot tubs, ponds and water falls</li> <li>■ Move furniture, stored items, or any coverings like carpets or rugs in order to inspect the concealed floor structure</li> <li>■ Move drop / suspended ceiling tiles</li> <li>■ Operate or examine any sauna, steam-jenny, kiln, toaster, plug-in kitchen appliances, or other ancillary device</li> <li>◆ Inspect elevators, remote controls, appliances, or any items not permanently installed</li> <li>◆ Examine or operate any above-ground, movable, freestanding, or non-permanently installed pool/spa, recreational equipment or self-contained equipment</li> <li>◆ Test the operation of smoke detectors</li> <li>◆ Solid Fuel burning appliances including wood burning fireplaces and wood stoves</li> </ul>

## GENERAL LIMITATIONS AND EXCLUSIONS

### 1. General limitations:

1. Inspections performed in accordance with these Standards of Practice are not technically exhaustive.
2. Will not identify concealed conditions or latent defects.
3. These Standards of Practice are applicable to buildings with four or fewer dwelling units and their garages or carports.

### 2. General exclusions:

The inspector is not required to perform any action or make any determination unless specifically stated in these Standards of Practice, except as may be required by lawful authority.

Inspectors are NOT required to **determine**:

1. The condition of systems or components which are not readily accessible.
2. The remaining life of any system or component.
3. The strength, adequacy, effectiveness, or efficiency of any system or component.
4. The causes of any condition or deficiency.
5. The methods, materials, or costs of corrections.
6. Future conditions including, but not limited to, failure of systems and components.
7. The suitability of the property for any specialized use.
8. Compliance with regulatory requirements (codes, regulations, laws, ordinances, etc.).
9. The market value of the property or its marketability.
10. The advisability of the purchase of the property.
11. The presence of potentially hazardous plants or animals including, but not limited to wood destroying organisms or diseases harmful to humans.
12. The presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water, and air.
13. The effectiveness of any system installed or methods utilized to control or remove suspected hazardous substances.
14. The operating costs of systems or components.
15. The acoustical properties of any system or component.

### 3. Inspectors are NOT required to **offer**:

- a. Or perform any act or service contrary to the law.
- b. Or perform engineering services.
- c. Or perform work in any trade or any professional service other than home inspection.
- d. Warranties or guarantees of any kind.

4. Inspectors are NOT required to **operate**:

- a. Any system or component which is shut down or otherwise inoperable.
- b. Any system or component which does not respond to normal operating controls.
- c. Shut-off valves.

5. Inspectors are NOT required to **enter**:

- a. Any area which will, in the opinion of the inspector, likely be dangerous to the inspector or other persons or damage the property or its systems or components.
- b. The under-floor crawl spaces or attics which are not readily accessible.

6. Inspectors are NOT required to **inspect**:

- a. Underground items including, but not limited to underground storage tanks or other underground indications of their presence, whether abandoned or active.
- b. Systems or components which are not installed.
- c. Decorative items.
- d. Systems or components located in areas that are not entered in accordance with these Standards of Practice.
- e. Detached structures other than garages and carports.
- f. Common elements or common areas in multi-unit housing, such as condominium properties or cooperative housing.

7. Inspectors are NOT **required** to:

- a. Perform any procedure or operation which will, in the opinion of the inspector, likely be dangerous to the inspector or other persons or damage the property or its systems or components.
- b. Move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice, or debris.
- c. Dismantle any system or component, except as explicitly required by these Standards of Practice.

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS

