



# YOUR INSPECTION REPORT

*Inspection, Education, Knowledge.*

PREPARED BY:  
ADAM HANNAN



FOR THE PROPERTY AT:  
22 Ostend Avenue  
Toronto, ON M6S 1L4

PREPARED FOR:  
ALEX PORRITT  
GILLIAN RITCHIE  
INSPECTION DATE:  
Monday, February 28, 2022

## TIP

THE  
INSPECTION  
PROFESSIONALS

THE INSPECTION PROFESSIONALS, INC.  
3120 Rutherford Rd.  
Concord, ON L4K 0B2

416-725-5568  
HST# 89249 4501 RT0001  
[www.inspectionpros.ca](http://www.inspectionpros.ca)  
[adam@inspectionpros.ca](mailto:adam@inspectionpros.ca)



# TIP

THE  
INSPECTION  
PROFESSIONALS

March 1, 2022

Dear Alex Porritt and Gillian Ritchie,

RE: Report No. 7023  
22 Ostend Avenue  
Toronto, ON  
M6S 1L4

Thank you for choosing The Inspection Professionals to perform your Property Inspection. You can navigate the report by clicking the tabs at the top of each page. The Reference tab includes a 500-page Reference Library.

The Inspection Professionals (TIP) is a certified multi-inspector award-winning company founded by Adam Hannan. Since 2006, Adam has performed thousands of residential and commercial inspections and has become a respected expert in his field. Adam has a passion for education and has been an inspection instructor teaching at Community Colleges and Universities since 2009.

Adam is a member of the International Association of Certified Home Inspectors (CPI # NACHI07020704)

"We inspect every home as if we were buying it for ourselves. We care about our clients and we strive to exceed expectations. We offer a professional unbiased opinion of the current performance of the home regardless of who we are working for."

-Adam

#### BUYERS -

A phone review of the current report is available to prospective buyers. In order to more thoroughly familiarize yourself with the property and our findings, please book a Phone Review at your convenience by calling (416) 725-5568. The fee for this service is only \$195.

Sincerely,

ADAM HANNAN  
on behalf of  
THE INSPECTION PROFESSIONALS, INC.

THE INSPECTION PROFESSIONALS,  
INC.  
3120 Rutherford Rd.  
Concord, ON L4K 0B2  
416-725-5568  
HST# 89249 4501 RT0001  
[www.inspectionpros.ca](http://www.inspectionpros.ca)  
[adam@inspectionpros.ca](mailto:adam@inspectionpros.ca)

# SUMMARY

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## HIGHLIGHTS:

This solid masonry on stone foundations home is in good condition overall as compared to homes of similar age and style. The electrical system features a 200-amp electrical service with upgraded copper wiring. The basement has been professionally remodeled. The windows are double-glazed units. The furnace appears to be a newer high efficient unit. As is typical for homes of this age, there is a mix of newer and older systems and components

This Summary outlines some of the potentially short-term significant issues from a cost standpoint. This section is provided as a COURTESY ONLY and cannot be considered a substitute for reading the entire report. Please read the complete document.

It is not possible for a home inspector to predict the future. It would be advisable to annually budget between 0.5% to 1% of the value of the home for unforeseen repairs and maintenance. This would hold true for any house that you were considering.

Things will wear out, break down, and fail without warning. This is a fact of home ownership.

We adhere to the CAHPI Standards of Practice which can be viewed here:

CAHPI\_2012\_Standards\_of\_Practice\_verf-aug\_22\_final\_ver041519.pdf

NOTE: ALL ELECTRICAL ISSUES ARE CONSIDERED PRIORITY ITEMS

NOTE: FOR BALLPARK COSTS THE TERM 'MINOR' REFERS TO COSTS UNDER \$500

NOTE: FOR DIRECTIONAL PURPOSES USED THROUGHOUT THE REPORT, THE "FRONT" OF THE HOUSE IS REFERENCED AS FACING THE FRONT DOOR FROM THE EXTERIOR.

During a home inspection we inspect all visible systems and components. There are literally hundreds of potential minor issues found in every home, new and old. The inspection is not a technical audit on every minor flaw or deficiency. A technical audit can be performed at an additional cost. The focus of this inspection was to identify MAJOR issues with major systems and components. To simplify and give you a better understanding of what is considered a major issue, the inspection can generally be categorized as follows:

- 1)OBSERVABLE STRUCTURAL DEFECTS
- 2)OBSERVABLE WATER LEAKAGE/DAMAGE Roof, Plumbing, and basement moisture intrusion.
- 3)OBSERVABLE ELECTRICAL DEFECTS
- 4)LIFESPAN SYSTEMS- Roof Covering, Heating System, Cooling System, Windows

Disclaimer / Note to prospective buyers: This inspection report was performed for our client(s) as named on the report. We take no responsibility or hold no liability until an onsite review is purchased by the buyer and an onsite review is performed by our company and our inspection agreement of limitations and liability are signed. By accepting the information in this report without our onsite review, you are waiving all rights.

For Ballpark costs of various home components, please click here:

<http://www.inspectionlibrary.com/costs.htm>

# SUMMARY

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Roofing

### SLOPED ROOFING \ Asphalt shingles

**Condition:** • [Old, worn out](#)

The current roof covering is old /worn and is at the end of its lifespan. Due to sun exposure, the South / West sides of roofs typically wear out faster. We recommend full replacement.

**Location:** Throughout Exterior Roof

**Task:** Replace

**Time:** This Spring

**Cost:** \$7,000 - and up

## Cooling & Heat Pump

### AIR CONDITIONING \ Life expectancy

**Condition:** • Past life expectancy

Typical lifespan is 10-15 years. The current unit is 20 years old. Service annually and continue to use until replacement is needed. Not tested due to low outdoor temperature

**Location:** Exterior

**Task:** Replace

**Time:** When necessary / Unpredictable

**Cost:** \$3,000 - and up

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a home inspection. These may have to be adjusted based on the findings of specialists.

<http://www.inspectionlibrary.com/wtgw.htm>



# ROOFING

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**Sloped roofing material:** • [Asphalt shingles](#)

**Approximate age:** • Old

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • General Recommendation for all homes - Strip Roof Covering when replacing. When replacing a roof covering, it is common to apply a second layer over the first to minimize costs. Best practice however, is to remove the old roof covering before installing the new roof. Adding a third layer of roofing is not recommended. It is common when re-roofing to find concealed damage to roofing boards, these and other hidden components. There is no practical way to predict the presence or extent of the damage.

**Condition:** • All Roofing issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes.

### SLOPED ROOFING \ Asphalt shingles

**Condition:** • [Old, worn out](#)

The current roof covering is old /worn and is at the end of its lifespan. Due to sun exposure, the South / West sides of roofs typically wear out faster. We recommend full replacement.

**Location:** Throughout Exterior Roof

**Task:** Replace

**Time:** This Spring

**Cost:** \$7,000 - and up



1. Old, worn out



2. Old, worn out

### SLOPED ROOF FLASHINGS \ General notes

**Condition:** • Replace when reroofing

# ROOFING

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Inspection Methods and Limitations

**General:** • Most roofs are susceptible to ice damming under the right weather conditions. This is where ice forms at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather

**Inspection performed:** • With binoculars from the ground • Through Window - Limited View

# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**Gutter & downspout material:** • [Aluminum](#)

**Lot slope:** • [Away from building](#) • [Flat](#)

**Wall surfaces - masonry:** • [Brick](#)

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • All Exterior issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes, and personal safety.

### ROOF DRAINAGE \ Gutters

**Condition:** • Aging - Wear and tear noted. Fasteners loose in some areas

Recommendation is to replace gutters and downspouts at same time as roof covering

**Location:** Various Exterior

**Task:** Replace

**Time:** see note

**Cost:** \$7-\$10 per sq ft

### ROOF DRAINAGE \ Downspouts

**Condition:** • [Damage](#)

**Location:** Left Exterior

**Task:** Repair / Replace

**Time:** Less than 1 year

**Cost:** Regular maintenance item

# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Downspouts - common leakage areas

leaking  
elbows  
and seams

split along  
back seam

clogged

staining or  
efflorescence



3. Damage

**Condition:** • [Discharge too close to building](#)


**Location:** Various Exterior

**Task:** Improve


**Time:** Less than 1 year



## Gutter and downspout installation



## Downspout extension too short



# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



4. Discharge too close to building



5. Discharge too close to building


**Condition:** • [Should discharge 6 feet from building](#)

Likely contributing to why efflorescence is noted at wall.

**Location:** Left Side Exterior

**Task:** Extend downspout to ground

**Time:** Less than 1 year



# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


LINKS

MORE INFO

APPENDIX

REFERENCE

## Downspout extension too short



6. Should discharge 6 feet from building

**Condition:** • [Missing](#)

Downspout has fallen off

**Location:** Right Exterior

**Task:** Replace

**Time:** As Soon As Possible



# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



7. Missing

## WALLS \ Flashings and caulking

**Condition:** • Caulking around windows, doors and wall penetrations should be checked regularly for deficiencies and improved as needed.

## WALLS \ Masonry (brick, stone) and concrete

**Condition:** • [Mortar deterioration](#)

Provide mortar (Repointing, Tuck pointing) at various areas of the exterior brick, and window sills. This is routine maintenance for homes of this age. Photos show a sampling


**Location:** Various walls and window sills

**Task:** Repair

**Time:** Less than 2 years and ongoing

**Cost:** Consult masonry specialist

## Repointing



8. Mortar deterioration



9. Mortar deterioration



# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



10. Mortar deterioration



11. Mortar deterioration

**Condition:** • Most masonry walls have small cracks due to shrinkage or minor settlement. These will not be individually noted in the report, unless leakage, building movement or similar problems are noted

## EXTERIOR GLASS/WINDOWS \ General notes

**Condition:** • Sill - Near or at Grade Level

We often find windows on older homes that are at or near grade. Modern standards require that bottom of window be above grade by 6-inches or a window well be provided. Ensure window is kept well sealed and wood components painted.

**Location:** Exterior

**Task:** Monitor / Improve

**Time:** As Required



12. Sill - Near or at Grade Level

# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## EXTERIOR GLASS/WINDOWS \ Frames

**Condition:** • [Paint or stain needed](#)

**Location:** Various Exterior

**Task:** Improve

**Time:** Regular maintenance

## DOORS \ General notes

**Condition:** • Threshold too low

Having a minimal step makes the inside/outside transition easier.

On the other hand, it also makes it more prone to snow buildup/leakage.

While it is probably not practical to improve the current situation (unless rebuilding the deck), it will be important to keep any weatherstripping/caulking in good condition.

**Location:** Rear Exterior Deck

**Task:** Monitor / Improve

**Time:** If/as necessary



13. Threshold too low

## DOORS \ Doors and frames

**Condition:** • [Rot](#)

**Location:** Rear Exterior

**Task:** Repair / Replace

**Time:** Less than 1 year

**Cost:** Regular maintenance item

# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



14. example



15. example

## PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Stairs and landings

**Condition:** • [Steps springy, loose or sagging](#)

**Location:** Front Exterior Staircase

**Task:** Improve / Repair riser floor board support

**Time:** Less than 1 year



16. Riser old/worn

## PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Handrails and guards

**Condition:** • [Missing](#)

**Location:** Rear Exterior Deck Staircase

**Task:** Provide Handrail

**Time:** Less than 1 year

**Cost:** Minor



# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


LINKS

MORE INFO

APPENDIX

REFERENCE

## Handrails and guards



**Condition:** • [Damage at bottom](#)

Secure both handrails

**Location:** Front Exterior stairs

**Task:** Repair handrails on both side

**Time:** As Soon As Possible

**Condition:** • Inspect when snow melts. Improve as needed.

## LANDSCAPING \ Lot grading

**Condition:** • When the snow melts, ensure that the grading around the home is promoting drainage of water away from the home.

**Condition:** • During rainfall, walk the exterior to view if any water is draining towards the home. Improve these areas as needed

## LANDSCAPING \ Retaining wall

**Condition:** • [Bowing or bulging](#)

Uncertain if wall was installed with curve or bowing over time. Does not appear to be an imminent issue. Monitor activity and make improvements/repairs only if movement noted.

**Location:** Front Exterior

**Task:** Monitor

**Time:** Ongoing

**Cost:** Highly variable

# EXTERIOR

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



17. soil retaining wall

## Inspection Methods and Limitations

**Inspection limited/prevented by:** • Snow / ice / frost

**Upper floors inspected from:** • Ground level



## Descriptions

**Configuration:** • [Basement](#)

**Foundation material:** • [Stone](#)

**Floor construction:** • [Joists](#)

**Exterior wall construction:** • [Masonry](#)

**Roof and ceiling framing:** • Rafters

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • All Structure issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes, and personal safety.

### FOUNDATIONS \ General notes

**Condition:** • [Mortar deteriorated or missing](#)

Older Stone foundations typically require masonry and mortar work.. Recommendation is to provide mortar and masonry at stone foundations where required and then parge foundations (parging also noted in report) photos show small sampling

**Location:** Various Exterior Wall

**Task:** Repair

**Time:** Less than 1 year

**Cost:** Consult masonry specialist



18. Mortar deteriorated or missing



19. Mortar deteriorated or missing

# STRUCTURE

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Condition: • [Parging damaged or missing](#)

It is common to provide parging on older stone foundations. The parging will break down over time and crack/crumble. photos show a sampling

**Location:** Right Side and Left Side Exterior Foundations

**Task:** Provide parging (cement)

**Time:** Less than 1 year

**Cost:** Typically \$5-\$7 per square foot



20. Parging damaged or missing



21. Parging damaged or missing



22. Parging damaged or missing

## WALLS \ Solid masonry walls

### Condition: • [Prior repairs](#)

It is common to find a multitude of wall repairs on homes of this age

**Location:** Various Exterior Wall

**Task:** For Your Information



# STRUCTURE

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Condition: • [Efflorescence](#)

efflorescence noted at right and left side. Both areas appear to be caused by deficiencies with lack of downspouts.

**Location:** Right and left Exterior

**Task:** For Your Information



23. Efflorescence

## ROOF FRAMING \ Sheathing (roof/attic)

### Condition: • [Water stains](#)

Evidence of prior leakage. See roofing note

**Location:** Attic



24. Water stains

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Inspection Methods and Limitations

**Inspection limited/prevented by:** • Finishes, insulation, furnishings and storage conceal structural components.

**Attic/roof space:** • Inspected from access hatch

**Percent of foundation not visible:** • 80 %

## Descriptions

**General:** • ALL ELECTRICAL CONDITIONS ARE CONSIDERED PRIORITY ITEMS

**Service entrance cable and location:** • [Overhead - cable type not determined](#)

**Service size:** • [200 Amps \(240 Volts\)](#)


**Main disconnect/service box type and location:** • [Breakers - basement](#)

**System grounding material and type:** • [Copper - water pipe](#)

**Distribution panel type and location:**

• [Breakers - basement](#)

Good condition



25. Breakers - basement

**Distribution panel rating:** • [200 Amps](#)

**Distribution wire (conductor) material and type:** • [Copper - non-metallic sheathed](#)

**Type and number of outlets (receptacles):** • [Grounded - typical](#)

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • [GFCI - bathroom and exterior](#)

**Smoke alarms (detectors):** • Provide New

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • All electrical recommendations are safety issues. POTENTIAL worst-case implications are fire and shock hazards. Treat them as high priority items, and consider the time frame as Immediate, unless otherwise noted.

### DISTRIBUTION SYSTEM \ Outlets (receptacles)

**Condition:** • [Loose](#)

**Location:** First Floor

**Task:** Correct



**Time:** As Soon As Possible



26. Loose

**Condition:** • Outlet outdoor cover damaged

**Location:** Rear Exterior Wall

**Task:** Replace

**Time:** As soon as possible

**Cost:** Less than \$100

**DISTRIBUTION SYSTEM \ GFCI (Ground Fault Circuit Interrupter) protection not noted at**

**Condition:** • Kitchen counters

**Location:** Kitchen

**Task:** Replace outlets near sink with gfi outlet

**Time:** Less than 1 year

**DISTRIBUTION SYSTEM \ Smoke alarms (detectors)**

**Condition:** • Missing

**Location:** Ceilings

**Task:** Provide

**Time:** immediate

**Condition:** • Smoke and carbon monoxide (CO) detectors should be provided at every floor level of every home. Smoke detectors should be close to sleeping areas, and carbon monoxide detectors should be in any room with a wood-burning stove or fireplace. These devices are not tested as part of a home inspection. Once you take possession of the home, detectors should be tested regularly, and replaced every 10 years. If unsure of the age of a smoke detector, it should be replaced. Smoke detector batteries should be replaced annually.

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Inspection Methods and Limitations

**General:** • The electrical system has been upgraded at some point. Knob and Tube wiring was the typical wiring used in homes built prior to 1950. We did not observe any knob and tube during our inspection and all the outlets we tested appeared grounded and in good working order. Sometimes remnants of knob and tube wiring is found during renovations. If found, remove during renovations.

**System ground:** • Quality of ground not determined

# HEATING

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**Heating system type:** • [Furnace](#)

**Fuel/energy source:** • [Gas](#)

**Heat distribution:** • [Ducts and registers](#)

**Approximate capacity:** • Not determined

**Efficiency:** • [High-efficiency](#)

**Approximate age:**

• Not determined

Age estimated to be 4 years old based on gas tag

Age and capacity not verified due to storage in furnace room

**Typical life expectancy:** • Furnace (high efficiency) 15 to 20 years

**Fireplace/stove:** • [Gas fireplace](#)

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • Set up annual service plan which includes coverage for parts and labour.

**Location:** Basement Furnace Room

**Task:** Service annually

**Time:** Ongoing

**Cost:** Regular maintenance item

### GAS FURNACE \ Ducts, registers and grilles

**Condition:** • Typical of an older layout, some of the registers are at interior walls and not below the windows. Provide auxiliary heating near windows if necessary (baseboards for example)

**Location:** Various

### FIREPLACE \ Gas fireplace or gas logs

**Condition:** • A specialist should be engaged to inspect the gas fireplace prior to using the appliance. There are many manufacturers and many models of these units, with many different installation rules. We also recommend the gas fireplace be covered under a maintenance contract that includes regular service.

## Inspection Methods and Limitations

**Safety devices:** • Not tested as part of a building inspection

**Heat loss calculations:** • Not done as part of a building inspection

**Heat exchanger:** • Not visible

# COOLING & HEAT PUMP

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**Air conditioning type:** • [Air cooled](#)

**Cooling capacity:** • [24,000 BTU/hr](#)

**Compressor approximate age:** • 20 years

**Typical life expectancy:** • 10 to 15 years

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • In general, air conditioning units have a lifespan of 10-15 years but often last longer with regular servicing.

### AIR CONDITIONING \ Life expectancy

**Condition:** • Past life expectancy

Typical lifespan is 10-15 years. The current unit is 20 years old. Service annually and continue to use until replacement is needed. Not tested due to low outdoor temperature

**Location:** Exterior

**Task:** Replace

**Time:** When necessary / Unpredictable

**Cost:** \$3,000 - and up

## Inspection Methods and Limitations

**Inspection limited/prevented by:** • Cooling systems are not operated when the outdoor temperature is below 60°F

**Heat gain/loss calculations:** • Not done as part of a building inspection

# INSULATION AND VENTILATION

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**Attic/roof insulation material:** • [Cellulose](#)

**Attic/roof insulation amount/value:** • [R-20](#)

**Attic/roof air/vapor barrier:** • [None found](#) • Spot Checked Only

**Attic/roof ventilation:** • [Roof and soffit vents](#)

## Observations and Recommendations

### ATTIC/ROOF \ Insulation

**Condition:** • [Amount less than current standards](#)

Below current standards of R-60 (as of 2016)

**Location:** Throughout Attic

**Task:** Upgrade

**Time:** Discretionary

**Cost:** \$1,500 - and up

**Condition:** • Debris in attic

various pots/pans. evidence of prior leaking. See roofing note - replace roof covering

**Location:** Various Attic

**Task:** See roofing note

### ATTIC/ROOF \ Hatch/Door

**Condition:** • Attic Hatch Too Small

**Location:** Second Floor bedroom closet


**Task:** Improve before for better access



## Attic access hatch

the illustration shows a good attic access hatch design

hatches in many houses (especially older ones) won't meet these ideals



**Condition:** • Attic hatch is less than ideal. Improve hatch and weather strip to prevent air loss into attic

**Location:** Attic

**Task:** Replace



27.

# INSULATION AND VENTILATION

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Inspection Methods and Limitations

**Inspection limited/prevented by lack of access to:** • Walls, which were spot checked only

**Attic inspection performed:** • From access hatch

**Roof ventilation system performance:** • Not evaluated

**Air/vapor barrier system:** • Continuity not verified

## Descriptions

**Service piping into building:** • [Copper](#)

**Supply piping in building:** • [Not visible](#)

**Main water shut off valve at the:** • Furnace Room

**Water flow and pressure:** • [Functional](#)

**Water heater type:** • Not visible due to storage. See interior note

**Water heater fuel/energy source:** • Not visible. assumption is gas

**Water heater tank capacity:** • Not determined

**Water heater approximate age:** • Not determined

**Water heater typical life expectancy:** • 10 to 15 years

**Waste and vent piping in building:** • [Plastic](#)

**Floor drain location:**

• Not visible

Unable to enter furnace room due to storage.

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • All Plumbing issues have POTENTIAL worst-case implications of water damage to contents, finishes and/or structure.

### WASTE PLUMBING \ Drain piping - performance

**Condition:** • Sewer backup insurance is recommended for ALL homes

Sewer backup can happen to any home. There are many potential causes and it is prudent for homeowners to have coverage for this.

**Condition:** • A videoscan of the waste plumbing is recommended to determine whether there are tree roots or other obstructions, and to look for damaged or collapsed pipe. This is common on older properties, especially where there are mature trees nearby. This is a great precautionary measure, although many homeowners wait until there are problems with the drains. The cost may be roughly \$200 to \$400.

GENERAL RECOMMENDATION FOR ALL HOMES BUILT PRIOR TO 1970

### FIXTURES AND FAUCETS \ Faucet

**Condition:** • [Shower diverter inoperative or defective](#)

The shower diverter operates however some water still trickles from the spout when the shower head is engaged.

**Location:** Basement Bathroom

**Task:** Clean or Replace

**Time:** Regular maintenance

**Cost:** Minor



28. Shower diverter

## **FIXTURES AND FAUCETS \ Shower stall**

**Condition:** • [Caulking loose, missing or deteriorated](#)

**Location:** Second Floor Bathroom

**Task:** Improve caulking at shower fixtures

**Time:** Regular maintenance

## Inspection Methods and Limitations

### **Fixtures not tested/not in service:**

- Water heater  
no access due to storage

**Items excluded from a building inspection:** • Water quality • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water treatment equipment • Spa • Tub and basin overflows are not tested as part of a home inspection. Leakage at the overflows is a common problem.

**Not included as part of a building inspection:** • Not readily accessible interiors of vent systems, flues, and chimneys



## Descriptions

**General:** • The interior of the home is in good condition overall.

**Major floor finishes:** • [Hardwood](#) • [Laminate](#)

**Major wall and ceiling finishes:** • [Plaster/drywall](#)

**Windows:** • [Fixed](#) • [Single/double hung](#)

**Glazing:** • [Double](#)

**Evidence of basement leakage:** • During our inspection, we look for evidence of basement moisture intrusion. We did not observe standing water or evidence of active moisture intrusion in visible areas on this particular day.

## Observations and Recommendations

### RECOMMENDATIONS \ General

**Condition:** • All Interior issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes, and personal safety.

**Condition:** • Typical minor flaws were noted on floors, walls and ceilings. These cosmetic issues reflect normal wear and tear

### RECOMMENDATIONS \ Overview

**Condition:** • Furnace room was full of storage which prevented access. Therefore all systems and components in this area including - locating floor drain, main water service pipe and shut off, furnace, water heater, venting, etc were not inspected.

**Location:** Furnace Room

**Task:** Provide access and inspect

**Time:** As soon as practical

### FLOORS \ Subflooring

**Condition:** • Slope or Sag Noted.

Many older homes tend to have sagging or sloping floors.

**Task:** Repair when desired or when remodelling

**Cost:** Depends on cause (Joists vs foundations, etc)

### WINDOWS \ General notes

**Condition:** • Most of the windows appear to be from 2000 and were in good working order. Front main window is old and replacement is discretionary.

### DOORS \ Doors and frames

**Condition:** • Does not latch properly

**Location:** Front Door

**Task:** Adjust

**Time:** Regular maintenance



### STAIRS \ Handrails and guards

**Condition:** • [Missing](#)

**Location:** Basement Staircase (both portions)

**Task:** Provide

**Time:** Less than 1 year



29. Missing

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
LINKS	MORE INFO	APPENDIX	REFERENCE						

## EXHAUST FANS \ Kitchen range exhaust system (range hood)

**Condition:** • Inoperative

Microwave/vent combo inoperative.

**Location:** First Floor Kitchen

**Task:** Repair or Replace

**Time:** As Soon As Possible



30. Inoperative

**Condition:** • Not vented to exterior

Venting to the exterior was not standard when home was built

**Location:** Basement Kitchen

**Task:** Improve

**Time:** When remodelling

## BASEMENT \ Leakage

**Condition:** • \*\*\*FOR FUTURE REFERENCE\*\*\* GENERAL ADVICE FOR ALL HOMES IF BASEMENT LEAKAGE IS EVER OBSERVED

Basement Leakage 4-step method. Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it is impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and downspouts, and ground sloping down toward the house often cause basement leakage problems. To summarize, wet basement issues can be addressed in 4 steps: 1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost) 2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.) 3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$500 to \$600 per crack or \$300 per hole.) 4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

## BASEMENT \ Wet basements - vulnerability

**Condition:** • Typical of many homes with stone, brick, or block foundations, some moisture can be expected from time to

time and is not unusual. Exterior grading and water management improvements are generally effective at reducing basement moisture. A dehumidifier can also be used to keep humidity levels down.

## Inspection Methods and Limitations

**General:** • Up until about 1985, Asbestos was used in a multitude of building materials including but not limited to: Insulation on hydronic piping, attic insulation, flooring and ceiling tiles, stucco / stipple ceilings, glue, insulation around heating ducts and registers, plaster and so on. Identification of asbestos is outside the scope of a home inspection. If you have concerns about asbestos, consult with a professional environmental company that specializes with asbestos lab testing. If you plan to remove/disturb any building material, testing for asbestos is recommended beforehand.

**Inspection limited/prevented by:** • Storage/furnishings • New finishes/paint • Storage in closets and cabinets / cupboards

**Not included as part of a building inspection:** • Carbon monoxide alarms (detectors), security systems, central vacuum • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

**Cosmetics:** • No comment offered on cosmetic finishes

**Appliances:** • Appliances are not inspected as part of a building inspection • Appliances are not moved during an inspection

**Percent of foundation not visible:** • 99 %

**Basement leakage:** • Storage in basement limited inspection • Basement leakage is common. Most basements will experience leakage at some point. We cannot predict future occurrence or extent of basement leakage • Monitor the basement for leaks in the Spring.



# LINKS

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**General:** • [Low concentrations of CO can go undetected and can contribute to ongoing, unidentified illnesses. At high concentrations, it can be deadly.](#) • [Serious structural problems in houses are not very common, but when they occur they are never cheap to fix. Some cant be fixed at all. This report wont turn you into a home inspector, but it will give you some of the common indicators.](#) • [There are so many home maintenance and repair items that are important; it can be confusing trying to establish which are the most critical.](#) • [\(Life Cycles and Costs\)](#) • [This report will deal with the simpler topic of home repair--basically replacing things that are worn out or fixing things that are broken.](#) • [Common Building Technical Terms Explained](#)

**General:** • [The Inspection Professionals Website](#)

## MORE INFO

22 Ostend Avenue, Toronto, ON February 28, 2022

Report No. 7023

[www.inspectionpros.ca](http://www.inspectionpros.ca)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

## Descriptions

**GOOD ADVICE FOR ALL HOMEOWNERS:** • The following items apply to all homes and explain how to prevent and correct some common problems.

**Roof Leaks:** • Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced.

**Annual Roof Maintenance:** • We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of your roof.

**Ice Dams on Roofs:** • [Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms](#) at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather.

**Maintaining the Exterior of Your Home:** • Regular maintenance includes painting and caulking of all exterior wood.

**Insulation Amounts - Current Standards:** • R-50

**Reduce Air Leaks:** • Insulation is not effective if air (and the heat that goes with it) can escape from the home. Caulking and weather-stripping help control air leakage, improving comfort while reducing energy consumption and costs. Air leakage control improvements are inexpensive and provide a high return on investment.

**Bathtub and Shower Maintenance:** • Caulking and grout in bathtubs and showers should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

**Basement/Crawlspace Leakage:** • Almost every basement (and crawlspace) leaks under the right conditions. • [Click for more information.](#)

**MORE GOOD ADVICE FOR ALL HOMES:** • Here is some more information that applies to all homes.

**MORE GOOD INFORMATION:** • The following links give you access to documents that provide additional information on a range of topics.

**Life Cycles and Costs:** • [Ballpark estimates based on a typical three-bedroom home.](#)

**Priority Items for Home Buyers:** • [A list of things you should do when moving into your new home and a few regular maintenance items.](#)

**Maintenance:** • [Scheduled maintenance can avoid repairs and extend the life expectancy of many home components.](#) This document helps you look after your home.

**When Things Go Wrong:** • [Unpleasant surprises are unfortunately part of homeownership. This document helps to explain why things happen and why your home inspector may not have predicted it.](#)

**Standards of Practice:** • [This document sets out what a professional home inspection should include, and guides the activities of our inspectors.](#)

**END OF REPORT**



### Congratulations The Inspections Professionals

Consumers and Businesses in your city have once again selected your business as the 2021 Consumer Choice Award recipient in the category of **Home Inspection for York Region**.

Congratulation on winning this award for the **third straight year!** To be worthy of this award, you have stood out amongst all other businesses in your category - something you can be very proud of. You have been recognized as a beloved member of your business community, and through no influence of your own, you can now make the claim that you have been chosen as the top-rated business in your category.

Consumers are always searching for the best businesses in their cities and the Consumer Choice Award seal of approval is well recognized and respected. It lets your current and future customers know that they are dealing with a company who cares deeply about their products, services and clients. There is no greater differentiator available to you today.

To ensure you were chosen with a fair and unbiased process, our selection process relies on data from multiple, reliable sources that produce the most up-to-date research results. You can rest assured that you were chosen on the merits and reputation of your company within your community.

As a Consumer Choice Award Winner, you are now part of an exclusive group of companies recognized as one of the best businesses in Canada!

### Congratulations and Welcome to the Winners' Circle!

Handwritten signature of Jack McFadden in black ink.

Jack McFadden  
President

Handwritten signature of Jerrott Mitchell in black ink.

Jerrott Mitchell  
Market Development Manager

Recognizing and Promoting Business Excellence Since 1987.

**This is a copy of our home inspection contract and outlines the terms,  
limitations and conditions of the home inspection**

THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY AND INSPECTOR.

PLEASE READ CAREFULLY BEFORE SIGNING.

The Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. It is based on a visual examination of the readily accessible features of the building. The Inspection is performed in accordance with the Standards of Practice of the Ontario Association of Home Inspectors. A copy of these Standards is available at <http://www.oahi.com/webdocs/StandardsofPractice-OAHI-Rev.pdf>.

The Home Inspector's report is an opinion of the present condition of the property. The Inspection and report are not a guarantee, warranty or an insurance policy with regards to the property. A Home Inspector cannot predict future deficiencies, intermittent problems or future water leakage.

PLEASE READ THE FOLLOWING PARAGRAPH: Due to the unpredictable nature of basement water leakage, a home inspector cannot predict future basement leakage. Almost all basements will leak at some point so there is a very good chance that it will happen. Basement leakage can occur for any number of reasons - Rainfall, sewer backup, high water tables, lot grading, clogged weeping tiles, gutter and downspout performance, just to name a few. The home inspector and The Inspection Professionals accepts no responsibility or liability for future basement water problems.

The inspection report is for the exclusive use of the client named above. No use of the information by any other party is intended. See item 8 below.

**LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION**

These Limitations and Conditions explain the scope of your Home Inspection. Please read them carefully before signing this Agreement.

The purpose of your Home Inspection is to evaluate the general condition of a property. This includes determining whether systems are still performing their intended functions.

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

1. The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive. If you have concerns about any of the conditions noted, please consult the text that is referenced in the report.



Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential structural problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the report, we strongly recommend that you consult a qualified licensed contractor or engineering specialist. These professionals can provide a more detailed analysis of any conditions noted in the report at an additional cost.

2. A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, structure, plumbing and insulation that is hidden or inaccessible.

Some intermittent conditions may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. Inspectors do not remove wall coverings, including wallpaper, or lift flooring, including carpet to look underneath.

A Home Inspection is a sampling exercise with respect to house components that are numerous, such as bricks, windows and electrical receptacles. As a result, some conditions that are visible may go un-reported.

3. The Inspection does not include hazardous materials that may be in or behind the walls, floors or ceilings of the property, whether visible or not. This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based products, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fire proofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicide's or pesticides. The Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

4. We are not responsible for and do not comment on the quality of air in a building. The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building. The Inspection does not include spores, fungus, mold or mildew including that which may be concealed behind walls or under floors, for example. You should note that whenever there is water damage, there is a possibility that visible or concealed mold or mildew may be present unseen behind a wall, floor or ceiling.

If anyone in the home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens.

5. Your Home Inspector does not look for, and is not responsible for, fuel oil, septic or gasoline tanks that may be buried on the property. If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

6. We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced, or otherwise changed before we have had a reasonable period of time to investigate.

7. The Client understands and agrees to be bound by each and every provision of this contract. The Client has the authority to bind any other family members or other interested parties to this Contract.

8. REPORT IS FOR OUR CLIENT ONLY. The inspection report is for the exclusive use of the client named herein. The client may provide the report to prospective buyers, at their own discretion. Potential buyers are required to obtain their own Onsite Review with The Inspection Professionals if they intend to rely on this report. The Inspection Professionals will not be responsible for the use of or reliance upon this Report by any third party without an Onsite Review and transfer of report to client after they have agreed to our inspection agreement.

9. The liability of the Home Inspector (and the Home Inspection Company) arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
LINKS	MORE INFO	APPENDIX	REFERENCE						

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS

