



Your Inspection Report



5325 Anystreet
Anytown, AB

PREPARED FOR:
BRUCE MC

INSPECTION DATE:
Friday, December 6, 2013

PREPARED BY:
Dan Kameka

SurePro
Property Inspections



SurePro Property Inspections Inc.
12326 105 Street
Grande Prairie, AB T8V 8L6

780-978-7813
www.sureproinspections.com
dan@sureproinspections.com

Make Sure with SurePro!!!



March 24, 2020

Dear Bruce Mc,

RE: Report No. 1012, v.4
5325 Anystreet
Anytown, AB

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Dan Kameka
on behalf of
SurePro Property Inspections Inc.

SUMMARY

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Note: For the purpose of this report the building is considered to be facing **North**.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Priority Maintenance Items

Electrical

SERVICE BOX, GROUNDING AND PANEL \ System grounding

Condition: • Missing

Unable to find the system ground wire. Recommend a qualified electrician to further evaluate.

Implication(s): Electric shock

Heating

HEAT RECOVERY VENTILATOR \ Ducts and grilles


Condition: • Warm-side fresh air duct not well-connected to furnace duct

Implication(s): Equipment ineffective

Location: Basement Utility Room

Task: Further evaluation

Time: Immediate



SUMMARY

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR

REFERENCE

HRV connections to furnace ductwork



Warm-side fresh air duct not well-connected to furnace duct

Cooling & Heat Pump


HEAT PUMP \ Duct system

Condition: • When testing the return air ducts it was noted that the grills mounted high on the walls showed little to no air movement. I recommend further evaluation to determine proper air ventilation throughout the house.

Location: Various First Floor Living Room Bathroom Hallway Bathroom Staircase

Task: Further evaluation

Time: Immediate



SUMMARY

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR


REFERENCE

Testing cold air returns



A

hold a tissue next to the cold air return



B

there should be enough suction to pull the tissue towards the return
if not, the ductwork may be obstructed or the filters (or coil) may be dirty

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

General Information

General: • The primary purpose of a roof is to keep the building and its occupants protected from weather and pests. Our evaluation of the roof focuses on determining if portions are missing and/or deteriorated and, therefore, subject to potential leakage. Given that portions of the roofs underlayment and decking are hidden from view, these components are not evaluated during our visual inspection.

Sloped roofing material:

- Asphalt shingles



Asphalt shingles



Asphalt shingles

Probability of leakage:

- Low
- New shingles 2013

Inspection Methods & Limitations

Roof inspection limited/prevented by: • Snow/ice/frost

Inspection performed: • From roof edge

Observations & Recommendations

ROOF DRAINAGE \ Gutters

Condition: • Missing

Implication(s): Chance of water damage to contents, finishes and/or structure

Task: Provide

Time: Discretionary

Cost: Minor






Gutters Missing

General Information

General: • The exterior components of a home work together to provide a weather tight skin and protect the home against intruders. Our exterior evaluation is based on visual observations made at the time of the inspection and our experience and understanding of common building methods and materials. Our review does not take into consideration normal wear associated with virtually all properties. For example, hairline cracks in stucco, concrete and asphalt are common and are not considered a significant defect.

Gutter & downspout material:

- Aluminum



Asphalt shingles

Gutter & downspout type:

- Eave mounted



Aluminum

Gutter & downspout discharge:

- Below grade



Below grade

Lot slope: • Hillside

Soffit (underside of eaves) and fascia (front edge of eaves): • Aluminum

Wall surfaces and trim: • composite wood panel

Wall surfaces - masonry: • Brick veneer


Wall surfaces - wood: • Boards

Retaining wall: • Concrete

Driveway: • Gravel • No performance issues were noted.

Deck:

• Raised



Raised

- Pressure-treated wood
- No performance issues were noted.

Bottom edge of railing needs support from deck floor with wood blocking




Add railing support

Garage:

- General

Unattached Garage



Unattached Garage

Observations & Recommendations


FOUNDATIONS \ General notes

Condition: • Typical minor cracks

Implication(s): Chance of water entering building

Location: Exterior Wall

Time: Discretionary



Crack repair - epoxy and polyurethane injection


polyurethane is flexible and is not a structural repair, however, it can prevent leakage

it starts out with low viscosity, then expands within the crack

do-it-yourself crack repair kits usually feature polyurethane foam

epoxy is as strong as concrete and forms a structural seal

however, it hardens slowly, and if there is space at the back of the crack, it may leak out



alternatively, holes may be drilled along the crack for epoxy injection


Crack repair - drainage layer

dimpled plastic membrane protects the wall from moisture and provides drainage plane (other membranes and methods may also be used)


gravel fill next to wall to facilitate drainage

adding a drainage layer next to the wall helps to relieve hydrostatic pressure

this method may be used when there are many small cracks, when it is difficult to identify the specific source of leakage, and when it is difficult to correct poor grading (such as a hill next to the house).



Crack repair - exterior patching



Minor Cracks

STRUCTURE

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

General Information

General: • The structure of a home is the skeleton, which includes the foundations and footings as well as the floors, walls, and roof. Structures are judged by how well they are able to stand still. Successful structures do not move; less successful structures do.

Configuration: • Basement

Foundation material: • Poured concrete

Floor construction:

- Joists



Joists

Exterior wall construction: • Wood frame • Wood frame / Brick veneer

Roof and ceiling framing: • Trusses

Inspection Methods & Limitations

Inspection limited/prevented by: • Ceiling, wall and floor coverings

Attic/roof space: • Inspected from access hatch

Observations & Recommendations


SERVICE BOX, GROUNDING AND PANEL \ System grounding

Condition: • Missing

Unable to find the system ground wire. Recommend a qualified electrician to further evaluate.

Implication(s): Electric shock

SERVICE BOX, GROUNDING AND PANEL \ Distribution panel

Condition: • Openings in panel**Implication(s):** Fire hazard | Electric shock



Openings in panel

DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • No GFCI/GFI (Ground Fault Circuit Interrupter)

Implication(s): Electric shock

Location: Kitchen & Laundry Area


Ground fault circuit interrupter

also known as ground fault interrupter (GFI)

the GFCI circuitry within the outlet checks constantly for a difference between the current in the black and white wires
if there is a difference of at least 5 milliamps, there is a current leak and the GFCI shuts off the outlet and all outlets downstream

note:

if the GFCI is in the panel, the entire circuit will be shut down



ELECTRICAL

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



No GFCI



No GFCI

General Information

General: • The electrical system is very important from both a safety and convenience standpoint. Generally speaking, electrical systems are expanded and upgraded over the life of a house, rather than taken out and replaced on a regular basis.

Service entrance cable and location:

- Overhead



Overhead



Overhead

- Overhead copper

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Service size:

- 200 Amps (240 Volts)



200 Amps (240 Volts)

Main disconnect/service box rating: • 200 Amps**Main disconnect/service box type and location:** • Breakers - basement**System grounding material and type:** • Not visible**Distribution wire (conductor) material and type:** • Copper - non-metallic sheathed**Type and number of outlets (receptacles):** • All outlets tested for reverse polarity. All OK**Type and number of outlets (receptacles):** • Grounded - typical**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • No GFCI**Smoke alarms (detectors):** • Present

Inspection Methods & Limitations

System ground: • Not found

Observations & Recommendations

HEAT RECOVERY VENTILATOR \ Ducts and grilles

Condition: • Leak

Implication(s): Equipment ineffective

Location: Basement



Leak

Condition: • Warm-side fresh air duct not well-connected to furnace duct


Implication(s): Equipment ineffective

Location: Basement Utility Room


Task: Further evaluation

Time: Immediate

Furnace duct/HRV connection



HRV connections to furnace ductwork





Warm-side fresh air duct not well-connected t

General Information

General: • A well designed heating system is large enough to provide adequate heat on the coldest day, is reliable, is inexpensive to install and operate, is quick to respond to its controls, is able to heat all parts of the home equally, and is safe. There is no one system which performs all these functions to perfection. Every system is a compromise in one way or another, with low initial cost being the predominant factor.

System type: • Furnace

Fuel/energy source: • Geothermal Heat pump with closed loop water supply and 12,000 watt electrical backup



Fuel/energy source: • Gas

Heat distribution: • Ducts and registers

Approximate capacity: • Electrical backup 12KW

Approximate capacity: • 50,000 BTU/hr

Efficiency: • High-efficiency

Approximate age: • 2 years

Typical life expectancy: • 50 years

Main fuel shut off at: • Utility room

Failure probability: • Low

Fireplace/stove:

• Factory-built

HEATING

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION


PLUMBING

INTERIOR

REFERENCE



Factory-built



Factory-built



Factory-built

Chimney/vent: • Metal

Chimney liner: • Not visible

Inspection Methods & Limitations

Safety devices: • Not tested as part of a building inspection

Heat loss calculations: • Not done as part of a building inspection

Heat exchanger: • Not accessible

COOLING & HEAT PUMP

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Observations & Recommendations


HEAT PUMP \ Duct system

Condition: • When testing the return air ducts it was noted that the grills mounted high on the walls showed little to no air movement. I recommend further evaluation to determine proper air ventilation throughout the house.

Location: Various First Floor Living Room Bathroom Hallway Bathroom Staircase

Task: Further evaluation

Time: Immediate



COOLING & HEAT PUMP

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR


REFERENCE

Testing cold air returns



A

hold a tissue next to the cold air return



B

there should be enough suction to pull the tissue towards the return
if not, the ductwork may be obstructed or the filters (or coil) may be dirty

General Information

General: • Air conditioning systems move heat from a relatively cool space to a relatively warm space. They operate on some basic laws of liquids and gases. When liquids evaporate into gases, they absorb a considerable amount of heat. When gases are condensed back into a liquid, they give off heat. In addition if the pressure of a gas is increased, the temperature will also increase. Many systems use "Freon", a substance which changes state at temperatures and

pressures which are well suited for this application.

Air conditioning type: • Water cooled

Heat pump type: • Water source

Cooling capacity:

• 48,000 BTU/hr

COOLING & HEAT PUMP

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING


COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



48,000 BTU/hr

Compressor approximate age: • 2 years

Failure probability: • Low

Inspection Methods & Limitations

Heat gain calculations: • Not done as part of a building inspection

INSULATION AND VENTILATION

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

General Information

General: • Virtually every home has room for the improvement of insulation, ventilation, caulking and weather-stripping. By improving these you improve the comfort levels and conserve energy. Good insulation slows the rate of heat loss from a house. The best insulating materials are light weight, because air is a very good insulator. The problem is that air moves around by convection and wind, and the heat travels freely in the air. A good insulating material is one that limits the movement of trapped air.

Attic/roof insulation material: • Glass fiber

Attic/roof insulation amount/value: • R-40

Attic/roof air/vapor barrier: • Not determined

Attic/roof ventilation: • Roof vent • Soffit vent • Gable vent

Wall insulation material: • Glass fiber

Wall insulation amount/value: • R-20

Inspection Methods & Limitations

Attic inspection performed: • From access hatch

Air/vapor barrier system: • Continuity not verified

Mechanical ventilation effectiveness: • Not verified

General Information

General: • The purpose of a homes plumbing system is twofold. On the supply side, the idea is to get water for drinking, washing and cooking to the appropriate areas of the house. The waste side of the plumbing system is intended to get rid of the water and waste. The supply water operates under pressure, while the waste water flows by gravity. Plumbing components are expensive and plumbing repairs or improvements are among the more costly projects homeowners undertake.

Water supply source: • Pumped from lake

Water supply source:

- Private



Private

Service piping into building: • Copper

Supply piping in building: • Copper

Main water shut off valve at the: • Basement

Water flow and pressure: • Typical for neighborhood

Water heater type:

- Rental



Rental

Water heater fuel/energy source: • Electric

Water heater tank capacity: • 38.5 imp gal

Water heater approximate age: • 2 years

Water heater failure probability: • Low

Waste disposal system: • Septic system

Waste and vent piping in building: • ABS plastic

Water treatment system: • Iron filter • Ultraviolet treatment

Inspection Methods & Limitations

Items excluded from a building inspection: • Water quality • Septic system • Isolating/relief valves & main shut-off valve

Observations & Recommendations

WALLS \ Plaster or drywall


Condition: • Water damage

This appears to be a one time, old leak from something on the first floor and not a recurring issue.

Location: Basement Utility Room


Task: Monitor

Cost: Minor



Common locations for water damage

water damage to walls is common below windows, bathrooms, roof flashings, chimneys and vents



Minor water damage

Condition: • Typical flaws

Location: First Floor Hallway Bathroom



Plaster/drywall



Damaged

STAIRS \ Handrails and guards


Condition: • Missing

With no obstruction between the posts the step is too high. A railing to block the step or a bridging of the two outer steps to create one continuous step is recommended.

Implication(s): Fall hazard

Location: Basement

Handrails and guards



Missing

General Information

General: • The building interior is looked at for a number of reasons. The interior provides clues to structural problems and is often the area where water leakage is first detectable. The interior finishes themselves usually reflect overall building quality and their condition helps indicate the level of overall maintenance.

Major floor finishes: • Carpet • Resilient

Major wall finishes: • Plaster/drywall

Major ceiling finishes: • Plaster/drywall • Wood

Major wall and ceiling finishes: • Plaster/drywall • Paneling

Windows: • All windows tested. All OK


Windows:

- Casement



Casement

- Skylight



Skylight

Glazing: • Double

Exterior doors - type/material:

- Hinged
- French
- Metal



Metal

Doors:

- Inspected



Inspected

Bathroom ventilation: • Exhaust fan

Inspection Methods & Limitations

Not included as part of a building inspection: • Carbon monoxide alarms (detectors), security systems, central vacuum

END OF REPORT

REFERENCE LIBRARY

5325 Anystreet, Anytown, AB December 6, 2013

Report No. 1012, v.4

www.sureproinspections.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

- » 01. ROOFING, FLASHINGS AND CHIMNEYS
- » 02. EXTERIOR
- » 03. STRUCTURE
- » 04. ELECTRICAL
- » 05. HEATING
- » 06. COOLING/HEAT PUMPS
- » 07. INSULATION
- » 08. PLUMBING
- » 09. INTERIOR
- » 10. APPLIANCES
- » 11. LIFE CYCLES AND COSTS
- » 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

- » 13. HOME SET-UP AND MAINTENANCE
- » 14. MORE ABOUT HOME INSPECTIONS

