



YOUR INSPECTION REPORT

Inspection, Education, Knowledge.

PREPARED BY:
ADAM HANNAN



FOR THE PROPERTY AT:

771 Indian Road
Toronto, ON M6P 2E4

PREPARED FOR:
WENDY HAMMOND

INSPECTION DATE:
Tuesday, October 9, 2018

TIP

THE
INSPECTION
PROFESSIONALS

THE INSPECTION PROFESSIONALS, INC.
3120 Rutherford Rd.
Concord, ON L4K 0B2

416-725-5568
HST# 89249 4501 RT0001

www.inspectionpros.ca
adam@inspectionpros.ca

TIP

THE
INSPECTION
PROFESSIONALS

October 10, 2018

Dear Wendy Hammond,

RE: Report No. 2347
771 Indian Road
Toronto, ON
M6P 2E4

Thank you for choosing The Inspection Professionals to perform your Home Inspection.

The Inspection Professionals (TIP) is a Full-Time Professional, Certified multi-inspector company founded by Adam Hannan. Since 2006, Adam has performed thousands of residential and commercial inspections and has become a respected expert in his field. Adam has a passion for education and has been an inspection instructor teaching at Community Colleges and Universities since 2009.

Adam is a member of the Ontario Association of Home Inspectors and International Association of Certified Home Inspectors.

"We inspect every home as if we were buying it for ourselves. We care about our clients and we strive to exceed expectations. We offer a professional unbiased opinion of the current performance of the home regardless of who we are working for."

-Adam

BUYERS -

An Onsite Review is an essential component to a complete home inspection. In order to more thoroughly familiarize yourself with the property and our findings, please book an Onsite Review at your convenience by calling (416) 725-5568. Once we have completed the Onsite Review, we will transfer the inspection report to the buyer. The fee for this service is only \$249. (A minimum savings of \$175)

Sincerely,

ADAM HANNAN
on behalf of
THE INSPECTION PROFESSIONALS, INC.

THE INSPECTION PROFESSIONALS,
INC.
3120 Rutherford Rd.
Concord, ON L4K 0B2
416-725-5568
HST# 89249 4501 RT0001
www.inspectionpros.ca
adam@inspectionpros.ca

SUMMARY

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

This Summary outlines some of the potentially short-term significant issues from a cost standpoint. This section is provided as a COURTESY ONLY and cannot be considered a substitute for reading the entire report. Please read the complete document.

It is not possible for a home inspector to predict the future. It would be advisable to annually budget between 0.5% to 1% of the value of the home for unforeseen repairs and maintenance. This would hold true for any house that you were considering.

Things will wear out, break down, and fail without warning. This is a fact of home ownership.

NOTE: ALL ELECTRICAL ISSUES ARE CONSIDERED PRIORITY ITEMS

NOTE: FOR BALLPARK COSTS THE TERM 'MINOR' REFERS TO COSTS UNDER \$500

NOTE: FOR DIRECTIONAL PURPOSES USED THROUGHOUT THE REPORT, THE "FRONT" OF THE HOUSE IS REFERENCED AS FACING THE FRONT DOOR FROM THE EXTERIOR.

During a home inspection we inspect all visible systems and components. There are literally hundreds of potential minor issues found in every home, new and old. The focus of this inspection was not to list all the minor deficiencies. But rather, the focus of this inspection was to identify MAJOR issues with MAJOR systems and components. To simplify and give you a better understanding of what is considered a major issue, the inspection can generally be categorized as follows.

- 1)OBSERVABLE STRUCTURAL DEFECTS
- 2)OBSERVABLE WATER LEAKAGE/DAMAGE Roof, Plumbing, and basement moisture intrusion.
- 3)OBSERVABLE ELECTRICAL DEFECTS
- 4)LIFESPAN SYSTEMS- Roof Covering, Heating System, Cooling System, Windows

For Ballpark costs of various home components, please click here:

<http://www.inspectionlibrary.com/costs.htm>

Heating

GAS FURNACE \ Life expectancy

Condition: • [Near end of life expectancy](#)

The Typical life expectancy is 15-20 years. The current unit is 16 years old and appeared in working order at time of inspection. Service the unit and have HVAC licensed technician check heat exchanger for cracks or holes. If the heat exchanger is in good condition, continue to use until replacement is needed.

Implication(s): No heat for building | Equipment failure

Location: Basement Furnace

Task: Replace

Time: When necessary / Unpredictable

Cost: \$4,000

GAS FURNACE \ Cabinet

Condition: • [Rust](#)

SUMMARY

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Rust noted inside furnace cabinet. Evidence of prior leakage noted on the inside and exterior of furnace. Unknown if condensate leak is still active or intermittent. Dry at time of inspection. Service furnace and have HVAC technician check heat exchanger for rust.

Implication(s): Reduced system life expectancy | Material deterioration

Location: Basement Furnace

Task: Service

Time: As Soon As Possible

Interior

WINDOWS \ General

Condition: • The windows are old but generally function. At some point soon they should be replaced for cosmetics, ease-of-operation, or improved energy efficiency. Replacement windows are expensive, roughly \$30 to \$50/sq. ft. installed for moderate quality units. Although more energy-efficient, new windows will typically not pay for themselves quickly in energy savings.

We noted many windows manufactured between 1988-1992. The sliding door was manufactured 1976. We were not able to determine the age of some of the older windows.

Location: Throughout

Task: Upgrade

Time: Discretionary

Cost: \$15,000 - and up

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

<http://www.inspectionlibrary.com/wtgw.htm>

ROOFING

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Sloped roofing material: • [Asphalt shingles](#) • [Strip when reroofing](#)

Flat roofing material:

• [Modified bitumen membrane](#)



1. Modified bitumen membrane



2. Modified bitumen membrane



3. Modified bitumen membrane



4. Modified bitumen membrane

Observations and Recommendations

RECOMMENDATIONS \ Overview

Condition: • Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather

FLAT ROOFING \ Modified bitumen

Condition: • For Your Information - Professional roofer onsite noted that the flat roof was in good condition. We also observed roof from roof edge and determined that there are several years of service remaining. With flat roofs it is recommended to inspect annually

ROOFING

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Inspection Methods and Limitations

Inspection performed: • With binoculars from the ground • From roof edge

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Gutter & downspout material: • [Aluminum](#)

Gutter & downspout discharge: • [Above grade](#)

Lot slope: • [Away from building](#) • [Flat](#)

Wall surfaces and trim: • [Metal siding](#)

Wall surfaces - masonry: • [Brick](#)

Observations and Recommendations

ROOF DRAINAGE \ Gutters

Condition: • [Clogged](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Garage

Task: Clean

Time: Regular maintenance

Cost: Regular maintenance item



5. Clogged

WALLS \ Flashings and caulking

Condition: • [Flashings incomplete or ineffective](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Rear Exterior

Task: Provide

Time: Less than 1 year

Cost: Minor

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



6. Flashings incomplete or ineffective

WALLS \ Metal siding

Condition: • [Loose or missing pieces](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Rear Exterior Wall

Task: Improve

Time: Less than 1 year

Cost: Minor



7. Loose or missing pieces

WALLS \ Brick, stone and concrete

Condition: • Most masonry walls have small cracks due to shrinkage or minor settlement. These will not be individually noted in the report, unless leakage, building movement or similar problems are noted

Condition: • [Cracked](#)

It is common to see differential settlement type cracks on walls below and above windows. Patch cracks to prevent water entry and damage. It is not possible on a one-time visit to know if cracks are active. Repair / Patch and monitor for activity.

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Implication(s): Weakened structure | Chance of movement | Chance of water entering building

Location: Rear Exterior Wall

Task: Patch

Time: Less than 1 year

Cost: Regular maintenance item



8. Minor cracking

Condition: • [Spalling](#)

Spalling/ masonry deterioration noted at various areas. Repair / Replace / Tuck point masonry. This is regular maintenance for a home of this age.

Implication(s): Chance of structural movement | Weakened structure

Location: Various Exterior Wall

Task: Repair / Replace

Time: Regular maintenance

Cost: Regular maintenance item

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS


PHOTOS

MORE INFO

REFERENCE

Freezing water spalls bricks

freezing temperatures, saturated brick and a susceptible type of brick are required for spalling to occur



9. Spalling



10. Spalling

EXTERIOR GLASS/WINDOWS \ Exterior trim

Condition: • [Sill deteriorated](#)

Minor crack at sill noted. Patch to prevent further damage. Typical Maintenance

Implication(s): Material deterioration

Location: Exterior

Task: Patch

Time: Regular maintenance

Cost: Regular maintenance item

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



11. Sill deteriorated

DOORS \ Doors and frames

Condition: • [Stiff](#)

Implication(s): Chance of damage to finishes

Location: Right Side Door

Task: Adjust

Time: Regular maintenance

Cost: Regular maintenance item

PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Columns / Posts

Condition: • [Spalling](#)

Spalling bricks and mortar deterioration. Tuckpoint mortar and repair/replace bricks.


Implication(s): Chance of movement | Weakened structure

Location: Front Exterior Porch

Task: Repair / Replace

Time: Less than 2 years

Cost: Regular maintenance item



12. Spalling



13. Spalling

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Floors

Condition: • [Rot](#)

Some of the boards have already been replaced.

Implication(s): Material deterioration | Chance of movement | Weakened structure

Location: Rear Deck Balcony

Task: Repair

Time: Less than 1 year

Cost: Regular maintenance item



14. Rot

PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Handrails and guards

Condition: • [Rust](#)

Old Railings. Rusted at bottom of railings.

Implication(s): Fall hazard

Location: Front Exterior Porch

Task: Repair / Replace

Time: Discretionary

Cost: \$500 - and up



15. Rust



16. Rust

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

LANDSCAPING \ General

Condition: • [Trees or shrubs too close to building](#)


Tree is in contact with top of garage and roof.

Implication(s): Chance of pests entering building | Material deterioration | Chance of water damage to contents, finishes and/or structure

Location: Exterior Garage

Task: Monitor/Improve

Time: Less than 2 years



17. Trees or shrubs too close to building



18. Trees or shrubs too close to building

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

LANDSCAPING \ Lot grading

Condition: • During rainfall, walk the exterior to view if any water is draining towards the home. Improve these areas as needed

LANDSCAPING \ Walkway


Condition: • [Uneven \(trip hazard\)](#)

Implication(s): Physical injury

Location: Rear Exterior

Task: Improve

Time: Less than 1 year



19. Uneven (trip hazard)



20. Uneven (trip hazard)

LANDSCAPING \ Fence

Condition: • Leaning


Implication(s): Damage or physical injury due to falling materials | Chance of movement

Location: Rear Exterior Yard

Task: Improve

Time: Discretionary

Cost: Regular maintenance item



21. Prior temporary repair

EXTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Inspection Methods and Limitations

Upper floors inspected from: • Ground level

STRUCTURE

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Configuration: • [Basement](#)

Foundation material: • Not visible

Floor construction: • [Joists](#)

Exterior wall construction: • [Masonry](#)

Roof and ceiling framing: • Not visible

Observations and Recommendations

WALLS \ Solid masonry walls

Condition: • [Prior repairs](#)

It is common to find a multitude of wall repairs on homes of this age.

Implication(s): Weakened structure

Location: Various Exterior Wall

Task: For Your Information

Inspection Methods and Limitations

Inspection limited/prevented by: • Ceiling, wall and floor coverings • Carpet/furnishings • New finishes/paint

Attic/roof space: • No access

Percent of foundation not visible: • 99 %

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

General: • ALL ELECTRICAL CONDITIONS ARE CONSIDERED PRIORITY ITEMS

Service entrance cable and location: • [Overhead copper](#)

Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box type and location:

• [Breakers - basement](#)



22. Breakers - basement

Distribution panel type and location: • [Breakers - basement](#)

Distribution panel rating: • [125 Amps](#)

Distribution wire material and type: • [Copper - non-metallic sheathed](#) • [Copper - metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - upgraded](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCI - bathroom and exterior](#)

Smoke detectors: • [Present](#)

Observations and Recommendations

SERVICE BOX, GROUNDING AND PANEL \ Distribution panel

Condition: • [Openings in panel](#)

Implication(s): Fire hazard | Electric shock

Location: Basement Panel



Task: Correct

Time: Immediate

Cost: Less than \$100

Panel openings

any exposed panel openings (that would allow access to the inside of the panel) should be fitted with secure covers



23. Openings in panel

SERVICE BOX, GROUNDING AND PANEL \ Distribution fuses/breakers

Condition: • [No links for multi-wire circuits](#)

Implication(s): Electric shock


Location: Basement Panel

Task: Correct

Time: Immediate

Cost: Less than - \$200

Staggered bus bars on circuit breaker panels



24. No links for multi-wire circuits

SERVICE BOX, GROUNDING AND PANEL \ Panel wires

Condition: • [Double taps](#)



Implication(s): Fire hazard

Location: Basement Panels

Task: Correct

Time: Immediate

Cost: Minor

Double tapping (double lugging)

25. Double taps




26. Double taps

DISTRIBUTION SYSTEM \ Knob-and-tube wiring

Condition: • [Replace when renovating](#)

Based on the age of the property Knob and Tube may be present in the walls or ceiling, although NONE WAS OBSERVED during the inspection. Sometimes knob and tube wiring is found during renovations. If found during renovations, replacement is recommended to satisfy insurance companies. Many insurance companies will require an electrical audit to determine if there is knob and tube present.

Knob and tube wiring**DISTRIBUTION SYSTEM \ Wiring - installation****Condition:** • [Open splices](#)

Various electrical issues noted in Garage. Have electrician clean up connections, and provide junction boxes.

Implication(s): Fire hazard | Electric shock**Location:** Various Garage**Task:** Correct**Time:** Immediate**27.** Open splices**28.** Open splices

ELECTRICAL

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



29. Open splices

Condition: • [Not well secured](#)

Implication(s): Fire hazard | Electric shock

Location: First Floor

Task: Correct

Time: Immediate



30. Outlets not well secured

DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • [GFCI/GFI needed \(Ground Fault Circuit Interrupter\)](#)

Implication(s): Electric shock

Location: Exterior Wall

Task: Replace

Time: Prior to first use

Cost: Minor


Ground fault interrupter

the GFI circuitry within the outlet checks constantly for a difference between the current in the black and white wires

if there is a difference (even as little as 5 milliamps), there is a current leak (possibly through your body) and the GFI shuts down the receptacle and other receptacles downstream

note:

if the GFI is in the panel, the entire circuit will be shut down



31. GFCI/GFI needed (Ground Fault Circuit...

DISTRIBUTION SYSTEM \ Smoke detectors

Condition: • Smoke and carbon monoxide (CO) detectors should be provided at every floor level of every home. Smoke detectors should be close to sleeping areas, and carbon monoxide detectors should be in any room with a wood-burning stove or fireplace. These devices are not tested as part of a home inspection. Once you take possession of the home, detectors should be tested regularly, and replaced every 10 years. If unsure of the age of a smoke detector, it should be replaced. Smoke detector batteries should be replaced annually.

ELECTRICAL

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Inspection Methods and Limitations

System ground: • Quality of ground not determined

HEATING

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

System type: • [Furnace](#)

Fuel/energy source: • [Gas](#)

Heat distribution: • [Ducts and registers](#)

Approximate capacity: • [100,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Approximate age: • [16 years](#)

Typical life expectancy: • Furnace (high efficiency) 15 to 20 years

Fireplace/stove: • Wood-burning fireplace - not in service • Decorative only

Observations and Recommendations

General

• Set up annual service plan which includes coverage for parts and labour.

Location: Basement Furnace Room

Task: Service annually

Time: Ongoing

Cost: Regular maintenance item

GAS FURNACE \ Life expectancy

Condition: • [Near end of life expectancy](#)

The Typical life expectancy is 15-20 years. The current unit is 16 years old and appeared in working order at time of inspection. Service the unit and have HVAC licensed technician check heat exchanger for cracks or holes. If the heat exchanger is in good condition, continue to use until replacement is needed.

Implication(s): No heat for building | Equipment failure

Location: Basement Furnace

Task: Replace

Time: When necessary / Unpredictable

Cost: \$4,000

GAS FURNACE \ Cabinet

Condition: • [Rust](#)

Rust noted inside furnace cabinet. Evidence of prior leakage noted on the inside and exterior of furnace. Unknown if condensate leak is still active or intermittent. Dry at time of inspection. Service furnace and have HVAC technician check heat exchanger for rust.

Implication(s): Reduced system life expectancy | Material deterioration

Location: Basement Furnace

Task: Service

Time: As Soon As Possible

HEATING

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



32. Rust



33. Rust

Inspection Methods and Limitations

Safety devices: • Not tested as part of a building inspection

Heat loss calculations: • Not done as part of a building inspection

Heat exchanger: • Not visible

COOLING & HEAT PUMP

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Air conditioning type: • None present

Observations and Recommendations

RECOMMENDATIONS \ Overview

Condition: • No air conditioning or heat pump recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

Heat gain/loss calculations: • Not done as part of a building inspection

INSULATION AND VENTILATION

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Attic/roof insulation material: • Not determined • Not visible

Attic/roof insulation amount/value: • [Not visible](#)

Attic/roof air/vapor barrier: • [Not visible](#)

Attic/roof ventilation: • [Roof vent](#)

Wall insulation material: • Not visible

Wall insulation amount/value: • Not visible

Observations and Recommendations

RECOMMENDATIONS \ Overview

Condition: • No insulation recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

Inspection prevented by no access to: • Roof space • Walls, which were spot checked only

Roof ventilation system performance: • Not evaluated

Air/vapor barrier system: • Continuity not verified

Descriptions

Service piping into building: • [Not visible](#)

Supply piping in building: • [Copper](#)

Main water shut off valve at the: • Basement

Water flow and pressure: • [Functional](#)

Water heater type: • [Induced draft](#)

Water heater fuel/energy source: • [Gas](#)

Tank capacity: • 189 liters

Water heater approximate age: • 14 years

Typical life expectancy: • 10 - 15 years

Waste and vent piping in building: • [Plastic](#) • [Copper](#)

Floor drain location:

• Near heating system



34. Near heating system

Observations and Recommendations

WATER HEATER \ Life expectancy

Condition: • [Medium failure probability](#)

Typical life expectancy for this unit is 10-15 years. The current unit is 14 years old. Replace when necessary.

Implication(s): No hot water

Location: Basement Furnace Room

Task: Service annually

WASTE PLUMBING \ Drain piping - performance

Condition: • Sewage backup insurance is recommended.

Implication(s): drainage and/or leakage problems

Location: Basement

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Task: Provide

Time: Immediate

Condition: • Drain line video camera inspection recommended

We make this recommendation on all homes built prior to 1970

Implication(s): Drainage and/or leakage problems

Location: Basement

Task: Camera inspection

Time: Immediate

FIXTURES AND FAUCETS \ Faucet

Condition: • [Shower diverter inoperative or defective](#)

Implication(s): Equipment failure

Location: Third Floor Bathroom

Task: Replace

Time: Regular maintenance

Cost: Minor



35. *Shower diverter inoperative or defective*

FIXTURES AND FAUCETS \ Basin, sink and laundry tub

Condition: • [Slow drains](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Basement Bathroom

Task: Clean trap

Time: Regular maintenance

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Inspection Methods and Limitations

Inspection limited/prevented by:

- Water supply turned off
basement toilet

Items excluded from a building inspection: • Tub and basin overflows are not tested as part of a home inspection. Leakage at the overflows is a common problem.

Items excluded from a building inspection: • Well • Water quality • Septic system • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water treatment equipment • Pool • Spa

Descriptions

Major floor finishes: • [Carpet](#) • [Hardwood](#)

Major wall and ceiling finishes: • [Plaster/drywall](#) • [Stucco/texture/stipple](#)

Windows: • [Fixed](#) • [Sliders](#)

Glazing: • [Single](#) • [Double](#) • [Primary plus storm](#)

Exterior doors - type/material: • Hinged • [Sliding glass](#)

Observations and Recommendations

General

• Typical minor flaws were noted on floors, walls and ceilings. These cosmetic issues reflect normal wear and tear. Flaws typical for a home of this age.

CEILINGS \ Plaster or drywall

Condition: • [Patched](#)

All patches were tested with a moisture meter. Dry at time of inspection. Repaired ceilings are common in homes of this age.

Implication(s): Chance of damage to contents, finishes and/or structure

Location: Various Third Floor

Task: Monitor

WALLS \ Plaster or drywall

Condition: • [Bulging](#)

Implication(s): Damage or physical injury due to falling materials | Material deterioration

Location: Basement

Task: Improve

Time: Discretionary



36. *Bulging*

FLOORS \ General

Condition: • Worn

INTERIOR

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Implication(s): Material deterioration

Location: Second Floor

Task: Repair / Replace

Time: Discretionary

Cost: Regular maintenance item



37. Worn

FLOORS \ Ceramic tile, stone, marble, etc

Condition: • [Tiles cracked](#)

Implication(s): Trip or fall hazard

Location: Basement bathroom and kitchen

Task: Replace

Time: Regular maintenance

Cost: Regular maintenance item



38. Tiles cracked



39. Tiles cracked

WINDOWS \ General

Condition: • The windows are old but generally function. At some point soon they should be replaced for cosmetics, ease-of-operation, or improved energy efficiency. Replacement windows are expensive, roughly \$30 to \$50/sq. ft.

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

installed for moderate quality units. Although more energy-efficient, new windows will typically not pay for themselves quickly in energy savings.

We noted many windows manufactured between 1988-1992. The sliding door was manufactured 1976. We were not able to determine the age of some of the older windows.

Location: Throughout

Task: Upgrade

Time: Discretionary

Cost: \$15,000 - and up

CARPENTRY \ Cabinets

Condition: • [Drawers - missing or defective stops](#)

Implication(s): Damage or physical injury due to falling materials

Location: First floor Kitchen

Task: Provide drawer stops

Time: Less than 1 year

Cost: Minor

Condition: • [Stained, worn, damaged](#)

Implication(s): Material deterioration

Location: Various Basement Kitchen

Task: Repair / Replace

Time: Discretionary

STAIRS \ Handrails and guards

Condition: • [Missing](#)

Implication(s): Fall hazard



Location: Basement Staircase

Task: Provide Handrail

Time: Less than 1 year

Cost: Minor

Handrails and guards



40. Missing

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
LINKS	PHOTOS	MORE INFO	REFERENCE						

BASEMENT \ Leakage

Condition: • ***FOR FUTURE REFERENCE*** Basement Leakage 4-step method.

Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and downspouts, and ground sloping down toward the house often cause basement leakage problems. To summarize, wet basement issues can be addressed in 4 steps: 1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost) 2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.) 3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.) 4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

BASEMENT \ Wet basements - vulnerability

Condition: • Typical of many homes with stone, brick, or block foundations, some moisture can be expected from time to time and is not unusual. Exterior grading and water management improvements are generally effective at reducing basement moisture. A dehumidifier can also be used to keep humidity levels down.

Inspection Methods and Limitations

General: • Up until about 1985, Asbestos was used in a multitude of building materials including but not limited to: Insulation on hydronic piping, attic insulation, flooring and ceiling tiles, stucco ceilings, glue, insulation around heating ducts and registers and so on. Identification of asbestos is outside the scope of a home inspection. If you have concerns about asbestos, consult with a professional environmental company that specializes with asbestos lab testing.

Inspection limited/prevented by:

- Storage/furnishings
 - New finishes/paint
 - New finishes/paint
- Recent painting. Still drying in many areas.
- Storage in closets and cabinets / cupboards

Not included as part of a building inspection: • Carbon monoxide detectors, security systems, central vacuum • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

Cosmetics: • No comment offered on cosmetic finishes

Appliances: • Appliances are not inspected as part of a building inspection • Appliances are not moved during an inspection

Percent of foundation not visible: • 99 %

Basement leakage: • Cannot predict how often or how badly basement will leak

LINKS

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

General: • [The Inspection Professionals Website](#)

General: • [Low concentrations of CO can go undetected and can contribute to ongoing, unidentified illnesses. At high concentrations, it can be deadly.](#)

General: • [Serious structural problems in houses are not very common, but when they occur they are never cheap to fix.](#) Some cant be fixed at all. This report wont turn you into a home inspector, but it will give you some of the common indicators.

General: • [There are so many home maintenance and repair items that are important; it can be confusing trying to establish which are the most critical.](#)

General: • [\(Life Cycles and Costs\)](#)

General: • [This report will deal with the simpler topic of home repair--basically replacing things that are worn out or fixing things that are broken.](#)

General: • [Common Building Technical Terms Explained](#)

PHOTOS

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

General: • pictures taken during inspection

MORE INFO

771 Indian Road, Toronto, ON October 9, 2018

Report No. 2347

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

GOOD ADVICE FOR ALL HOMEOWNERS: • The following items apply to all homes and explain how to prevent and correct some common problems.

Roof Leaks: • Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced.

Annual Roof Maintenance: • We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of your roof.

Ice Dams on Roofs: • [Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms](#) at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather.

Maintaining the Exterior of Your Home: • Regular maintenance includes painting and caulking of all exterior wood.

Insulation Amounts - Current Standards: • Attic and roof space: R-40 (R-50 if electric heat)

Reduce Air Leaks: • Insulation is not effective if air (and the heat that goes with it) can escape from the home. Caulking and weather-stripping help control air leakage, improving comfort while reducing energy consumption and costs. Air leakage control improvements are inexpensive and provide a high return on investment.

Bathtub and Shower Maintenance: • Caulking and grout in bathtubs and showers should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

Basement/Crawlspace Leakage: • Almost every basement (and crawlspace) leaks under the right conditions. • [Click](#) for more information.

MORE GOOD ADVICE FOR ALL HOMES: • Here is some more information that applies to all homes.

MORE GOOD INFORMATION: • The following links give you access to documents that provide additional information on a range of topics.

Life Cycles and Costs: • [Ballpark estimates based on a typical three-bedroom home.](#)

Priority Items for Home Buyers: • [A list of things you should do when moving into your new home and a few regular](#) maintenance items.

Maintenance: • [Scheduled maintenance can avoid repairs and extend the life expectancy of many home components.](#) This document helps you look after your home.

When Things Go Wrong: • [Unpleasant surprises are unfortunately part of homeownership. This document helps to](#) explain why things happen and why your home inspector may not have predicted it.

Standards of Practice: • [This document sets out what a professional home inspection should include, and guides the](#) activities of our inspectors.

END OF REPORT

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS