YOUR INSPECTION REPORT



297 St Clair Ave E Toronto, ON





PREPARED FOR: JAMES WARREN

INSPECTION DATE: Wednesday, August 13, 2014

PREPARED BY: Gordon Mathieu, B.Sc Elec Eng, MBA



Carson, Dunlop & Associates Ltd. 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2

416-964-9415

www.carsondunlop.com info@carsondunlop.com

Powered by Knowledge



August 13, 2014

Dear James Warren,

RE: Report No. 44185 297 St Clair Ave E Toronto, ON

Thank you for choosing us to perform your home inspection. We hope the experience met your expectations.

There are a series of coloured tabs at the top of each page of the attached report that you can click for easy navigation. The report begins with a Summary and then has one section for every major home system (Roofing, Exterior, Structure, etc.). Blue, underlined text indicates a hyperlink. Click on the hyperlink for more information on that subject or condition. There is further reference material at the end.

A home inspection identifies the current condition of the property but cannot predict the future. Our home warranty protects you against the high cost of repair and replacement to furnaces, air conditioners, water heaters and appliances for as long as you own your home. To learn more, click on the Appendix heading at the top of any page of your report.

Please feel free to contact us with questions about the report or the home itself any time, for as long as you own your home. Our telephone and e-mail consulting service is available at no cost to you. Please watch for your follow-up e-mail. We hope you will fill out and return our client questionnaire.

Thanks again for choosing Carson Dunlop.

Sincerely,

Gordon Mathieu, B.Sc Elec Eng, MBA on behalf of Carson, Dunlop & Associates Ltd.

> Carson, Dunlop & Associates Ltd. 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2 416-964-9415 www.carsondunlop.com info@carsondunlop.com



INVOICE

August 13, 2014

Client: James Warren

Report No. 44185 For inspection at: 297 St Clair Ave E Toronto, ON

on: Wednesday, August 13, 2014

 Sellers Home Inspection PLUS - E
 \$615.00

 Coupon
 (\$25.00)

 Subtotal
 \$590.00

 HST
 \$76.70

 #108348343
 RT0001

 Total
 \$666.70

PAID IN FULL - THANK YOU!

Carson, Dunlop & Associates Ltd. 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2 416-964-9415 www.carsondunlop.com info@carsondunlop.com

SUMMARY									No. 44185
297 St Cla	ir Ave E, Tor	onto, ON	August 13, 2	014				www.carso	ndunlop.com
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

INTRODUCTION

This Summary lists some of the significant report items that may need attention in the short term. This must not be considered as the complete report. Please read the entire report and the appropriate text included in the hyperlinks.

The goal of a home inspection is to identify significant issues that would affect the average person's decision to buy a home. While looking for big issues we typically identify some minor defects along the way. We include these in the report as a courtesy, but please understand a home inspection is not a Technical Audit and does not include a comprehensive list of minor issues. (That service is available at additional cost.)

When you move into the home you may find some issues not identified in the report. That is to be expected and we suggest you allow roughly 1% of the value of the home annually for this type of maintenance and repair.

END OF SUMMARY

NOTE: BALLPARK COSTS AND TIME FRAMES

Any ballpark costs and time estimates provided are a courtesy and should not be relied on for budgeting or decision-making. Quotations from specialists should be obtained. The word 'Minor' describes any cost up to roughly \$500.

Report No. 44185 297 St Clair Ave E, Toronto, ON August 13, 2014 summary Roofing Exterior Structure Electrical Heating Cooling Insulation Plumbing Interior APPENDIX REFERENCE

Descriptions

Sloped roofing material:

<u>Asphalt shingles</u>





East face



East face

Flat roofing material:

• <u>Fiberglass/plastic</u> 3rd floor balcony decking.

West face




Front

Report No. 44185 www.carsondunlop.com

ROOFING

297 St Clair Ave E, Toronto, ON August 13, 2014

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
	REFERENCE								



Fiberglass/plastic

Dormer roofing material:

<u>Asphalt shingles</u>



Asphalt shingles

Porch roofing material:

<u>Asphalt shingles</u>

Powered by Knowledge

ROOFING				Report	No. 44185
297 St Clair Ave E, Toronto, ON August 13, 2014				www.carso	ndunlop.com
SUMMARY ROOFING EXTERIOR STRUCTURE ELEC	CTRICAL HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE					





Asphalt shingles

Garage roofing material:

<u>Asphalt shingles</u>





Asphalt shingles

Probability of leakage: • Moderate

Approximate age: • The roof covering appears to be within the first half of its normal life expectancy.

Chimneys:

<u>Masonry</u>

ROOF	ING							Report	No. 44185
	air Ave E, Tor	onto, ON	August 13, 2	014				www.carso	ndunlop.com
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								





Masonry


Observations and Recommendations

VULNERABLE AREAS \ Observations

Condition: • <u>Complex roof layout creates numerous vulnerable areas</u> Task: Monitor / Improve Time: Regular maintenance

Condition: • Flashings are vulnerable areas Task: Monitor / Improve Time: Regular maintenance





Flashings are vulnerable areas

ROOF	ING							Report	No. 44185	
	air Ave E, Tor	ronto, ON	August 13, 2014						www.carsondunlop.com	
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR	
APPENDIX	REFERENCE									
Inspect	Inspection Methods and Limitations									

Roof inspection method: • Ladder at the edge of the roof • Sections of the roof were walked on and sections were viewed from the ground through binoculars

Roof inspection limited/prevented by: • Slope - too steep to walk

EXTER	RIOR							Report	No. 44185
297 St Clair Ave E, Toronto, ON			August 13, 2014					www.carsondunlop.com	
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								
Decerir	tiono								

Descriptions

General: • Several components have been updated

Note: ie. windows, front door, newly created rear door, several masonry retaining walls, front porch, rear deck, rear 2nd floor sun room, reclaimed 3rd storey with rear upper deck & left side dormer, landscaping, gardens, long cobble stone driveway, rear damp-proofing, vehicle doors, walkways, gutters & downspouts, new sloped garage roof & shingles, new garage concrete floor & reinforced walls, etc.









Gutters and Downspouts:

<u>Discharge above grade</u>

EXTERIOR 297 St Clair Ave E, Te	pronto, ON	August 13, 2	014					No. 44185 ndunlop.com
SUMMARY ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE	1							
							D	





Discharge above grade

Retaining Walls:

<u>Masonry</u>

Extensive, well built, retaining walls were noted.





Masonry

Wall Surfaces: • Brick • Hardboard/Plywood • Wood shingles

EXTERIOR

Report No. 44185 www.carsondunlop.com

297 St Clair Ave E, Toronto, ON August 13, 2014

EXTERIOR

14

STRUCTURE ELECTRICAL

INSULATION PLUMBING

INTERIOR

SUMMARY ROOFING

APPENDIX REFERENCE

Observations and Recommendations

LOT GRADING \ Observations

Condition: • The grading around portions of the house is relatively neutral.

Implication(s): When trying to minimize basement leakage, it is always best to be proactive and slope the grades away from the house. Maintain positive slope away from house


Task: Monitor/Improve

Time: If necessary



LANDSCAPING \ Observations

Condition: • <u>Mature tree too close to building</u> Task: Monitor Time: Unpredictable



EXTER	RIOR							Report	No. 44185
	air Ave E, Toi	ronto, ON	August 13, 2	014				www.carso	ndunlop.com
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								





Mature tree too close to building

WINDOWS \ Exterior sideCondition: • Sill - clearance inadequate (above exterior grade level)Location: VariousTask: Monitor after heavy stormsTime: Regular maintenance



Sill - clearance inadequate (above exterior...

WALL SURFACES \ Observations Condition: • Prior repairs noted

Powered by Knowledge

EXTERIOR			Report No. 44185
	ugust 13, 2014		www.carsondunlop.com
SUMMARY ROOFING EXTERIOR	STRUCTURE ELECTRICAL	HEATING COOLING	INSULATION PLUMBING INTERIOR
APPENDIX REFERENCE			
<image/> <image/> <image/>			
guards are the floor of porch or b more than above			Click on image to enlarge.
	Powered by F	Knowledge	Page 12 of 41
		<u> </u>	

EXTERIOR 297 St Clair Ave E, Toronto, ON August 13, 2014	Report No. 44185 www.carsondunlop.com
SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL	HEATING COOLING INSULATION PLUMBING INTERIOR
<image/>	

Inspection Methods and Limitations

Exterior inspection method: • The exterior was inspected from ground level.

Limitations: • Fences, outbuildings (other than garages) and landscape features are not included as part of a home inspection.

Limitations: • Deck/porch/steps - restricted/no access under

STRU	CTURE						Report	No. 44185	
297 St Cla	air Ave E, Tor	ronto, ON	August 13, 2	014				www.carso	ndunlop.com
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

Descriptions

Foundations: • Brick • Masonry block

Configuration:

<u>Basement</u>

The basement floor has been significantly lowered and the walls benched.



Floor Construction: • Joists - wood

Exterior Wall Construction: • Masonry • Wood Frame

Roof and Ceiling Framing:

- Not visible in some areas
- <u>Rafters/Roof joists</u>





Attic

Garage

STRUCTURE				Report N	lo. 44185
297 St Clair Ave E, Toronto, ON	August 13, 2014			www.carson	dunlop.com
SUMMARY ROOFING EXTERIOR	STRUCTURE ELECTRICAL	HEATING COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE					
Attic					

Observations and Recommendations

CONCRETE FLOORS \Observations

Condition: • Concrete basement, crawlspace and garage floors are not typically part of the structure. Almost all basement, crawlspace and garage concrete floors have minor shrinkage and settlement cracks.



FOUNDATIONS AND MASONRY WALLS \ Observations

Condition: • Most foundation walls and masonry walls have small cracks due to minor shrinkage, settlement or shifting. These will not be individually noted, unless leakage or building movement is noted. ...noted in the garage.

STRUCTURE 297 St Clair Ave E, Toronto, ON	August 13, 2014					No. 44185
SUMMARY ROOFING EXTERIOR	STRUCTURE ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR

Inspection Methods and Limitations

Structure inspection method: • Roof structure inspected from attic access hatch

Limitations: • Finishes, insulation, furnishings and storage conceal structural components, preventing/restricting inspection. • It is not possible to determine the presence or extent of ongoing movement based on a one-time visit. • The footings supporting the house are typically not visible and cannot be inspected. Only a small part of the foundation can be seen and inspected from outside the home. Finished or concealed portions of the interior of the foundation cannot be inspected.

Limitations: • Roof space - no access

.

ELECTRICAL www.carsondunlop.com 297 St Clair Ave E, Toronto, ON August 13, 2014 ROOFING STRUCTURE ELECTRICAL COOLING INSULATION PLUMBING APPENDIX REFERENCE Descriptions Service Size: • 200 amps (240 Volts) **Distribution Panel Type and Location:** • Breakers - Basement Breakers - Basement Distribution Wire: • Copper - metallic sheathed • Copper - non-metallic sheathed Outlet Type & Number: • Grounded - upgraded number **Observations and Recommendations** General • No Electrical recommendations are offered as a result of this inspection. **Inspection Methods and Limitations** Limitations: • Main disconnect cover not removed - unsafe to do so. • Concealed electrical components are not inspected. • The continuity and quality of the system ground are not verified as part of a home inspection. • The following low voltage systems are not included in a home inspection: intercom, alarm/security, doorbells, low voltage light control, central vacuum, telephone, television, Internet, and Smart Home wiring systems. • A professional home inspection includes the inspection of a representative sample of wiring, lights, receptacles, etc.

Report No. 44185

HEATING	Report No. 44185
297 St Clair Ave E, Toronto, ON August 13, 2014	www.carsondunlop.com
SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INS	SULATION PLUMBING INTERIOR
APPENDIX REFERENCE	
Descriptions	
Main Heating System - Type: • <u>Boiler (hot water)</u>	



Boiler (hot water)

Efficiency: • Mid-efficiency

Main Heating System - Fuel/Energy Source: • Natural gas

Approximate Input Capacity: • 175,000 BTU/hr

Approximate Age: • <u>15 years</u>

Typical Life Expectancy: • Boiler with cast iron heat exchanger: 20 to 35 years.

Failure Probability: • Moderate

Chimney Liner:

• Metal

.





Metal

Powered by Knowledge

HEATING					Report N	lo. 44185
297 St Clair Ave E, Tore	onto, ON August 13, 20)14			www.carson	dunlop.com
SUMMARY ROOFING	EXTERIOR STRUCTURE	ELECTRICAL HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE						
 <u>Not visible</u> <u>Not required</u> 						

Not required, for water heater.

Main Fuel Shut-off Location:

• Gas Meter on exterior near front of the house



Observations and Recommendations

BOILER \ Observations

Condition: • No gas tag was found... Task: Provide Time: As required Cost: Minor

HEATING					Report	No. 44185
297 St Clair Ave E, Toronto, ON	August 13, 2014	ugust 13, 2014 www.cars				
SUMMARY ROOFING EXTERIOF	STRUCTURE ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE						
RADIATORS, CONVECTORS A	ND PIPING \ Observations					
Condition: • Layout not ideal, ha	ave HVAC specialist balance	e radiator val	ves if neces	<u>sary to provic</u>	<u>le more even</u>	heating;
improve layout if heating is inade	quate.					
Task: Further evaluation/Improve)					

Time: As required

Inspection Methods and Limitations

Limitations: • Heat loss calculations are not performed as part of a home inspection. • Safety devices are not tested as part of a home inspection. • The heat exchanger is substantially concealed and could not be inspected. • Radiator and zone valves on a hot water heating system are not tested as part of a home inspection.

Limitations: • Circulating pump not tested

Environmental issues outside the scope of a home inspection: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

Report No. 44185

COOLING				Report I	No. 44185
297 St Clair Ave E, Toronto, ON August 13, 2014				www.carsor	ndunlop.com
SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE					
Descriptions					
<text><text></text></text>					

Compressor outside.

Air handler in 3rd floor knee wall.

Cooling Capacity: • <u>36,000 BTU/hr</u> Approximate Age (Outdoor Unit / Compressor): • <u>7 years</u> Typical Life Expectancy: • 10 to 15 years

Inspection Methods and Limitations

Limitations: • Heat gain and heat loss calculations are not performed as part of a home inspection.

Report No. 44185 297 St Clair Ave E, Toronto, ON August 13, 2014 SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR REFERENCE

Descriptions

Attic insulation - value & material:

- R-28
- <u>Fiberglass</u>



Insulated hatch lid



Soffit baffles

Fiberglass

Attic air/vapour barrier: • Not visible

Cathedral/sloped roof insulation - value & material: • Amount not determined • Fiberglass • Plastic/foam board Roof ventilation:

<u>Roof vents</u>





INSULATION Report No. 44185 297 St Clair Ave E, Toronto, ON August 13, 2014 www.carsondunlop.com SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR APPENDIX REFERENCE V

<u>Soffit vents</u>

Knee wall insulation - value & material: • Not determined

Wood frame wall insulation - value & material: • Not determined

Roof vents

Masonry wall insulation - value & material: • Not determined

Basement wall insulation - value & material: • Amount not determined • Fiberglass • Plastic/foam board

Inspection Methods and Limitations

Insulation inspection method: • Attic inspected from access hatch

Limitations: • Concealed wall insulation is not inspected. • The continuity of air/vapour barriers and the performance of roof and attic ventilation are not verified as part of a home inspection.

Limitations: • Roof space - access not gained

Environmental issues outside the scope of a home inspection: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070. • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

Report No. 44185 PLUMBING www.carsondunlop.com 297 St Clair Ave E, Toronto, ON August 13, 2014 SUMMARY ROOFING STRUCTURE ELECTRICAL PLUMBING APPENDIX REFERENCE **Descriptions** General: • The kitchen and bathrooms have been updated. Water Piping to the Building: • Not determined Supply Piping in the Building: • Not visible in most areas. Supply Piping in the Building: • Copper Main Shut-off Valve Location: • Front of basement

Front of basement

Water Flow / Pressure: • Typical for neighbourhood

Water Heater Type and Energy Source:

- <u>Conventional</u>
- Induced draft



Induced draft

Powered by Knowledge

 PLUMBING
 Report No. 44185

 297 St Clair Ave E, Toronto, ON
 August 13, 2014

 SUMMARY
 ROOFING
 EXTERIOR

 STRUCTURE
 ELECTRICAL
 HEATING
 COOLING

 APPENDIX
 REFERENCE
 INTERIOR

<u>Natural Gas</u>

<u>Tempering (mixing) Valve noted</u>



Tempering (mixing) Valve noted

Water Heater Approximate Age: • 3 years

Typical Life Expectancy: • 10 to 15 years

Water Heater Tank Capacity: • 48 US

Hot Water Circulation:

• Circulating loop in place



Circulating loop in place

Waste Piping Material: • Cast iron • Copper • Plastic Floor Drain Location: • <u>Boiler room</u> • <u>Laundry Area</u> Pump:

PLUMBING Report No. 4418										
297 St Clair Ave E, Toronto, ON			August 13, 2	014				www.carso	ondunlop.com	
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR	
APPENDIX	REFERENCE									

• <u>Sump pump</u>

The pit does not appear to be active.



Sump pump

Observations and Recommendations

WASTE PIPING \ Observations

Condition: • A video inspection of the waste plumbing is recommended to determine whether there are tree roots, other obstructions, or damaged pipe. This is common on older properties, especially when mature trees are nearby. This is a great precautionary measure and can help prevent a sewage backup, although many homeowners wait until there are problems with the drains. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

Task: Provide Time: As required Cost: Minor



Large trees on front lawn ...

PLUMBING 297 St Clair Ave E, Toronto, ON August 13, 2014 SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

APPENDIX	REFERENCE		

BATHTUB \ Observations

Condition: • Window in bathtub enclosure

Implication(s): Windows in tub enclosures are more prone to water damage. Extra attention should be paid to ensure the area is well sealed and efforts should be made to minimize the amount of water directed at the window.



Inspection Methods and Limitations

Limitations: • Concealed plumbing is not inspected. This includes supply and waste piping under floors and under the yard.

Limitations: • Isolating valves, relief valves and main shut-off valves are not tested as part of a home inspection.

Limitations: • Tub and basin overflows are not tested as part of a home inspection. Leakage at the overflows is a common problem.

Limitations: • Swimming pools, spas, fountains, ponds and other water features are not included as part of a home inspection.

Note: Irrigation system

PLUMBING	Report No. 44185
297 St Clair Ave E, Toronto, ON August 13, 2014	www.carsondunlop.com
SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION	PLUMBING INTERIOR
APPENDIX REFERENCE	

Environmental issues outside the scope of a home inspection: • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

INTERIOR

Report No. 44185

Clair Ave E, Toronto, ON August 13, 2014 www.carson							
STRUCTURE ELECTRICAL HEATING	COOLING INSULATION PLUMBING INTERIOR						
General: Interior finishes are in good repair overall.							
R	R STRUCTURE ELECTRICAL HEATING						

General: • Interior finishes are high quality for the most part.

General: • The newer windows help improve comfort and energy efficiency.

Fireplaces and Stoves: • Fireplace - wood burning - masonry firebox


Observations and Recommendations

General

• Typical minor flaws were noted on floors, walls and ceilings. These cosmetic issues reflect normal wear and tear.

STAIRS \ Observations

Condition: • Railing missing Location: Basement Task: Provide Time: As required Cost: Depends on approach



INTERIOR					Report	No. 44185
297 St Clair Ave E, Toronto, ON	August 13, 2014				www.carso	ondunlop.com
SUMMARY ROOFING EXTERIO	STRUCTURE ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX REFERENCE						

Railing missing

FIREPLACE / STOVE \ WETT Inspection

Condition: • Fireplace, flue and chimney should be inspected and swept as needed by a WETT certified technician and any recommended repairs completed before the fireplace is used. (WETT - Wood Energy Technology Transfer Inc. is a non-profit training and education association.)

WHAT TO DO IF YOUR BASEMENT OR CRAWLSPACE LEAKS \ Observations

Condition: • Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and downspouts, and ground sloping down toward the house often cause basement leakage problems. Please read Section 10.0 in the Interior section of the Home Reference Book before taking any action.

To summarize, wet basement issues can be addressed in 4 steps:

1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost)

2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.)

3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.)

4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

INTERIOR Report No. 44185											
297 St Cla	air Ave E, Toi	ronto, ON	August 13, 2014					www.carsondunlop.com			
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR		

APPENDIX REFERENCE

Inspection Methods and Limitations

Limitations: • Security systems, intercoms, central vacuum systems, chimney flues and elevators are not included as part of a home inspection. Smoke detectors and carbon monoxide detectors are not tested as part of a home inspection. • Limited access to cabinets and closets • Perimeter drainage tile around foundations is not visible and is not included as part of a home inspection. • Basement leakage frequency or severity cannot be predicted during a home inspection • No comment is made on cosmetic finishes during a home inspection.

Limitations: • Basement finishes restricted the inspection • Storage/furnishings in some areas limited inspection

% of interior foundation wall not visible: • 100

Environmental issues outside the scope of a home inspection: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070. • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070. • Moisture problems may result in visible or concealed mold growth. An Environmental Consultant can assist if this is a concern. This Specialty Service can be booked through Carson Dunlop at 1-800-268-7070.

END OF REPORT

Depart Ne 11105

APPENDIX Report No. 441											
297 St Cla	air Ave E, Tor	ronto, ON	August 13, 2014 www.carsondu					ndunlop.com			
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR		
	REFERENCE										

GOOD ADVICE FOR ALL HOMEOWNERS

The following items explain how to prevent and correct some common problems around the house.

Roof Leaks

Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced.

Annual Roof Maintenance

We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of the roof.

Ice Dams on Roofs

Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms at the lower edge of the sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather. For information on prevention and cure, please see section 1.14.2 of the Roofing section of the Home Reference Book. This can be found under the Reference tab in this report.

Maintaining the Exterior of Your Home

Regular maintenance includes painting and caulking of all exterior wood. Caulking should also be well maintained at joints, intersections, wall penetrations and any other places water may get into the building.

Heating and Cooling System - Annual Maintenance

An annual maintenance agreement that covers parts and labour is recommended for all heating and cooling equipment. Humidifiers and electronic air cleaners should be included in the service agreement. The first service visit should be arranged as soon as possible, preferably before equipment is used.

Filters for furnaces and air conditioners should be checked monthly during the operating season and changed or cleaned as needed. Duct systems should be balanced during regular servicing for maximum comfort. Systems with heating and air conditioning are balanced differently for summer and winter.

For boiler/hot water systems, we recommend that any balancing or adjusting the radiator valves be performed by a specialist, due to the risk of leakage. Heating system valves are not operated during a home inspection.

Gas fireplaces and heaters should be included in annual service plans.

Fireplace and Wood Stove Maintenance

Wood-burning appliances and their chimneys should be inspected and cleaned **before you use them** the first time, and annually thereafter. We recommend specialists with WETT (Wood Energy Technology Transfer, Inc.) designations for this kind of work.

Electrical System - Label the Panel

The electrical panel should be labeled to indicate what is controlled by each fuse or breaker. Where the panel is already labeled, please verify the labeling is correct. Do not rely on the labeling being accurate.

Report No. 44185 www.carsondunlop.com

APPENDIX

		_	~ · ·		
297 St Clair	Ave E,	Toronto,	ON	August 13,	2014

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

Water Heaters

Tankless water heaters should be flushed by a heating or plumbing contractor every year to avoid poor performance and shortened life expectancy.

Bathtub and Shower Maintenance

Caulking and grout in bathtubs and showers should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

Basement/Crawlspace Leakage

Almost every basement (and crawlspace) leaks under the right conditions. Click for more information. For information on prevention and cure, please see section 10 of the Interior section of the Home Reference Book. This can be found under the REFERENCE tab in this report.

Washing Machine Hoses

We suggest braided steel hoses rather than rubber hoses for connecting washing machines to supply piping in the home. A ruptured hose can result in serious water damage in a short time, especially if the laundry area is in or above a finished area of the home.

Clothes Dryer Vents

We recommend vents for clothes dryers discharge outside the home. The vent material should be smooth walled (not corrugated) metal, and the run should be as short and straight as practical. This reduces drying time, energy consumption and cost; and minimizes the risk of a lint fire inside the vent.

Smoke and Carbon Monoxide (CO) Detectors

Smoke and carbon monoxide detectors should be provided at every floor level of every home, including basements and crawl spaces. (Even if they are present during the inspection, we recommend replacing detectors.) Smoke detectors should be close to sleeping areas, and carbon monoxide detectors should be in any room with a wood-burning stove or fireplace. These devices are not tested as part of a home inspection. Once you take possession of the home, detectors should be tested regularly, and replaced every 10 years. If unsure of the age of a smoke detector, it should be replaced. Smoke detector batteries should be replaced annually.

Priority Maintenance and Home Set-Up

When moving into a resale home, there are some things that you will want to take care of. The Home Set-Up and Maintenance section in the Home Reference Book will provide you with information regarding both things that are done just once as well as regular maintenance activities. This can be found under the REFERENCE tab in this report.

APPENDIX		Report No. 44185
297 St Clair Ave E, Toronto, ON	August 13, 2014	www.carsondunlop.com
SUMMARY ROOFING EXTERIOR	STRUCTURE ELECTRICAL HEATING	COOLING INSULATION PLUMBING INTERIOR
APPENDIX REFERENCE		
	This is a copy of our home inspection contract the terms, limitations and conditions of the ho	
THIS CC	ONTRACT LIMITS THE LIABILITY OF THE HOME PLEASE READ CAREFULLY BEFORE SIG	
The inspection is performed in Inspectors.	accordance with the STANDARDS OF PRACTIC	CE of the Ontario Association of Home
To review the STANDARDS OF	PRACTICE, visit <u>www.oahi.com/webdocs/Stan</u>	dardsofPractice-OAHI-Rev.pdf
The Home Inspector's report is readily accessible features of t	an opinion of the present condition of the pr he building.	operty, based on a visual examination of the
In addition to the limitations in set out in this Agreement.	n the STANDARDS, the Inspection of this prope	erty is subject to Limitations and Conditions
LIMITATIONS AND CONDITION	S OF THE HOME INSPECTION	
be needed. It is not intended to	ope of this Inspection. It provides a general ov o be an exhaustive list. The ultimate decision ertain conditions require repair or replaceme	of what to repair or replace is yours. One
1) THE INSPECTION IS NOT TEC	HNICALLY EXHAUSTIVE.	
	you with a basic overview of the condition of me to go through the property, the Inspection	
	s foundation cracks or other signs of settling i nat is beyond the scope of the Home Inspectic	
information than a Home Inspe	depth, technically-exhaustive inspection of the ection. We have both services available. By sig	
-	r or Consulting Engineer. These professionals	port, we strongly recommend that you consult can provide a more detailed analysis of any
2) THE INSPECTION IS AN OPIN	IION OF THE PRESENT CONDITION OF THE VIS	IBLE COMPONENTS.
The Home Inspector's Report is the readily accessible features	s an opinion of the present condition of the pr of the building.	roperty. It is based on a visual examination of
	clude identifying defects that are hidden behi ure, plumbing and insulation that are hidden o	

Powered by Knowledge

Report No. 44185

APPEN 297 St Cla	NDIX air Ave E, Tor	ronto, ON						•	No. 44185
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage or furniture to look underneath or behind.

3) THIS IS NOT A CODE-COMPLIANCE INSPECTION

The Inspector does NOT try to determine whether or not any aspect of the property complies with any past, present or future codes (such as building codes, electrical codes, fuel codes, fire codes, etc.), regulations, laws, by-laws, ordinances or other regulatory requirements.

4) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and ureaformaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fire proofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

5) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

6) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property. If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

APPENDIX Report No. 441								No. 44185	
297 St Clair Ave E, Toronto, ON			August 13, 2014			www.carsondunlop.com			
SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
_									

7) TIME TO INVESTIGATE

REFERENCE

APPENDIX

The Home Inspector and the Home Inspection Company will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

8) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

9) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the fee will apply.

10) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection and report are not a guarantee, warranty or an insurance policy with regard to the fitness of the property. A home warranty is available. For more information, visit www.carsondunlop.com/home-inspection/home-warranty-plan/

11) LIMIT OF LIABILITY

THE LIABILITY OF THE HOME INSPECTOR AND THE HOME INSPECTION COMPANY ARISING OUT OF THIS INSPECTION AND REPORT, FOR ANY CAUSE OF ACTION WHATSOEVER, WHETHER IN CONTRACT OR IN NEGLIGENCE, IS LIMITED TO A REFUND OF THE FEES THAT YOU HAVE BEEN CHARGED FOR THIS INSPECTION, OR \$1,000, WHICHEVER IS GREATER.

APPENDIX

297 St Clair Ave E, Toronto, ON

Report No. 44185 www.carsondunlop.com

PLUMBING

August 13, 2014

STRUCTURE

COOLING

APPENDIX

SUMMARY

REFERENCE

ROOFING

ONTARIO ASSOCIATION OF HOME INSPECTORS (OAHI)

Established by the Ontario Association of Home Inspectors Act, 1994

STANDARDS OF PRACTICE

INTRODUCTION 1.

1.1 The Ontario Association of Home Inspectors (OAHI) is a not-for-profit association established in 1987. In 1994, it became a self-regulating professional body when the OAHI Act received royal assent (passage of Bill Pr158). Membership in OAHI is voluntary and its members include private, fee-paid home inspectors. OAHI's objectives include promotion of excellence within the profession and continual improvement of its member's inspection services to the public. (The OAHI acknowledges The American Society of Home Inspectors®, Inc. (ASHI®) for the use of their Standards of Practice (version January 1, 2000).

2. PURPOSE AND SCOPE

2.1 The purpose of these Standards of Practice is to establish a minimum and uniform standard for private, fee-paid home inspectors who are members of the Ontario Association of Home Inspectors. Home Inspections performed to these Standards of Practice are intended to provide the client with information regarding the condition of the systems and components of the home as inspected at the time of the Home Inspection.

2.2 The Inspector shall:

- A. inspect:
 - 1. readily accessible systems and components of homes listed in these Standards of Practice
 - 2. installed systems and components of homes listed in these Standards of Practice.

B. report

- 1. on those systems and components inspected which, in the professional opinion of the inspector, are significantly deficient or are near the end of their service lives.
- 2. a reason why, if not self-evident, the system or component is significantly deficient or near the end of its service life.
- 3. the inspector's recommendations to correct or monitor the reported deficiency
- 4. on any systems and components designated for inspection in these Standards of Practice which were present at the time of the Home Inspection but were not inspected and a reason they were not inspected
- 2.3 These Standards of Practice are not intended to limit inspectors from:
 - A. including other inspection services, systems or components in addition to those required by these Standards of Practice.
 - B. specifying repairs provided the inspector is appropriately qualified and willing to do so.
 - C. excluding systems and components from the inspection if requested by the client

3. STRUCTURAL SYSTEM

- 3.1 The inspector shall:
 - A. inspect:
 - 1. the structural components including foundation and framing.
 - 2. by probing a representative number of structural components where deterioration is suspected or where clear indications of possible deterioration exist. Probing is NOT required when probing would damage any finished surface or where no deterioration is visible

B. describe:

- 1. the foundation and report the methods used to inspect the under-floor crawl space
- 2. the floor structure.
- 3. the wall structure.
- 4. the ceiling structure 5. the roof structure and report the methods used to inspect the attic.

3.2 The inspector is NOT required to:

A. provide any engineering service or architectural service.

B. offer an opinion as to the adequacy of any structural system or component.

4. EXTERIOR

4.1 The inspector shall:

A. inspect:

- 1. the exterior wall covering, flashing and trim.
- 2. all exterior doors
- 3. attached decks, balconies, stoops, steps, porches, and their associated railings
- 4. the eaves, soffits, and fascias where accessible from the ground level.
- 5. the vegetation, grading, surface drainage, and retaining walls on the property when any of these are likely to adversely affect the building. 6. walkways, patios, and driveways leading to dwelling entrances.
- B.describe the exterior wall covering.

4.2 The inspector is NOT required to:

- A. inspect:
 - 1. screening, shutters, awnings, and similar seasonal accessories.
 - 2. fences. 3. geological, geotechnical or hydrological conditions.
 - recreational facilities.
 - 5. outbuildings
 - 6. seawalls, break-walls, and docks,
 - 7. erosion control and earth stabilization measures.

5. ROOF SYSTEM

- 5.1 The inspector shall:
 - A. inspect:
 - 1. the roof covering.
 - 2. the roof drainage systems.
 - 3 the flashings 4. the skylights, chimneys, and roof penetrations.
 - B. describe the roof covering and report the methods used to inspect the roof.

5.2 The inspector is NOT required to:

- A. inspect:
- 1. antennae
- 2. interiors of flues or chimneys which are not readily accessible.
- 3. other installed accessories

Standards of Practice. © Copyright 2000 American Society of Home Inspectors, Inc. All Rights Reserved. Reproduced with Permission.

Report No. 44185 APPENDIX www.carsondunlop.com 297 St Clair Ave E, Toronto, ON August 13, 2014 COOLING SUMMARY ROOFING STRUCTURE PLUMBING REFERENCE APPENDIX Ontario Association of Home Inspectors Standards of Practice - Page 2 6. PLUMBING SYSTEM 8. HEATING SYSTEM 8.1 The inspector shall: 6.1 The inspector shall A. inspect: A. inspect: 1. the installed heating equipment. 1. the interior water supply and distribution systems including all fixtures 2. the vent systems, flues, and chimneys. and faucets 2. the drain, waste and vent systems including all fixtures B describe 3. the water heating equipment. 1. the energy source. 4. the vent systems, flues, and chimneys. 2. the heating method by its distinguishing characteristics 5. the fuel storage and fuel distribution systems. 6. the drainage sumps, sump pumps, and related piping. 8.2 The inspector is NOT required to: B. describe A. inspect: 1. the water supply, drain, waste, and vent piping materials. 1. the interiors of flues or chimneys which are not readily 2. the water heating equipment including the energy source. accessible. 3. the location of main water and main fuel shut-off valves. 2. the heat exchanger. 3. the humidifier or dehumidifier. 6.2 The inspector is NOT required to: 4. the electronic air filter 6. the solar space heating system. A. inspect: B. determine heat supply adequacy or distribution balance. 1. the clothes washing machine connections. 2. the interiors of flues or chimneys which are not readily accessible. 3. wells, well pumps, or water storage related equipment. 9. AIR CONDITIONING SYSTEMS 4. water conditioning systems. 9.1 The inspector shall: 5. solar water heating systems. 6. fire and lawn sprinkler systems A. inspect the installed central and through-wall cooling equipment. 7. private waste disposal systems B. describe B. determine 1. the energy source 2. the cooling method by its distinguishing characteristics. 1. whether water supply and waste disposal systems are public or private. 2. the quantity or quality of the water supply. 9.2 The inspector is NOT required to: C. operate safety valves or shut-off valves. A. inspect electronic air filters B. determine cooling supply adequacy or distribution balance. 7. ELECTRICAL SYSTEM 10. INTERIOR 7.1 The inspector shall: 10.1 The inspector shall: A. inspect: A. inspect: 1. the service drop. 2. the service entrance conductors, cables, and raceways. 1. the walls, ceilings, and floors. 3. the service equipment and main disconnects. 2. the steps, stairways, and railings. 4. the service grounding. 3. the countertops and a representative number of installed cabinets. 5. the interior components of service panels and sub panels. 4. a representative number of doors and windows. 5. garage doors and garage door operators 6. the conductors 7. the overcurrent protection devices. 10.2 The inspector is NOT required to: 8. a representative number of installed lighting fixtures, switches, and receptacles. A. inspect: 9. the ground fault circuit interrupters. 1. the paint, wallpaper, and other finish treatments. 2. the carpeting. B. describe 3. the window treatments. 1. the amperage and voltage rating of the service. the central vacuum systems. 2. the location of main disconnect(s) and sub panels. 5. the household appliances. 3. the wiring methods. 6. recreational facilities C. report 11. INSULATION AND VENTILATION on the presence of solid conductor aluminum branch circuit wiring. 2. on the absence of smoke detectors 11.1 The inspector shall:

7.2 The inspector is NOT required to:

A. inspect:


- 1. the remote control devices unless the device is the only control device.
- 2. the alarm systems and components.
- 3. the low voltage wiring, systems and components.
- 4. the ancillary wiring, systems and components not a part of the primary
- electrical power distribution system.
- 5. measure amperage, voltage, or impedance.

- A. inspect:
 - 1. the insulation and vapour retarders in unfinished spaces
 - 2. the ventilation of attics and foundation areas.
 - 3. the mechanical ventilation systems.
- B. describe
 - 1. the insulation and vapour retarders in unfinished spaces.
 - 2. the absence of insulation in unfinished spaces at conditioned surfaces.

11.2 The inspector is NOT required to:

- A. disturb insulation or vapour retarders.
- B. determine indoor air quality.

Standards of Practice. © Copyright 2000 American Society of Home Inspectors, Inc. All Rights Reserved. Reproduced with Permission.



- the operating costs of systems or components.
 the acoustical properties of any system or component.
- C. Inspectors are NOT required to offer:
- . Inspectors are not required to orier.
- or perform any act or service contrary to law
 or perform engineering services.
- or perform work in any trade or any professional service other than
- home inspection.
- 4. warranties or guarantees of any kind.

Standards of Practice. © Copyright 2000 American Society of Home Inspectors, Inc. All Rights Reserved. Reproduced with Permission.

APPENDIX

Report No. 44185

297 St Clair Ave E, Toronto	o, ON Aug	just 13, 2014	www.car	sondunlop.com
SUMMARY ROOFING EX	TERIOR ST	RUCTURE ELECTRICAL	HEATING COOLING INSULATION PLUMBING	INTERIOR
APPENDIX REFERENCE				
•				
Ontario Association	n of Home Inspecto	ors	Standards of Practice – Pag	e 4
detectors, flue gas and other spill smoke alarms Architectural Service Any practice involving the art and structure or grouping of structure structures or the design for const design, design development, pre- administration of the construction Automatic Safety Controls Devices designed and installed t conditions Component A part of a system Decorative Ornamental; not required for the home Describe To report a system or componen- to distinguish it from other syster Dismantle To take apart or remove any com	e-standing, including b llage detectors, securit d science of building de se and the use of space truction, including but r sparation of construction n contract to protect <i>systems</i> and operation of the essen n/ by its type or other of <i>ms</i> or <i>components</i>	esign for construction of any e within and surrounding the not specifically limited to, schematic n contract documents, and	Readily Accessible Available for visual inspection without requiring moving of personal property, dismantil destructive measures, or any action which will likely involve risk to persons or property Readily Openable Access Panel A panel provided for homeowner inspection and maintenance that is within normal rea can be removed by one person, and is not sealed in place Recreational Facilities Spas, saunas, steam baths, swimming pools, exercise, entertainment, athletic, playgre or other similar equipment and associated accessories Report To communicate in writing Representative Number One component per room for multiple similar interior components such as windows an electric outlets; one component on each side of the building for multiple similar exterior components Roof Drainage Systems Component sused to carry water off a roof and away from a building Significantly Deficient Unsafe or not functioning Shut Down A state in which a system or component cannot be operated by normal operating contains is built and fire chamber or similar prepared place in which a fire may be built and will built is onjunction with a chimmey; or a listed assembly of a fire chamber, its chimme and related factory-made parts designed for unit assembly without requiring field	ch, und 1 <i>ols</i> ich
Engineering Service Any professional service or creat experience and the application o engineering sciences to such pro investigation, evaluation, plannin	of special knowledge of ofessional service or cr g, design and supervis specifications and desi works or processes ualified professional, tr	i the mathematical, physical and reative work as consultation, sion of construction for the purpose ign, in conjunction with structures,	construction Structural Component A component that supports non-variable forces or weights (dead loads) and variable forces or weights (live loads) System A combination of interacting or interdependent components, assembled to carry out or more functions Technically Exhaustive An investigation that involves dismantling, the extensive use of advanced techniques,	e or
Home Inspection	tor visually examines th th <i>describes</i> those <i>syst</i>	he <i>readily accessible systems</i> and tems and components in	measurements, instruments, testing, calculations, or other means Under-floor Crawl Space The area within the confines of the foundation and between the ground and the unders of the floor	ide
Household Appliances Kitchen, laundry, and similar app Inspect To examine readily accessible sy these Standards of Practice, usin openable access panels Inspector A person hired to examine any sy these Standards of Practice Installed Attached such that removal requ	ystems and componen ng normal operating co system or component o	<i>ils</i> of a building in accordance with <i>ontrols</i> and opening <i>readily</i>	Unsafe A condition in a readily accessible, installed system or component which is judged to b significant risk of personal injury during normal, day-to-day use. The risk may be due to damage, deterioration, improper installation or a change in accepted residential construction standards Wiring Methods Identification of electrical conductors or wires by their general type, such as "non-meta sheathed cable" ("Romex"), "armored cable" ("bx") or "knob and tube", etc. • Note: In these Standards of Practice, redundancy in the description of the requirements, limitations and exclusions regarding the scope of the Home Inspection is provided for clarity not emphasis.	
Normal Operating Controls Devices such as thermostats, sw homeowner			e Inspectors, Inc. All Rights Reserved. Reproduced with Permission.	

		Report No. 44185
297 St Clai SUMMARY	r Ave E, Toronto, ON August 13, 2014 ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION	www.carsondunlop.com
APPENDIX	REFERENCE	
	elow connect you to a series of documents that will help you understand your home and tion to links attached to specific items in the report.	how it works. These
Click on ar	y link to read about that system.	
O	. ROOFING, FLASHINGS AND CHIMNEYS	
≥ 02	2. EXTERIOR	
>> 03	3. STRUCTURE	
04	I. ELECTRICAL	
ම 05	5. HEATING	
00	6. COOLING/HEAT PUMPS	
07	7. INSULATION	
30 🔇	3. PLUMBING	
>> 09). INTERIOR	
≥ 10). APPLIANCES	
》 11	LIFE CYCLES AND COSTS	
》 12	2. SUPPLEMENTARY	
	Asbestos	
	Radon	
	Urea Formaldehyde Foam Insulation (UFFI)	
	Lead	
	Carbon Monoxide	
	Mold Household Pests	7
	Termites and Carpenter Ants	
	B. HOME SET-UP AND MAINTENANCE	
14	A. MORE ABOUT HOME INSPECTIONS	
		Contraction of the second second second

Powered by Knowledge