



YOUR INSPECTION REPORT

Inspection, Education, Knowledge.

PREPARED BY:
ADAM HANNAN



FOR THE PROPERTY AT:

43 Maher Avenue
Toronto, ON M6P 1S7

PREPARED FOR:

GILLIAN RITCHIE
ALEX PORRITT

INSPECTION DATE:

Friday, September 17, 2021

TIP

THE
INSPECTION
PROFESSIONALS

THE INSPECTION PROFESSIONALS, INC.

3120 Rutherford Rd.
Concord, ON L4K 0B2

416-725-5568
HST# 89249 4501 RT0001

www.inspectionpros.ca
adam@inspectionpros.ca



TIP

THE
INSPECTION
PROFESSIONALS

September 20, 2021

Dear Gillian Ritchie and Alex Porritt,

RE: Report No. 2947, v.2
43 Maher Avenue
Toronto, ON
M6P 1S7

Thank you for choosing The Inspection Professionals to perform your Property Inspection. You can navigate the report by clicking the tabs at the top of each page. The Reference tab includes a 500-page Reference Library.

The Inspection Professionals (TIP) is a certified multi-inspector award-winning company founded by Adam Hannan. Since 2006, Adam has performed thousands of residential and commercial inspections and has become a respected expert in his field. Adam has a passion for education and has been an inspection instructor teaching at Community Colleges and Universities since 2009.

Adam is a member of the International Association of Certified Home Inspectors (CPI # NACHI07020704)

"We inspect every home as if we were buying it for ourselves. We care about our clients and we strive to exceed expectations. We offer a professional unbiased opinion of the current performance of the home regardless of who we are working for."

-Adam

BUYERS -

An Onsite Review is an essential component to a complete home inspection. In order to more thoroughly familiarize yourself with the property and our findings, please book an Onsite Review at your convenience by calling (416) 725-5568. Once we have completed the Onsite Review, we will transfer the inspection report to the buyer. The fee for this service is only \$275. (A minimum savings of \$175). A full phone report review is also available for \$97.00

Sincerely,

ADAM HANNAN
on behalf of
THE INSPECTION PROFESSIONALS, INC.

THE INSPECTION PROFESSIONALS,
INC.
3120 Rutherford Rd.
Concord, ON L4K 0B2
416-725-5568
HST# 89249 4501 RT0001
www.inspectionpros.ca
adam@inspectionpros.ca

SUMMARY

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

HIGHLIGHTS:

This solid masonry home is in above-average to excellent condition overall as compared to homes of similar age and style. The home has undergone extensive renovations and remodeling throughout. The electrical system features a 100-amp electrical service with copper wiring and upgraded switches, outlets, and fixtures. The windows are premium double-glazed energy efficient units. The windows range in age from 1995 to new and are in good condition. The roof coverings are in good condition. Both the furnace and air conditioner are new premium high efficient units. The water heater is new. The interior of the home has been professionally renovated and premium new finishes and quality were noted throughout. The basement has been professionally finished. The exterior walls have been repaired or modified in various areas. Overall, we did not identify any significant major issues.

This Summary outlines some of the potentially short-term significant issues from a cost standpoint. This section is provided as a COURTESY ONLY and cannot be considered a substitute for reading the entire report. Please read the complete document.

It is not possible for a home inspector to predict the future. It would be advisable to annually budget between 0.5% to 1% of the value of the home for unforeseen repairs and maintenance. This would hold true for any house that you were considering.

Things will wear out, break down, and fail without warning. This is a fact of home ownership.

We adhere to the CAHPI Standards of Practice which can be viewed here:

[CAHPI_2012_Standards_of_Practice_verf-aug_22_final_ver041519.pdf](#)

NOTE: ALL ELECTRICAL ISSUES ARE CONSIDERED PRIORITY ITEMS

NOTE: FOR BALLPARK COSTS THE TERM 'MINOR' REFERS TO COSTS UNDER \$500

NOTE: FOR DIRECTIONAL PURPOSES USED THROUGHOUT THE REPORT, THE "FRONT" OF THE HOUSE IS REFERENCED AS FACING THE FRONT DOOR FROM THE EXTERIOR.

During a home inspection we inspect all visible systems and components. There are literally hundreds of potential minor issues found in every home, new and old. The inspection is not a technical audit on every minor flaw or deficiency. A technical audit can be performed at an additional cost. The focus of this inspection was to identify MAJOR issues with major systems and components. To simplify and give you a better understanding of what is considered a major issue, the inspection can generally be categorized as follows:

1)OBSERVABLE STRUCTURAL DEFECTS

2)OBSERVABLE WATER LEAKAGE/DAMAGE Roof, Plumbing, and basement moisture intrusion.

3)OBSERVABLE ELECTRICAL DEFECTS

4)LIFESPAN SYSTEMS- Roof Covering, Heating System, Cooling System, Windows

Disclaimer / Note to prospective buyers: This inspection report was performed for our client(s) as named on the report. We take no responsibility or hold no liability until an onsite review is purchased by the buyer and an onsite review is

SUMMARY

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

performed by our company and our inspection agreement of limitations and liability are signed. By accepting the information in this report without our onsite review, you are waiving all rights.

For Ballpark costs of various home components, please click here:

<http://www.inspectionlibrary.com/costs.htm>

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a home inspection. These may have to be adjusted based on the findings of specialists.

<http://www.inspectionlibrary.com/wtgw.htm>

ROOFING

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

General: • Newer premium roof coverings

Sloped roofing material: • [Asphalt shingles](#) • [Strip when reroofing](#)

Flat roofing material:

• [Modified bitumen membrane](#)



1. Modified bitumen membrane

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All Roofing issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes.

RECOMMENDATIONS \ Overview

Condition: • No roofing recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

General: • Most roofs are susceptible to ice damming under the right weather conditions. This is where ice forms at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather

Inspection performed: • With binoculars from the ground • From roof edge

EXTERIOR

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

General: • The exterior of the home is in good condition.

Gutter & downspout material: • [Aluminum](#)

Gutter & downspout discharge: • [Above grade](#)

Lot slope: • [Away from building](#) • [Flat](#)

Wall surfaces and trim: • [Metal siding](#)

Wall surfaces - masonry: • [Brick](#)

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All Exterior issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes, and personal safety.

ROOF DRAINAGE \ Gutters

Condition: • Damage

Minor damage likely from tree branch

Location: Rear Right Exterior

Task: Repair / Replace

Time: Less than 1 year

Cost: Minor



2. Damage

ROOF DRAINAGE \ Downspouts

Condition: • [Should discharge 6 feet from building](#)


Location: Left Side Exterior

Task: Improve


Time: Less than 1 year

Cost: Regular maintenance item

Gutter and downspout installation



Downspout extension too short



EXTERIOR

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



3. Should discharge 6 feet from building

Condition: • [Not well secured](#)

Location: Left Exterior Garage

Task: Improve

Time: Regular maintenance

Cost: Regular maintenance item



4. Not well secured

WALLS \ Masonry (brick, stone) and concrete

Condition: • [Mortar deterioration](#)


Provide mortar (Repointing, Tuck pointing) at various areas of the exterior brick and front window sill. This is routine maintenance for homes of this age. Overall the brickwork appears to be in good condition as there have been recent improvements/modifications.

Location: Various Exterior Wall

Task: Provide mortar

Time: Regular maintenance

Repointing



5. example

Condition: • Most masonry walls have small cracks due to shrinkage or minor settlement. These will not be individually noted in the report, unless leakage, building movement or similar problems are noted

Condition: • Gap at Wall

Location: Left Exterior Wall

Task: Seal

EXTERIOR

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Time: Less than one year

Cost: Less than \$100



6. Gap at Wall

EXTERIOR GLASS/WINDOWS \ Exterior trim

Condition: • [Caulking loose, missing or deteriorated](#)

Location: Front Second Floor Exterior

Task: Improve

Time: Regular maintenance

Cost: Regular maintenance item

EXTERIOR GLASS/WINDOWS \ Window wells

Condition: • [Less than 6 inches below window](#)

Location: Rear Exterior

Task: Lower gravel in window well and improve window well retaining walls

Time: Less than 1 year

Cost: Regular maintenance item

EXTERIOR

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING


INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



7. Less than 6 inches below window



8. Less than 6 inches below window

LANDSCAPING \ General notes

Condition: • Tree Branch Maintenance

Keep tree branches trimmed back 3 feet from roof line.

Location: Rear Exterior

Task: Improve

Time: Ongoing

Cost: Regular maintenance item

EXTERIOR

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE



9. Tree Branch Maintenance

LANDSCAPING \ Lot grading

Condition: • During rainfall, walk the exterior to view if any water is draining towards the home. Improve these areas as needed

Inspection Methods and Limitations

No or limited access to: • Space between buildings

Upper floors inspected from: • Ground level

Descriptions

General: • No significant structural performance issues were observed. • The solid masonry walls and foundations that are visible are in good condition overall.

Configuration:

- [Basement](#)
- [Crawlspace](#)



10. Crawlspace

Foundation material:

- [Masonry block](#)
 - [Brick](#)
 - Not visible
- Not visible in many areas.

Floor construction: • [Joists](#)

Exterior wall construction: • [Masonry](#)

Roof and ceiling framing: • Not visible

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All Structure issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes, and personal safety.

RECOMMENDATIONS \ Overview

Condition: • The home has undergone renovations/remodeling throughout. We do not assess quality of modifications during a home inspection as work behind finishes is not observable. This type of work usually requires city permits/inspections. Request documentation as needed.

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

WALLS \ Solid masonry walls

Condition: • [Prior repairs](#)

It is common to find a multitude of wall repairs on homes of this age. We noted improvements and/or modifications

Location: Various Exterior Wall

Inspection Methods and Limitations

Inspection limited/prevented by: • Finishes, insulation, furnishings and storage conceal structural components.

Attic/roof space: • No access

Crawlspace: • Inspected from access hatch

Percent of foundation not visible: • 95 %

Descriptions

Service entrance cable and location: • [Overhead - cable type not determined](#)


Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box type and location: • [Breakers - basement](#)

System grounding material and type: • [Not visible](#)

Distribution panel type and location:

• [Breakers - basement](#)



11. Breakers - basement

Distribution panel rating: • [125 Amps](#)

Distribution wire (conductor) material and type: • [Copper - non-metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - upgraded](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCI - bathroom and exterior](#) • [GFCI - kitchen](#) • AFCIs present

Smoke alarms (detectors): • [Present](#)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All electrical recommendations are safety issues. POTENTIAL worst-case implications are fire and shock hazards. Treat them as high priority items, and consider the time frame as Immediate, unless otherwise noted.

DISTRIBUTION SYSTEM \ Smoke alarms (detectors)

Condition: • Smoke and carbon monoxide (CO) detectors should be provided at every floor level of every home. Smoke detectors should be close to sleeping areas, and carbon monoxide detectors should be in any room with a wood-burning stove or fireplace. These devices are not tested as part of a home inspection. Once you take possession of the home, detectors should be tested regularly, and replaced every 10 years. If unsure of the age of a smoke detector, it should be replaced. Smoke detector batteries should be replaced annually.

Inspection Methods and Limitations

System ground: • Quality of ground not determined

HEATING

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

General: • The heating system is a premium quality system and is in good condition.

System type: • [Furnace](#)

Fuel/energy source: • [Gas](#)

Heat distribution: • [Ducts and registers](#)

Approximate capacity: • [60,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Approximate age: • [New](#)

Typical life expectancy: • Furnace (high efficiency) 15 to 20 years

Fireplace/stove: • [Gas fireplace](#)

Observations and Recommendations

FIREPLACE \ Gas fireplace or gas logs

Condition: • A specialist should be engaged to inspect the gas fireplace prior to using the appliance. There are many manufacturers and many models of these units, with many different installation rules. We also recommend the gas fireplace be covered under a maintenance contract that includes regular service.

Inspection Methods and Limitations

Safety devices: • Not tested as part of a building inspection

Heat loss calculations: • Not done as part of a building inspection

Heat exchanger: • Not visible

COOLING & HEAT PUMP

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

General: • The cooling system is a premium quality system and is in good condition.

Air conditioning type: • [Air cooled](#)

Cooling capacity: • [24,000 BTU/hr](#)

Compressor approximate age: • New

Typical life expectancy: • 10 to 15 years

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • In general, air conditioning units have a lifespan of 10-15 years but often last longer with regular servicing.

RECOMMENDATIONS \ Overview

Condition: • No air conditioning or heat pump recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

Heat gain/loss calculations: • Not done as part of a building inspection

INSULATION AND VENTILATION

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

Attic/roof insulation material: • Not visible

Attic/roof insulation amount/value: • [Not visible](#)

Attic/roof air/vapor barrier: • [Not visible](#)

Foundation wall insulation material: • Sprayed Foam

Observations and Recommendations

RECOMMENDATIONS \ Overview

Condition: • No insulation recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

Inspection limited/prevented by lack of access to: • Attic • Walls, which were spot checked only

Roof ventilation system performance: • Not evaluated

Air/vapor barrier system: • Continuity not verified

Descriptions

General: • Several components have been updated

Service piping into building:

- [Not visible](#)

Exact entry point not visible due to spray foam insulation. portion visible is copper

Supply piping in building: • PEX (cross-linked Polyethylene)

Main water shut off valve at the:

- Front of the basement



12. Main water shut off

Water flow and pressure: • [Functional](#)

Water heater type: • [Induced draft](#)

Water heater fuel/energy source: • [Gas](#)

Water heater tank capacity: • 50 gallons • 189 liters

Water heater approximate age: • New

Water heater typical life expectancy: • 10 to 15 years

Waste and vent piping in building: • [Plastic](#)

Pumps: • [Sump pump](#)

Floor drain location: • Near heating system

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All Plumbing issues have POTENTIAL worst-case implications of water damage to contents, finishes and/or structure.

WATER HEATER - GAS BURNER AND VENTING \ Combustion air

Condition: • [Inadequate combustion air](#)

Have HVAC specialist evaluate if there is sufficient combustion air in the area. (only needed for water heater. The furnace is receiving it's combustion air from the exterior) If combustion air is needed, this is typically done by providing an opening through door (louvres) or wall opening.

Location: Basement Furnace Room

Task: Provide

Time: If necessary

Cost: Minor

WASTE PLUMBING \ Sump pump

Condition: • Provide backup battery powered power source for sump pumps.

Inspection Methods and Limitations

Items excluded from a building inspection: • Well • Water quality • Septic system • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water treatment equipment • Pool • Spa • Tub and basin overflows are not tested as part of a home inspection. Leakage at the overflows is a common problem.

Descriptions

General: • The interior of the home is in good condition overall. • Many interior components have been updated

Major floor finishes: • [Carpet](#) • [Hardwood](#)

Major wall and ceiling finishes: • [Plaster/drywall](#)

Windows: • [Fixed](#) • [Casement](#)

Windows: • We noted window ages ranging from 1995 to newer. Operative and in good condition overall

Glazing: • [Double](#)

Exterior doors - type/material: • Hinged

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All Interior issues have POTENTIAL worst-case implications such as damage to contents, structure and/or finishes, and personal safety.

RECOMMENDATIONS \ Overview

Condition: • No interior recommendations are offered as a result of this inspection.

BASEMENT \ Leakage

Condition: • ***FOR FUTURE REFERENCE*** Basement Leakage 4-step method.

Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and downspouts, and ground sloping down toward the house often cause basement leakage problems. To summarize, wet basement issues can be addressed in 4 steps: 1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost) 2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.) 3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.) 4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

Inspection Methods and Limitations

Inspection limited/prevented by: • Storage/furnishings • New finishes/paint

Not included as part of a building inspection: • Carbon monoxide alarms (detectors), security systems, central vacuum • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

Cosmetics: • No comment offered on cosmetic finishes

Appliances: • Appliances are not inspected as part of a building inspection • Appliances are not moved during an inspection

Percent of foundation not visible: • 95 %

INTERIOR

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Basement leakage: • Basement leakage is common. Most basements will experience leakage at some point. We cannot predict future occurrence or extent of basement leakage • Monitor the basement for leaks in the Spring.

LINKS

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

General: • [Low concentrations of CO can go undetected and can contribute to ongoing, unidentified illnesses. At high concentrations, it can be deadly.](#) • [Serious structural problems in houses are not very common, but when they occur they are never cheap to fix. Some cant be fixed at all. This report wont turn you into a home inspector, but it will give you some of the common indicators.](#) • [There are so many home maintenance and repair items that are important; it can be confusing trying to establish which are the most critical.](#) • [\(Life Cycles and Costs\)](#) • [This report will deal with the simpler topic of home repair--basically replacing things that are worn out or fixing things that are broken.](#) • [Common Building Technical Terms Explained](#)

General: • [The Inspection Professionals Website](#)

MORE INFO

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

Descriptions

GOOD ADVICE FOR ALL HOMEOWNERS: • The following items apply to all homes and explain how to prevent and correct some common problems.

Roof Leaks: • Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced.

Annual Roof Maintenance: • We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of your roof.

Ice Dams on Roofs: • [Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms](#) at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather.

Maintaining the Exterior of Your Home: • Regular maintenance includes painting and caulking of all exterior wood.

Insulation Amounts - Current Standards: • R-50

Reduce Air Leaks: • Insulation is not effective if air (and the heat that goes with it) can escape from the home. Caulking and weather-stripping help control air leakage, improving comfort while reducing energy consumption and costs. Air leakage control improvements are inexpensive and provide a high return on investment.

Bathtub and Shower Maintenance: • Caulking and grout in bathtubs and showers should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

Basement/Crawlspace Leakage: • Almost every basement (and crawlspace) leaks under the right conditions. • [Click for](#) more information.

MORE GOOD ADVICE FOR ALL HOMES: • Here is some more information that applies to all homes.

MORE GOOD INFORMATION: • The following links give you access to documents that provide additional information on a range of topics.

Life Cycles and Costs: • [Ballpark estimates based on a typical three-bedroom home.](#)

Priority Items for Home Buyers: • [A list of things you should do when moving into your new home and a few regular](#) maintenance items.

Maintenance: • [Scheduled maintenance can avoid repairs and extend the life expectancy of many home components.](#) This document helps you look after your home.

When Things Go Wrong: • [Unpleasant surprises are unfortunately part of homeownership. This document helps to](#) explain why things happen and why your home inspector may not have predicted it.

Standards of Practice: • [This document sets out what a professional home inspection should include, and guides the](#) activities of our inspectors.

END OF REPORT

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

**This is a copy of our home inspection contract and outlines the terms,
limitations and conditions of the home inspection**

THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY AND INSPECTOR.

PLEASE READ CAREFULLY BEFORE SIGNING.

The Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. It is based on a visual examination of the readily accessible features of the building. The Inspection is performed in accordance with the Standards of Practice of the Ontario Association of Home Inspectors. A copy of these Standards is available at <http://www.oahi.com/webdocs/StandardsofPractice-OAHI-Rev.pdf>.

The Home Inspector's report is an opinion of the present condition of the property. The Inspection and report are not a guarantee, warranty or an insurance policy with regards to the property. A Home Inspector cannot predict future deficiencies, intermittent problems or future water leakage.

PLEASE READ THE FOLLOWING PARAGRAPH: Due to the unpredictable nature of basement water leakage, a home inspector cannot predict future basement leakage. Almost all basements will leak at some point so there is a very good chance that it will happen. Basement leakage can occur for any number of reasons - Rainfall, sewer backup, high water tables, lot grading, clogged weeping tiles, gutter and downspout performance, just to name a few. The home inspector and The Inspection Professionals accepts no responsibility or liability for future basement water problems.

The inspection report is for the exclusive use of the client named above. No use of the information by any other party is intended. See item 8 below.

LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

These Limitations and Conditions explain the scope of your Home Inspection. Please read them carefully before signing this Agreement.

The purpose of your Home Inspection is to evaluate the general condition of a property. This includes determining whether systems are still performing their intended functions.

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

1. The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive. If you have concerns about any of the conditions noted, please consult the text that is referenced in the report.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential structural problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the report, we strongly recommend that you consult a qualified licensed contractor or engineering specialist. These professionals can provide a more detailed analysis of any conditions noted in the report at an additional cost.

2. A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, structure, plumbing and insulation that is hidden or inaccessible.

Some intermittent conditions may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. Inspectors do not remove wall coverings, including wallpaper, or lift flooring, including carpet to look underneath.

A Home Inspection is a sampling exercise with respect to house components that are numerous, such as bricks, windows and electrical receptacles. As a result, some conditions that are visible may go un-reported.

3. The Inspection does not include hazardous materials that may be in or behind the walls, floors or ceilings of the property, whether visible or not. This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based products, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fire proofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicide's or pesticides. The Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

4. We are not responsible for and do not comment on the quality of air in a building. The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building. The Inspection does not include spores, fungus, mold or mildew including that which may be concealed behind walls or under floors, for example. You should note that whenever there is water damage, there is a possibility that visible or concealed mold or mildew may be present unseen behind a wall, floor or ceiling.

APPENDIX

43 Maher Avenue, Toronto, ON September 17, 2021

Report No. 2947, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

If anyone in the home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens.

5. Your Home Inspector does not look for, and is not responsible for, fuel oil, septic or gasoline tanks that may be buried on the property. If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

6. We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced, or otherwise changed before we have had a reasonable period of time to investigate.

7. The Client understands and agrees to be bound by each and every provision of this contract. The Client has the authority to bind any other family members or other interested parties to this Contract.

8. REPORT IS FOR OUR CLIENT ONLY. The inspection report is for the exclusive use of the client named herein. The client may provide the report to prospective buyers, at their own discretion. Potential buyers are required to obtain their own Onsite Review with The Inspection Professionals if they intend to rely on this report. The Inspection Professionals will not be responsible for the use of or reliance upon this Report by any third party without an Onsite Review and transfer of report to client after they have agreed to our inspection agreement.

9. The liability of the Home Inspector (and the Home Inspection Company) arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

MORE INFO

APPENDIX

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS